



Quality Assurance Report

CUSTOMER(고객명)	DESCRIPTION(품명)	LOT NO(로트번호)	ISSUED DATE(발행일자)
호연이엔지	0.4*100	20260918 -01	2026-09-18
규격(재질)		LOT SIZE(수량)	
0.4*100	Ni 1.0 μ m~3.0 μ m	20 Kg	

I. VISUAL INSPECTION (Sampling Plan : n=100mm/Reel, 5Reel/Shipping or n=50ea/Shipping, c=0)

NO	INSPECTION ITEMS	Ac/Re	RESULT	NO	INSPECTION ITEMS	Ac/Re	RESULT
1	DISCOLORATION(변색)	0/1	OK	6	NO PLATING(미도금)	0/1	OK
2	STAIN(일룩)	0/1	OK	7	PEELING(도금 벗겨짐)	0/1	OK
3	RUST(부식)	0/1	OK	8	LUMP(도금용침)	0/1	OK
4	CONTAMINATION(오염)	0/1	OK	9	CAMBER(휨)	0/1	OK
5	BENT(변형)	0/1	OK	10	PLATING BURR (도금버)	0/1	OK



II. DIMENSION INSPECTION (Sampling Plan : n=100mm/Reel, 5Reel/Shipping or n=50ea/Shipping, c=0)

NO	항목/구분	SPEC			검사주기	우리하이피		고객		판정
		규격	하한(-)	상한(+)		1차	2차	1차	2차	
1	전폭	100.0	-0.1		Reel/Lot	99.978				OK
2										
3										
4										
5										
6										
7										
8										
9										
10										

III. PLATING THICKNESS(도금두께) (Sampling Plan : 1y)

NO	SPECIFICATION	Measurement Data	RESULT
1	X-Ray 측정 Ni 1.0 μ m~3.0 μ m	첨부 : 도금성적서 첨부 : 도금성적서	OK

IV. FUNCTIONAL TEST (Sampling Plan : n=100mm/EA, 2EA/Shipping, c=0)

NO	INSPECTION ITEMS	SPECIFICATION	TEST SAMPLE	RESULT
1	ADHESION TEST (밀착성 시험)	1.제품을 스카치 Tape에 완전 밀착후 45도 각도로 순간적으로 떼어낸다.(돌돌 및 벗겨짐) 2.테이프 시험이 안되는 제품은 나퍼로 90도로 상,하각은후 도금돌돌 이나 벗겨짐이 없을것.		
제품도면			이 피 고 객	18 우리하이피(주) Q.C
			작성 승인 종합판정	

업체명 : 호연이엔지

품명 : 0.4x100 (초물) LOT NO : 260918-01 DATE : 26.09.18


No	μm Ni	Ni tolerance	
		1.310	1.331 1.352
1	1.311		
2	1.342		
3	1.344		
4	1.310		
5	1.348		
Mean	1.331		
S.Dev	0.019		

FUNC: MEASURE

COL : 0.100 mm

Ni
SS

SEC : 15 Sec



도금원소 : Ni//SS

측정값 개수 5

최대값 1.348

최소값 1.310

범위 0.038

평균값 1.331

표준편차 0.019

변동계수 1.416

우리하이피(주)

