

Third Party Inspection Report on
50 Bedded Field Hospital in the Campus of
Community Health Centre, Dist. Bhadohi (UP)

A. General

1	Reference letter no.	2113/Work-167, Dated: 21/12/2024
2	Date of Inspection	4 th Jan., 2025
3	Name of Construction Agency	UPRNSS Ltd. Mirzapur
	Name of Contractor	M/s Santosh Kumar Singh
4	Name of Architect	Arch Wing, Lucknow
5	Name of Structural Consultant	Span Structures, Lucknow
6	Name of the officials present during site inspection	Er. Ajay Singh, AE, UPRNSS, Mirzapur Er. Dinanath Yadav, JE, UPRNSS, Mirzapur Er. Govind Mohan Singh, JE, UPRNSS, Mirzapur Mr. Santosh Kumar Singh, Contractor
7	% progress of work at the time of inspection	100 %
8	Type of work	RCC Framed Structure

B. Detail of the site elements

1. Hospital building
2. CC Interlocking
3. Storm water drain
4. Septic tank and soak pit
5. Internal and External Water supply & Sanitation work
6. Fire fighting work
7. Electrical work

Krishna Kant
 Prof. K.K. PATHAK
 Department of Civil Engineering
 Indian Institute of Technology
 Banaras Hindu University
 Varanasi-221005

C. Progress of the work

Following is the progress of work-

Sr. No.	Elements	Progress	Remarks
1	Hospital building, Framed structure, Ground+1	Completed as per the specification	Quality of work is satisfactory
2	CC interlocking	Completed as per the specification	Quality of work is satisfactory
3	Storm water drain	Completed as per the specification	Quality of work is satisfactory
4	Septic tank and soak pit	Completed as per the specification	Quality of work is satisfactory
5	Internal and External Water supply & Sanitation work	Completed as per the specification	Quality of work is satisfactory

6	Fire fighting work	Completed as per the specification	Quality of work is satisfactory
7	Electrical work		
Overall Progress		100 %	

D. Material used

1	Concrete	M25
2	Brick	1 st class.
3	Cement	Ultratech cement
4	Reinforcement	Kamdhenu Fe 500, ECO Plus
5	Sand	Zone 2
6	Mortar	1:4 in ½ brickwall , 1:6 in plastering and 1 brickwall.

E. Routine quality control


1	Material testing report	MTC reports
2	Quality inspection	Regular inspection by competent committees
3	Vetted design and drawing details	Approved drawings are available at site.
4	Testing facilities at the site	Not available
5	Soil investigation report	Carried out by Geotechnical Associates Pvt. Ltd., Varanasi. SBC is 12 T/m ²

F. Quality statement

The overall quality of the construction of the 50 Bedded Field Hospital in the Campus of Community Health Centre, Dist. Bhadohi (UP) is found satisfactory.

G. Recommendations:

- Rough surfaces on walls and door panels should be properly finished.
- Gaps of the tiles should be grouted.
- Fittings of the toilets should be properly fixed.
- Campus should be properly cleaned before handover.


Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005

Prof. K.K. Pathak
Department of Civil Engineering
Indian Institute of Technology (BHU), Varanasi



Fig. 1: Front view of the building

Kishore Pathak

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005



Fig. 2: CC road and railing

Krishna Caut
Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005



Fig. 3: Fire fighting work

Krishna Kant
Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005



Fig. 4: Verification of the documents

Krishna Kant

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005




Fig. 5: Ramp sheet covering

Kishna Kant

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005



Fig. 6: Hospital Room



Fig. 7: Status of the ramp




Fig. 8: Checking of the wall tiles