Bayer Large Scale Dicamba Off Target Movement (OTM) Study

Summary of 20-ARL-SB24 study

Rodrigo Werle¹, Ryan DeWerff², Nick Arneson³, Sarah Striegel ⁴, Nikola Arsenijevic⁵, Felipe Faleco⁵, Kolby Grint⁵, Haleigh Ortmeier-Clarke⁵, Jose Nunes⁶ and Emily Glaeser⁷

¹ Principal Investigator, ² Research Technician, ³ Outreach Research and Extension Associate, ⁴ Former Graduate Student, ⁵ Graduate Student, ⁶ Visiting Scholar, ⁷ Undergraduate Research Assistant

Questions on the contents of this report should be directed to Rodrigo Werle (reverle@wisc.edu) and Sarah Striegel (sstriegel@wisc.edu).



Contents

1	Methods	6
	1.1 Plant Material and Area Management	6
	1.2 Modeling	
2	Results	8
	2.1 Weather data	8
	2.2 Modeling injury on non-DR soybean	11
	2.2.1 East	11
	2.2.2 North	15
	2.2.3 West	19
	2.2.4 South	23
	2.3 GPS mapping to 5% injury	27

List of Figures

Figure 1. Wind-rose of frequency and speed averaged three days after dicamba treats application at the University of Wisconsin-Madison	
Figure 2. Wind-rose of frequency and speed in each of the three days after dicamba treatment application at the University of Wisconsin-Madison	
Figure 3. Non-DR soybean injury with distance from the treated block in the East direction 21 DAT	
Figure 4. Non-DR soybean height with distance from the treated block in the East direction 21 DAT	12
Figure 5. Non-DR soybean injury under the covered area in the East direction 21 DAT	
Figure 6. Non-DR soybean injury under the non-covered area in the East direction 2 DAT	
Figure 7. Non-DR soybean injury with distance from the treated block in the North direction 21 DAT	
Figure 8. Non-DR soybean height with distance from the treated block in the North direction 21 DAT	
Figure 9. Non-DR soybean injury under the covered area in the North direction 21 DAT	17
Figure 10. Non-DR soybean injury under the non-covered area in the North direction 21 DAT	
Figure 11. Non-DR soybean injury with distance from the treated block in the West direction 21 DAT	
Figure 12. Non-DR soybean height with distance from the treated block in the West direction 21 DAT	t
Figure 13. Non-DR soybean injury under the covered area in the West direction 21 DAT	
Figure 14. Non-DR soybean injury under the non-covered area in the West direction 21 DAT	
Figure 15. Non-DR soybean injury with distance from the treated block in the South direction 21 DAT	n
Figure 16. Non-DR soybean height with distance from the treated block in the Sout direction 21 DAT	h
Figure 17. Non-DR soybean injury under the covered area in the South direction 21 DAT	
Figure 18. Non-DR sovbean injury under the non-covered area in the South direction	

	21 DAT	26
Figure 19.	Distance to 5% non-DR soybean injury from edges of treated block at 14	
	DAT	27
Figure 20.	Distance to 5% non-DR soybean injury from edges of treated block at 21	
	DAT	28

List of Tables

Table 1. Weather data of the three days after POST herbicide treatment in the large scale dicamba OTM study at the University of Wisconsin-Madison
Table 2. Parameter estimation of non-DR soybean injury in the East direction from the large scale dicamba OTM study at the University of Wisconsin-Madison 11
Table 3. Parameter estimation of non-DR soybean height in the East direction from the large scale dicamba OTM study at the University of Wisconsin-Madison 12
Table 4. Parameter estimation of non-DR soybean injury in the North direction from the large scale dicamba OTM study at the University of Wisconsin-Madison 15
Table 5. Parameter estimation of non-DR soybean height in the North direction from the large scale dicamba OTM study at the University of Wisconsin-Madison 16
Table 6. Parameter estimation of non-DR soybean injury in the West direction from the large scale dicamba OTM study at the University of Wisconsin-Madison 19
Table 7. Parameter estimation of non-DR soybean height in the West direction from the large scale dicamba OTM study at the University of Wisconsin-Madison 20
Table 8. Parameter estimation of non-DR soybean injury in the South direction from the large scale dicamba OTM study at the University of Wisconsin-Madison 23
Table 9. Parameter estimation of non-DR soybean height in the South direction from the large scale dicamba OTM study at the University of Wisconsin-Madison 24

1 Methods

1.1 Plant Material and Area Management

- Soybean variety
 - o Dicamba-resistant (DR) soybean: AG21X7
 - o Non-DR soybean: Stine 19BA23 (GT/LL)
- Soybean seeding rate: 160,000 seeds ac⁻¹ at 1.25" depth
- Soybean row width: 30" row width
- Soybean planting date: May 22
- Herbicide application
 - o PRE: May 22, 4 oz ac⁻¹ Sonic + 24 fl oz ac⁻¹ Moccasin II Plus
 - o POST: June 17, 24 fl oz ac⁻¹ Durango DMA + 6 fl oz ac⁻¹ Clethodim 2EC
- POST herbicide treatment (Xtendimax) application: 12:55 to 1:12 PM June 30
 - o Plastic removal –

South transect, 2:03 PM

West transect, 2:10 PM

North transect, 2:17 PM

East transect, 2:24 PM

- Soybean stage at POST application date:
 - o DR soybean: V5 stage; ht range -17.5 to 26.5-cm, avg -25-cm
 - Non-DR soybean: V5 stage; ht range 24 to 28-cm, avg 26.5-cm
- Results presented at 21 DAT (days after treatment)
- GPS waypoints to 5% soybean injury from treated area edges presented at 14 and 21 DAT
- Photos taken at 21 DAT

1.2 Modeling

Non-DR soybean injury (%) was collected from three soybean plant distance⁻¹ at 21 DAT. A three-parameter logistic model (Equation 1) was fit to non-DR soybean injury (%) over distance from the dicamba treated area (m) using the "drc" package 3.0-1.

Equation 1:

$$Y = \frac{d}{(1 + \exp \left[b(\log (x) - \log (e))\right]}$$

where Y is the non-DR soybean injury (%), x is the distance (m) from the dicamba treated area, the parameter d is the upper limit (asymptote), the parameter b is the slope, and the parameter e is the ED₅₀ (effective x that causes 50% reduction in Y).

Non-DR soybean height (cm) was collected from three soybean plant distance⁻¹ at 21 DAT. A linear model (Equation 2) was fit to non-DR soybean height (cm) over distance from the dicamba treated area (m).

Equation 2:

$$Y = A + bx$$

Where Y is the non-DR soybean height (cm), x is the distance (m) from the dicamba treated area, and b is the slope.

2 Results

2.1 Weather Data

Table 1. Weather data of the three days after POST herbicide treatment in the large Scale dicamba OTM study at the University of Wisconsin-Madison.^a

Date	Relative humidity (%)		Air temp (C)		Wind speed (m s ⁻¹)		m s ⁻¹)		
	Avg	Max	Min	Avg	Max	Min	Avg	Max	Min
0-24 h	77.0	93.5	54.7	25.1	30.5	19.8	2.8	8.0	0.6
24-48 h	66.7	94.0	46.3	23.7	29.9	16.6	1.9	6.7	0.0
48-72 h	69.3	96.5	44.6	25.1	29.9	18.2	1.3	5.7	0.0

^aWeather data obtained from Campbell Scientific CR300 datalogger equipped with a Vaisala Temperature/RH probe 1.7-m from the ground and a WindSonic4-L 2-D Sonic Wind Sensor with SDI-12 Output 3.1-m from the ground and programmed to collect measurements every 3-seconds to record 5-second averages for all parameters.




Figure 1. Wind-rose of frequency and speed averaged three days after dicamba treatment application at the University of Wisconsin-Madison.





Figure 2. Wind-rose of frequency and speed in each of the three days after dicamba treatment application at the University of Wisconsin-Madison.

2.2 Modeling injury on non-DR soybean

2.2.1 East

East transect



Source: University of Wisconsin-Madison Cropping Systems Weed Science, 2020

Figure 3. Non-DR soybean injury with distance from the treated block in the East direction 21 DAT.

Table 2. Parameter estimation of non-DR soybean injury in the East direction from the large scale dicamba OTM study at the University of Wisconsin-Madison.

<u>o</u>		J		
Parameter	Туре	Estimate	Standard error	P-value
Clone	Covered	1.7	0.5	0.00
Slope	Non-covered	1.2	0.3	0.00
TT1!!4	Covered	40.0^{a}	na	na
Upper limit	Non-covered	40.0^{a}	na	na
I. (I	Covered	1.0	0.2	0.00
Inflection point	Non-covered	0.9	0.2	0.00

^aParameter was set to maximum observed injury due to model overfitting.

East transect




Figure 4. Non-DR soybean height with distance from the treated block in the East direction 21 DAT.

Table 3. Parameter estimation of non-DR soybean height in the East direction from the large scale dicamba OTM study at the University of Wisconsin-Madison.

Parameter	Туре	Estimate	Standard error	P-value
Intomont	Covered	68.5	0.9	0.00
Intercept	Non-covered	75.8	1.0	0.00
C1	Covered	-0.2	0.1	0.10
Slope	Non-covered	-0.6	0.1	0.00





Figure 5. Non-DR soybean injury under the covered area in the East direction 21 DAT.



Figure 6. Non-DR soybean injury under the non-covered area in the East direction 21 DAT.

2.2.2 North

North transect



Source: University of Wisconsin-Madison Cropping Systems Weed Science, 2020

Figure 7. Non-DR soybean injury with distance from the treated block in the North direction 21 DAT.

Table 4. Parameter estimation of non-DR soybean injury in the North direction from the large scale dicamba OTM study at the University of Wisconsin-Madison.

Parameter	Туре	Estimate	Standard error	P-value
Clama	Covered	2.0	0.2	0.00
Slope	Non-covered	3.5	0.3	0.00
I Immon limit	Covered	42.7	3.2	0.00
Upper limit	Non-covered	40.7	0.8	0.00
Infloation point	Covered	3.1	0.3	0.00
Inflection point	Non-covered	20.7	0.7	0.00

North transect




Figure 8. Non-DR soybean height with distance from the treated block in the North direction 21 DAT.

Table 5. Parameter estimation of non-DR soybean height in the North direction from the large scale dicamba OTM study at the University of Wisconsin-Madison.

Parameter	Туре	Estimate	Standard error	P-value
Intonont	Covered	68.5	1.0	0.00
Intercept	Non-covered	58.2	1.5	0.00
C1	Covered	0.2	0.1	0.10
Slope	Non-covered	0.3	0.1	0.00





Figure 9. Non-DR soybean injury under the covered area in the North direction 21 DAT.



Figure 10. Non-DR soybean injury under the non-covered area in the North direction 21 DAT.

West transect



Source: University of Wisconsin-Madison Cropping Systems Weed Science, 2020

Figure 11. Non-DR soybean injury with distance from the treated block in the West direction 21 DAT.

Table 6. Parameter estimation of non-DR soybean injury in the West direction from the large scale dicamba OTM study at the University of Wisconsin-Madison.

Parameter	Туре	Estimate	Standard error	P-value
Slope	Covered	2.8	0.5	0.00
Slope	Non-covered	1.6	0.1	0.00
Upper limit	Covered	35.6	1.3	0.00
Opper mint	Non-covered	57.6	1.2	0.00
Inflection point	Covered	12.5	0.5	0.00
point	Non-covered	18.3	0.8	0.00

West transect




Figure 12. Non-DR soybean height with distance from the treated block in the West direction 21 DAT.

Table 7. Parameter estimation of non-DR soybean height in the West direction from the large scale dicamba OTM study at the University of Wisconsin-Madison.

Parameter	Туре	Estimate	Standard error	P-value
Intonont	Covered	65.8	1.4	0.00
Intercept	Non-covered	60.5	1.6	0.00
C1	Covered	0.1	0.1	0.67
Slope	Non-covered	-0.2	0.1	0.05




Figure 13. Non-DR soybean injury under the covered area in the West direction 21 DAT.





Figure 14. Non-DR soybean injury under the non-covered area in the West direction 21 DAT.

South transect



Source: University of Wisconsin-Madison Cropping Systems Weed Science, 2020 Figure 15. Non-DR soybean injury with distance from the treated block in the South

direction 21 DAT.b

Table 8. Parameter estimation of non-DR soybean injury in the South direction from the large scale dicamba OTM study at the University of Wisconsin-Madison.^b

Parameter	Туре	Estimate	Standard error	P-value
Clana	Covered	3.7	1.4	0.01
Slope	Non-covered	1.7	0.6	0.00
Hanna limit	Covered	20.0^{a}	na	na
Upper limit	Non-covered	20.0^{a}	na	na
Inflection point	Covered	1.6	0.1	0.00
milection point	Non-covered	0.9	0.3	0.01

^aParameter was set to maximum observed injury due to model overfitting.

^bData collected 0.8-m from treated area were excluded from modeling for this transect due to direct exposure and extreme values (e.g. 80% injury and 20-cm ht).

South transect




Figure 16. Non-DR soybean height with distance from the treated block in the South

Table 9. Parameter estimation of non-DR soybean height in the South direction from

direction 21 DAT.b

the large scale dicamba OTM study at the University of Wisconsin-Madison. ^b					
	Parameter	Туре	Estimate	Standard error	P-value
	Intercept	Covered	68.4	1.3	0.00
		Non-covered	69.4	1.9	0.00
	Slope	Covered	0.4	0.1	0.00
		Non-covered	0.0	0.1	0.11

^bData collected 0.8-m from treated area were excluded from modeling for this transect due to direct exposure and extreme values (e.g. 80% injury and 20-cm ht).




Figure 17. Non-DR soybean injury under the covered area in the South direction 21 DAT.




Figure 18. Non-DR soybean injury under the non-covered area in the South direction 21 DAT.

2.3 GPS mapping to 5% injury.



Figure 19. Distance to 5% non-DR soybean injury from edges of treated block at 14 DAT.



Figure 20. Distance to 5% non-DR soybean injury from edges of treated block at 21 DAT.