

Weld Bead Trench Artifact (C05_top)
Documented in results/geometry/LIMITATIONS.md L2


C05: Color Image
(Convex MIG weld cap visible)



C05: Depth Image
(Weld appears as DARKER = farther)



Depth Profiles: Weld Reads as TRENCH (positive = farther)



L2: Depth Sensor Artifact Explanation

