
Boundary-map provenance: a retained point follows the wrong motion
412 shifts; no new support, fusion or carving
Stored point: original map transport
Same anchor: accepted local reference
Last fresh support (25.2 s)
True material position at 45.8 s
World y (m)
5.2
5.0
4.8
4.6
2.0
2.2
2.4
2.6
2.8
3.0
3.2
3.4
World x (m)
One selected historical point
Distance to current true boundary (mm)
800
700
600
500
400
300
200
100
0
748.755
1.187
Original map
Reference placement
Retrospective geometry diagnostic on one known failure. No new physics or validated controller outcome.
Boundary distance is not material-point error: reference placement still has 22.973 mm material error.