




(a) Raw Measured Cepstrum $P_{2D}(x)$ — Case 4: High-Fidelity Transmission Corridor Baseline ($S=80$ m, $n=4$)




(b) Sub-Process 1: Multi-Path Reverberation & Harmonic Peeling Operator



(c) Sub-Process 2: Cascaded Transmission Loss & Destructive Phase Equalization



(d) Sub-Process 3: Single-Cluster Physical Aperture Focusing & Ripple Stripping



(e) Output: Reconstructed True Fracture Profile & Spatial Authenticity Map

