


- ▲ Source main — Module DMM MIN-MAX × Historical contact fault
● Module main ★ M0 retest (3.241 V)

(a) Zero load



(b) Loaded (recorded)

