
Düz kasar 132 Makinesinde Tespit Edilen Kumas Hatalari

Tarih: 2.10.2023

Hafta	delik	leke
2.10.2023-2.10.2023	77	1



2.10.2023-2.10.2023'leri arasinda hata tespit turleri;


2.10.2023-2.10.2023'leri arasinda tespit edilen Delik ve Leke sayisi: 77-1 (Adet)

Düz kasar 132 Makinesinde Tespit Edilen Kumas Hatalari

Tarih: 2.10.2023


Tarih	Dok No	Kalite No	Delik Sayisi	Leke Sayisi
2.10.2023	0	RANFORCE	43	1














menderes	Düz kasar 132 Makinesinde Tespit Edilen Kumas Hatalari	

Dok No:0	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	45	
Hatanin Geldigi Metre(m)	0	
Hata Eni(mm)	22.02	
Hata Boyu(mm)	10.74	
Hata Alani(mm2)	236.49	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	2.10.2023	

Dok No:0	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	106		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	17.19		
Hata Boyu(mm)	15.04		
Hata Alani(mm2)	258.54		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	89	
Hatanin Geldigi Metre(m)	0	
Hata Eni(mm)	7.52	
Hata Boyu(mm)	3.22	
Hata Alani(mm2)	24.21	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	2.10.2023	

Dok No:0	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	33		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	8.06		
Hata Boyu(mm)	3.76		
Hata Alani(mm2)	30.31		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	45		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	20.95		
Hata Boyu(mm)	10.74		
Hata Alani(mm2)	225		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	106		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	17.19		
Hata Boyu(mm)	15.04		
Hata Alani(mm2)	258.54		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	89		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	8.06		
Hata Boyu(mm)	3.76		
Hata Alani(mm2)	30.31		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	33	
Hatanin Geldigi Metre(m)	0	
Hata Eni(mm)	8.06	
Hata Boyu(mm)	4.3	
Hata Alani(mm2)	34.66	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	2.10.2023	

Dok No:0	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	45		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	20.41		
Hata Boyu(mm)	10.74		
Hata Alani(mm2)	219.2		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	106		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	17.19		
Hata Boyu(mm)	15.04		
Hata Alani(mm2)	258.54		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	12		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	8.06		
Hata Boyu(mm)	3.76		
Hata Alani(mm2)	30.31		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	45		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	21.48		
Hata Boyu(mm)	10.74		
Hata Alani(mm2)	230.7		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Düz kasar 132 Makinesinde	
Tespit Edilen Kumas	
Hatalari	

Dok No:0	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	106		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	18.8		
Hata Boyu(mm)	15.04		
Hata Alani(mm2)	282.75		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	106		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	17.19		
Hata Boyu(mm)	14.5		
Hata Alani(mm2)	249.26		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	45		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	20.95		
Hata Boyu(mm)	10.74		
Hata Alani(mm2)	225		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORC	E
Hatanin Yatay Konumu(cm)	8	
Hatanin Geldigi Metre(m)	0	
Hata Eni(mm)	8.06	_
Hata Boyu(mm)	3.22	
Hata Alani(mm2)	25.95	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	2.10.2023	

Dok No:0	Kalite No:RANFORO	E
Hatanin Yatay Konumu(cm)	12	
Hatanin Geldigi Metre(m)	0	
Hata Eni(mm)	7.52	_
Hata Boyu(mm)	3.76	
Hata Alani(mm2)	28.28	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	2.10.2023	

Dok No:0	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	12		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	7.52		
Hata Boyu(mm)	3.76		
Hata Alani(mm2)	28.28		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORCE		
Hatanin Yatay Konumu(cm)	33		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	8.59	_	
Hata Boyu(mm)	4.3		
Hata Alani(mm2)	36.94		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	45	
Hatanin Geldigi Metre(m)	0	
Hata Eni(mm)	21.48	
Hata Boyu(mm)	10.74	
Hata Alani(mm2)	230.7	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	2.10.2023	

Dok No:0	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	106		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	16.65		
Hata Boyu(mm)	14.5		
Hata Alani(mm2)	241.42		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	33		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	8.59		
Hata Boyu(mm)	4.83		
Hata Alani(mm2)	41.49		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFOR	CE
Hatanin Yatay Konumu(cm)	89	
Hatanin Geldigi Metre(m)	0	
Hata Eni(mm)	8.06	
Hata Boyu(mm)	3.22	
Hata Alani(mm2)	25.95	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	2.10.2023	

Dok No:0	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	14	
Hatanin Geldigi Metre(m)	0	
Hata Eni(mm)	7.52	
Hata Boyu(mm)	3.22	
Hata Alani(mm2)	24.21	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	2.10.2023	

Dok No:0	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	28		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	31.69		
Hata Boyu(mm)	13.96		
Hata Alani(mm2)	442.39		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	106		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	17.72		
Hata Boyu(mm)	14.5		
Hata Alani(mm2)	256.94		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	15		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	6.98		
Hata Boyu(mm)	3.22		
Hata Alani(mm2)	22.48		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	45	
Hatanin Geldigi Metre(m)	0	
Hata Eni(mm)	21.48	
Hata Boyu(mm)	10.74	
Hata Alani(mm2)	230.7	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	2.10.2023	

Dok No:0	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	106		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	18.26		
Hata Boyu(mm)	14.5		
Hata Alani(mm2)	264.77		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	45		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	21.48		
Hata Boyu(mm)	10.74		
Hata Alani(mm2)	230.7		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	45		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	20.95		
Hata Boyu(mm)	10.74		
Hata Alani(mm2)	225		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	106	
Hatanin Geldigi Metre(m)	0	
Hata Eni(mm)	16.65	
Hata Boyu(mm)	14.5	
Hata Alani(mm2)	241.42	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	2.10.2023	

Dok No:0	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	96		
Hatanin Geldigi Metre(m)	0		
Hata Eni(mm)	8.06		
Hata Boyu(mm)	3.22		
Hata Alani(mm2)	25.95		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	2.10.2023		

Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	45
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	22.02
Hata Boyu(mm)	11.28
Hata Alani(mm2)	248.39
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023



Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	106
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	17.72
Hata Boyu(mm)	15.04
Hata Alani(mm2)	266.51
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023



Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	45
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	22.56
Hata Boyu(mm)	11.28
Hata Alani(mm2)	254.48
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023



Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	106
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	17.72
Hata Boyu(mm)	14.5
Hata Alani(mm2)	256.94
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023




Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	45
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	22.56
Hata Boyu(mm)	11.28
Hata Alani(mm2)	254.48
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023



Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	106
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	18.26
Hata Boyu(mm)	14.5
Hata Alani(mm2)	264.77
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023



Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	45
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	21.48
Hata Boyu(mm)	11.28
Hata Alani(mm2)	242.29
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023



Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	106
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	17.72
Hata Boyu(mm)	15.04
Hata Alani(mm2)	266.51
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023



Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	106
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	17.72
Hata Boyu(mm)	15.04
Hata Alani(mm2)	266.51
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023



Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	45
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	22.56
Hata Boyu(mm)	11.82
Hata Alani(mm2)	266.66
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023



Dok No:0	Kalite No:RANFORCE
Hatanin Yatay Konumu(cm)	89
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	6.45
Hata Boyu(mm)	2.69
Hata Alani(mm2)	17.35
Hata Sinifi	delik
Hatanin Geldigi Tarih	2.10.2023

