
Merserize Makinesinde Tespit Edilen Kumas Hatalari

Tarih: 4.4.2023

Hafta	delik	leke
3.4.2023-4.4.2023	108	463



3.4.2023-4.4.2023'leri arasinda hata tespit turleri;


3.4.2023-4.4.2023'leri arasinda tespit edilen Delik ve Leke sayisi: 108-463 (Adet)


Merserize Makinesinde Tespit Edilen Kumas Hatalari

Tarih: 4.4.2023

Tarih	Dok No	Kalite No	Delik Sayisi	Leke Sayisi
31.3.2023	1868	RANFORCE	1	12
31.3.2023	1868	SATEN(IS	1	10
31.3.2023	1823	SATEN(IS	63	226
31.3.2023	1600	RANFORCE	7	117
31.3.2023	4027	RANFORCE	6	213
31.3.2023	1386	RANFORCE	0	225
31.3.2023	745	RANFORCE	0	139
1.4.2023	2139	GB	3	153
1.4.2023	627	GB	20	699
1.4.2023	537	GB	8	164
1.4.2023	1237	SATEN(IS	54	94
1.4.2023	1227	SATEN(IS	15	48
1.4.2023	704	RANFORCE	2	48
1.4.2023	1474	RANFORCE	27	269
1.4.2023	1460	GB	2	151
1.4.2023	1132	GB	1	144
1.4.2023	508	SATEN(IS	13	90
1.4.2023	1699	SATEN(IS	49	301
1.4.2023	930	RANFORCE	4	127
3.4.2023	1482	WF	70	0

3.4.2023	119	GB	10	137
3.4.2023	176	GB	4	166
3.4.2023	240	GB	13	88
3.4.2023	171	GB	3	30
4.4.2023	171	GB	1	12
4.4.2023	478	GB	5	30
4.4.2023	1014	WF	2	0





Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	6.88	
Hatanin Geldigi Metre(m)	969	
Hata Eni(mm)	1.07	
Hata Boyu(mm)	1.03	
Hata Alani(mm2)	1.1	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:240	Kalite No:GB
Hatanin Yatay Konumu(cm)	14.56
Hatanin Geldigi Metre(m)	3487
Hata Eni(mm)	1.12
Hata Boyu(mm)	3.27
Hata Alani(mm2)	3.66
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023




Dok No:1823	Kalite No:SATEN(IS	3	
Hatanin Yatay Konumu(cm)	11.15		
Hatanin Geldigi Metre(m)	4151		
Hata Eni(mm)	1.07	_	
Hata Boyu(mm)	2.39		
Hata Alani(mm2)	2.56		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.9
Hatanin Geldigi Metre(m)	908
Hata Eni(mm)	3.37
Hata Boyu(mm)	12.45
Hata Alani(mm2)	41.96
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023








Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	0.91	
Hatanin Geldigi Metre(m)	5731	
Hata Eni(mm)	1.22	
Hata Boyu(mm)	2.34	
Hata Alani(mm2)	2.85	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:745	Kalite No:RANFORO	Œ	
Hatanin Yatay Konumu(cm)	2.61		
Hatanin Geldigi Metre(m)	2224		
Hata Eni(mm)	2		
Hata Boyu(mm)	1.46		
Hata Alani(mm2)	2.92		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:240	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.9
Hatanin Geldigi Metre(m)	875
Hata Eni(mm)	3.27
Hata Boyu(mm)	12.55
Hata Alani(mm2)	41.04
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.91
Hatanin Geldigi Metre(m)	834
Hata Eni(mm)	3.27
Hata Boyu(mm)	12.26
Hata Alani(mm2)	40.09
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	15.44
Hatanin Geldigi Metre(m)	1749
Hata Eni(mm)	1.12
Hata Boyu(mm)	3.12
Hata Alani(mm2)	3.49
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:240	Kalite No:GB
Hatanin Yatay Konumu(cm)	16.64
Hatanin Geldigi Metre(m)	2833
Hata Eni(mm)	2.73
Hata Boyu(mm)	3.76
Hata Alani(mm2)	10.26
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023



Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	7.96	
Hatanin Geldigi Metre(m)	2403	
Hata Eni(mm)	1.46	
Hata Boyu(mm)	0.73	
Hata Alani(mm2)	1.07	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	_

Dok No:4027	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	3.39		
Hatanin Geldigi Metre(m)	278		
Hata Eni(mm)	4.2		
Hata Boyu(mm)	5.91		
Hata Alani(mm2)	24.82		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1386	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	19.94		
Hatanin Geldigi Metre(m)	3063		
Hata Eni(mm)	0.93	_	
Hata Boyu(mm)	1.03		
Hata Alani(mm2)	0.96		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	10.19	
Hatanin Geldigi Metre(m)	2452	
Hata Eni(mm)	2.29	
Hata Boyu(mm)	4.44	
Hata Alani(mm2)	10.17	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:4027	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	16.77	
Hatanin Geldigi Metre(m)	3315	
Hata Eni(mm)	2.83	
Hata Boyu(mm)	1.51	
Hata Alani(mm2)	4.27	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	16.56
Hatanin Geldigi Metre(m)	216
Hata Eni(mm)	2.69
Hata Boyu(mm)	5.37
Hata Alani(mm2)	14.45
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1482	Kalite No:WF
Hatanin Yatay Konumu(cm)	8.79
Hatanin Geldigi Metre(m)	47
Hata Eni(mm)	1.22
Hata Boyu(mm)	1.27
Hata Alani(mm2)	1.55
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023



Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.9
Hatanin Geldigi Metre(m)	994
Hata Eni(mm)	3.17
Hata Boyu(mm)	12.35
Hata Alani(mm2)	39.15
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	9.15	
Hatanin Geldigi Metre(m)	3966	
Hata Eni(mm)	2.49	
Hata Boyu(mm)	1.17	
Hata Alani(mm2)	2.91	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1482	Kalite No:WF
Hatanin Yatay Konumu(cm)	11.8
Hatanin Geldigi Metre(m)	208
Hata Eni(mm)	1.22
Hata Boyu(mm)	0.98
Hata Alani(mm2)	1.2
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023



Dok No:1823	Kalite No:SATEN(IS	3	
Hatanin Yatay Konumu(cm)	6.13		
Hatanin Geldigi Metre(m)	2445		
Hata Eni(mm)	2.98		
Hata Boyu(mm)	2.78		
Hata Alani(mm2)	8.28		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1600	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	9.92		
Hatanin Geldigi Metre(m)	2269		
Hata Eni(mm)	0.98		
Hata Boyu(mm)	3.22		
Hata Alani(mm2)	3.16		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:745	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	0.1	
Hatanin Geldigi Metre(m)	2610	
Hata Eni(mm)	1.61	
Hata Boyu(mm)	1.66	
Hata Alani(mm2)	2.67	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	_

Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	13.38	
Hatanin Geldigi Metre(m)	5931	
Hata Eni(mm)	1.66	
Hata Boyu(mm)	0.78	
Hata Alani(mm2)	1.29	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	


Dok No:1823	Kalite No:SATEN(IS	3	
Hatanin Yatay Konumu(cm)	10.05		
Hatanin Geldigi Metre(m)	4854		
Hata Eni(mm)	2.25		
Hata Boyu(mm)	0.68		
Hata Alani(mm2)	1.53		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS	3	
Hatanin Yatay Konumu(cm)	9.71		
Hatanin Geldigi Metre(m)	4133		
Hata Eni(mm)	1.76		
Hata Boyu(mm)	0.68		
Hata Alani(mm2)	1.2		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:4027	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	18.2	
Hatanin Geldigi Metre(m)	1023	
Hata Eni(mm)	3.32	
Hata Boyu(mm)	2.59	
Hata Alani(mm2)	8.6	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	_

Dok No:4027	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	0.4		
Hatanin Geldigi Metre(m)	1646		
Hata Eni(mm)	1.17		
Hata Boyu(mm)	0.78		
Hata Alani(mm2)	0.91		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.89
Hatanin Geldigi Metre(m)	917
Hata Eni(mm)	3.37
Hata Boyu(mm)	12.55
Hata Alani(mm2)	42.29
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1386	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	9.35		
Hatanin Geldigi Metre(m)	3023		
Hata Eni(mm)	1.07		
Hata Boyu(mm)	1.9		
Hata Alani(mm2)	2.03		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	9.62	
Hatanin Geldigi Metre(m)	251	
Hata Eni(mm)	1.46	
Hata Boyu(mm)	0.88	
Hata Alani(mm2)	1.28	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	





Dok No:745	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	0.09		
Hatanin Geldigi Metre(m)	1340		
Hata Eni(mm)	1.03		
Hata Boyu(mm)	0.83		
Hata Alani(mm2)	0.85		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:4027	Kalite No:RANFORO	E
Hatanin Yatay Konumu(cm)	6.37	
Hatanin Geldigi Metre(m)	913	
Hata Eni(mm)	1.42	_
Hata Boyu(mm)	0.98	
Hata Alani(mm2)	1.39	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1600	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	16.68	
Hatanin Geldigi Metre(m)	1757	
Hata Eni(mm)	3.27	
Hata Boyu(mm)	0.88	
Hata Alani(mm2)	2.88	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:745	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	0.61		
Hatanin Geldigi Metre(m)	1854		
Hata Eni(mm)	3.76		
Hata Boyu(mm)	1.46		
Hata Alani(mm2)	5.49		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:240	Kalite No:GB
Hatanin Yatay Konumu(cm)	15.78
Hatanin Geldigi Metre(m)	2332
Hata Eni(mm)	2.1
Hata Boyu(mm)	3.86
Hata Alani(mm2)	8.11
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	11.46	
Hatanin Geldigi Metre(m)	592	
Hata Eni(mm)	0.78	_
Hata Boyu(mm)	0.83	
Hata Alani(mm2)	0.65	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:4027	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	4.7	
Hatanin Geldigi Metre(m)	143	
Hata Eni(mm)	1.46	
Hata Boyu(mm)	1.76	
Hata Alani(mm2)	2.57	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:745	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	12.04		
Hatanin Geldigi Metre(m)	2150		
Hata Eni(mm)	1.03		
Hata Boyu(mm)	2		
Hata Alani(mm2)	2.06		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	8.32	
Hatanin Geldigi Metre(m)	5130	
Hata Eni(mm)	3.61	
Hata Boyu(mm)	1.12	
Hata Alani(mm2)	4.04	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	


Dok No:4027	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	16.59		
Hatanin Geldigi Metre(m)	2206		
Hata Eni(mm)	3.56		
Hata Boyu(mm)	2.39		
Hata Alani(mm2)	8.51		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:745	Kalite No:RANFORCE]
Hatanin Yatay Konumu(cm)	0.58	
Hatanin Geldigi Metre(m)	991	I
Hata Eni(mm)	0.93	
Hata Boyu(mm)	1.66	
Hata Alani(mm2)	1.54	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:4027	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	16.57	
Hatanin Geldigi Metre(m)	2522	
Hata Eni(mm)	2.05	
Hata Boyu(mm)	1.07	
Hata Alani(mm2)	2.19	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:4027	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	5.42		
Hatanin Geldigi Metre(m)	3517		
Hata Eni(mm)	1.81		
Hata Boyu(mm)	1.66		
Hata Alani(mm2)	3		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	15.41
Hatanin Geldigi Metre(m)	2020
Hata Eni(mm)	0.93
Hata Boyu(mm)	2.44
Hata Alani(mm2)	2.27
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	9.06	
Hatanin Geldigi Metre(m)	5810	
Hata Eni(mm)	0.78	
Hata Boyu(mm)	1.17	
Hata Alani(mm2)	0.91	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1386	Kalite No:RANFOR	CE
Hatanin Yatay Konumu(cm)	3.3	
Hatanin Geldigi Metre(m)	823	
Hata Eni(mm)	3.27	
Hata Boyu(mm)	0.88	
Hata Alani(mm2)	2.88	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:745	Kalite No:RANFORC	Έ	
Hatanin Yatay Konumu(cm)	10.13		
Hatanin Geldigi Metre(m)	555		
Hata Eni(mm)	1.12		
Hata Boyu(mm)	2.34		
Hata Alani(mm2)	2.62		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	7.28
Hatanin Geldigi Metre(m)	3021
Hata Eni(mm)	1.46
Hata Boyu(mm)	1.71
Hata Alani(mm2)	2.5
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1386	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	4.68	
Hatanin Geldigi Metre(m)	995	
Hata Eni(mm)	2.83	
Hata Boyu(mm)	1.9	
Hata Alani(mm2)	5.38	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	


Dok No:745	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	11.77		
Hatanin Geldigi Metre(m)	3147		
Hata Eni(mm)	3.22		
Hata Boyu(mm)	1.76		
Hata Alani(mm2)	5.67		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1386	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	6.99		
Hatanin Geldigi Metre(m)	3161		
Hata Eni(mm)	1.22		
Hata Boyu(mm)	1.42		
Hata Alani(mm2)	1.73		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(I	S	
Hatanin Yatay Konumu(cm)	9.41		
Hatanin Geldigi Metre(m)	5824		
Hata Eni(mm)	1.76		
Hata Boyu(mm)	0.59		
Hata Alani(mm2)	1.04		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		


Dok No:4027	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	3.13	
Hatanin Geldigi Metre(m)	1936	
Hata Eni(mm)	1.61	
Hata Boyu(mm)	1.9	
Hata Alani(mm2)	3.06	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	12.97
Hatanin Geldigi Metre(m)	223
Hata Eni(mm)	1.32
Hata Boyu(mm)	2.44
Hata Alani(mm2)	3.22
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1386	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	18.01		
Hatanin Geldigi Metre(m)	3217		
Hata Eni(mm)	3.17		
Hata Boyu(mm)	4.64		
Hata Alani(mm2)	14.71		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023	_	

Dok No:240	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.92
Hatanin Geldigi Metre(m)	968
Hata Eni(mm)	3.42
Hata Boyu(mm)	12.65
Hata Alani(mm2)	43.26
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:478	Kalite No:GB
Hatanin Yatay Konumu(cm)	0.06
Hatanin Geldigi Metre(m)	2149
Hata Eni(mm)	0.93
Hata Boyu(mm)	2.39
Hata Alani(mm2)	2.22
Hata Sinifi	leke
Hatanin Geldigi Tarih	4.4.2023



Dok No:1386	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	17.23	
Hatanin Geldigi Metre(m)	62	
Hata Eni(mm)	1.37	
Hata Boyu(mm)	0.73	
Hata Alani(mm2)	1	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	15.52
Hatanin Geldigi Metre(m)	1092
Hata Eni(mm)	1.51
Hata Boyu(mm)	3.66
Hata Alani(mm2)	5.53
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1386	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	14.64	
Hatanin Geldigi Metre(m)	2487	
Hata Eni(mm)	1.22	
Hata Boyu(mm)	1.17	
Hata Alani(mm2)	1.43	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	0.26	
Hatanin Geldigi Metre(m)	1115	
Hata Eni(mm)	1.03	<u> </u>
Hata Boyu(mm)	1.07	
Hata Alani(mm2)	1.1	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:171	Kalite No:GB	
Hatanin Yatay Konumu(cm)	11.96	
Hatanin Geldigi Metre(m)	3561	
Hata Eni(mm)	2.1	
Hata Boyu(mm)	3.81	
Hata Alani(mm2)	8	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	4.4.2023	


Dok No:1386	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	17.37		
Hatanin Geldigi Metre(m)	1779		
Hata Eni(mm)	2.54		
Hata Boyu(mm)	0.98		
Hata Alani(mm2)	2.49		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:745	Kalite No:RANFORCI	E
Hatanin Yatay Konumu(cm)	3.14	
Hatanin Geldigi Metre(m)	388	
Hata Eni(mm)	0.88	_
Hata Boyu(mm)	0.63	
Hata Alani(mm2)	0.55	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1600	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	8.75		
Hatanin Geldigi Metre(m)	2218		
Hata Eni(mm)	2.83		
Hata Boyu(mm)	0.73		
Hata Alani(mm2)	2.07		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		


Dok No:1600	Kalite No:RANFORO	Œ	
Hatanin Yatay Konumu(cm)	9.1		
Hatanin Geldigi Metre(m)	2498		
Hata Eni(mm)	1.46		
Hata Boyu(mm)	0.54		
Hata Alani(mm2)	0.79		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		


Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.9
Hatanin Geldigi Metre(m)	1007
Hata Eni(mm)	3.22
Hata Boyu(mm)	12.4
Hata Alani(mm2)	39.93
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:4027	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	17.99	
Hatanin Geldigi Metre(m)	583	
Hata Eni(mm)	2.1	
Hata Boyu(mm)	2.05	
Hata Alani(mm2)	4.3	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	11.87
Hatanin Geldigi Metre(m)	393
Hata Eni(mm)	1.07
Hata Boyu(mm)	3.27
Hata Alani(mm2)	3.5
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023







Dok No:745	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	0.12	
Hatanin Geldigi Metre(m)	2414	
Hata Eni(mm)	1.42	
Hata Boyu(mm)	0.88	
Hata Alani(mm2)	1.25	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	


Dok No:1386	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	6.55		
Hatanin Geldigi Metre(m)	1273		
Hata Eni(mm)	0.93		
Hata Boyu(mm)	0.83		
Hata Alani(mm2)	0.77		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1482	Kalite No:WF
Hatanin Yatay Konumu(cm)	8.91
Hatanin Geldigi Metre(m)	94
Hata Eni(mm)	1.51
Hata Boyu(mm)	1.12
Hata Alani(mm2)	1.69
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023



Dok No:1386	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	19.12		
Hatanin Geldigi Metre(m)	2011		
Hata Eni(mm)	1.76		
Hata Boyu(mm)	0.93		
Hata Alani(mm2)	1.64		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	8.67
Hatanin Geldigi Metre(m)	525
Hata Eni(mm)	0.98
Hata Boyu(mm)	3.56
Hata Alani(mm2)	3.49
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1386	Kalite No:RANFORCE		
Hatanin Yatay Konumu(cm)	18.04		
Hatanin Geldigi Metre(m)	2747		
Hata Eni(mm)	1.66	_	
Hata Boyu(mm)	0.88		
Hata Alani(mm2)	1.46		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.26
Hatanin Geldigi Metre(m)	740
Hata Eni(mm)	2.54
Hata Boyu(mm)	2.29
Hata Alani(mm2)	5.82
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1823	Kalite No:SATEN(I	S	
Hatanin Yatay Konumu(cm)	10.13		
Hatanin Geldigi Metre(m)	4604		
Hata Eni(mm)	0.83		
Hata Boyu(mm)	0.78		
Hata Alani(mm2)	0.65		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS	3	
Hatanin Yatay Konumu(cm)	1.15		
Hatanin Geldigi Metre(m)	5508		
Hata Eni(mm)	1.86		
Hata Boyu(mm)	4.05		
Hata Alani(mm2)	7.53		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1386	Kalite No:RANFORO	CE
Hatanin Yatay Konumu(cm)	16.68	
Hatanin Geldigi Metre(m)	1974	
Hata Eni(mm)	3.91	
Hata Boyu(mm)	1.37	
Hata Alani(mm2)	5.36	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	19.22	
Hatanin Geldigi Metre(m)	2618	
Hata Eni(mm)	1.61	
Hata Boyu(mm)	1.22	
Hata Alani(mm2)	1.96	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:745	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	17.87		
Hatanin Geldigi Metre(m)	2715		
Hata Eni(mm)	1.12		
Hata Boyu(mm)	0.54		
Hata Alani(mm2)	0.6		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1600	Kalite No:RANFORC	Έ	
Hatanin Yatay Konumu(cm)	11.22		
Hatanin Geldigi Metre(m)	3207		
Hata Eni(mm)	2.73	_	
Hata Boyu(mm)	2.15		
Hata Alani(mm2)	5.87		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(I	S	
Hatanin Yatay Konumu(cm)	11.24		
Hatanin Geldigi Metre(m)	2442		
Hata Eni(mm)	2.59		
Hata Boyu(mm)	9.77		
Hata Alani(mm2)	25.3		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	31.3.2023	_	

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.9
Hatanin Geldigi Metre(m)	813
Hata Eni(mm)	3.22
Hata Boyu(mm)	12.26
Hata Alani(mm2)	39.48
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:4027	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	3.57		
Hatanin Geldigi Metre(m)	1204		
Hata Eni(mm)	1.07		
Hata Boyu(mm)	2.05		
Hata Alani(mm2)	2.19		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1600	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	8.44		
Hatanin Geldigi Metre(m)	3183		
Hata Eni(mm)	1.51		
Hata Boyu(mm)	2.83		
Hata Alani(mm2)	4.27		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.9
Hatanin Geldigi Metre(m)	991
Hata Eni(mm)	3.37
Hata Boyu(mm)	12.55
Hata Alani(mm2)	42.29
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023




Dok No:1386	Kalite No:RANFORCE	Ξ
Hatanin Yatay Konumu(cm)	2.73	
Hatanin Geldigi Metre(m)	1317	
Hata Eni(mm)	1.07	
Hata Boyu(mm)	0.54	
Hata Alani(mm2)	0.58	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1600	Kalite No:RANFORCI	E	
Hatanin Yatay Konumu(cm)	4.94		
Hatanin Geldigi Metre(m)	2525		
Hata Eni(mm)	1.46		
Hata Boyu(mm)	5.62		
Hata Alani(mm2)	8.21		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023	_	

Dok No:240	Kalite No:GB
Hatanin Yatay Konumu(cm)	19.21
Hatanin Geldigi Metre(m)	2901
Hata Eni(mm)	1.86
Hata Boyu(mm)	2.73
Hata Alani(mm2)	5.08
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023




Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	15.38
Hatanin Geldigi Metre(m)	1760
Hata Eni(mm)	1.03
Hata Boyu(mm)	3.08
Hata Alani(mm2)	3.17
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:171	Kalite No:GB	
Hatanin Yatay Konumu(cm)	3.84	
Hatanin Geldigi Metre(m)	3134	
Hata Eni(mm)	1.46	
Hata Boyu(mm)	1.32	
Hata Alani(mm2)	1.93	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	4.4.2023	

Dok No:745	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	1.45		
Hatanin Geldigi Metre(m)	128		
Hata Eni(mm)	1.37		
Hata Boyu(mm)	0.73		
Hata Alani(mm2)	1		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.89
Hatanin Geldigi Metre(m)	930
Hata Eni(mm)	3.56
Hata Boyu(mm)	12.6
Hata Alani(mm2)	44.86
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023




Dok No:1600	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	9.3		
Hatanin Geldigi Metre(m)	2105		
Hata Eni(mm)	1.37		
Hata Boyu(mm)	0.68		
Hata Alani(mm2)	0.93		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1482	Kalite No:WF
Hatanin Yatay Konumu(cm)	11.91
Hatanin Geldigi Metre(m)	148
Hata Eni(mm)	1.42
Hata Boyu(mm)	1.12
Hata Alani(mm2)	1.59
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023



Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	9.19
Hatanin Geldigi Metre(m)	2117
Hata Eni(mm)	0.83
Hata Boyu(mm)	2.15
Hata Alani(mm2)	1.78
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:745	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	7.99	
Hatanin Geldigi Metre(m)	95	
Hata Eni(mm)	0.83	
Hata Boyu(mm)	1.12	
Hata Alani(mm2)	0.93	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:4027	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	3.11		
Hatanin Geldigi Metre(m)	458		
Hata Eni(mm)	2.1		
Hata Boyu(mm)	0.73		
Hata Alani(mm2)	1.53		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	7.73
Hatanin Geldigi Metre(m)	2801
Hata Eni(mm)	2.05
Hata Boyu(mm)	3.12
Hata Alani(mm2)	6.4
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:4027	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	1.01		
Hatanin Geldigi Metre(m)	1624		
Hata Eni(mm)	0.78		
Hata Boyu(mm)	1.76		
Hata Alani(mm2)	1.37		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:745	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	1.13		
Hatanin Geldigi Metre(m)	2224		
Hata Eni(mm)	1.56	_	
Hata Boyu(mm)	1.37		
Hata Alani(mm2)	2.14		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:4027	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	18.44	
Hatanin Geldigi Metre(m)	1858	
Hata Eni(mm)	3.12	
Hata Boyu(mm)	6.98	
Hata Alani(mm2)	21.78	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	17.43
Hatanin Geldigi Metre(m)	2485
Hata Eni(mm)	1.76
Hata Boyu(mm)	2.1
Hata Alani(mm2)	3.7
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1482	Kalite No:WF
Hatanin Yatay Konumu(cm)	8.76
Hatanin Geldigi Metre(m)	13
Hata Eni(mm)	1.61
Hata Boyu(mm)	1.46
Hata Alani(mm2)	2.35
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023




Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	15.57
Hatanin Geldigi Metre(m)	1135
Hata Eni(mm)	1.03
Hata Boyu(mm)	1.46
Hata Alani(mm2)	1.5
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023




Dok No:1386	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	18.14		
Hatanin Geldigi Metre(m)	2291		
Hata Eni(mm)	2.39	_	
Hata Boyu(mm)	0.88		
Hata Alani(mm2)	2.1		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:240	Kalite No:GB
Hatanin Yatay Konumu(cm)	5.01
Hatanin Geldigi Metre(m)	2798
Hata Eni(mm)	1.42
Hata Boyu(mm)	1.03
Hata Alani(mm2)	1.46
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023



Dok No:1386	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	1.96		
Hatanin Geldigi Metre(m)	856		
Hata Eni(mm)	1.17		
Hata Boyu(mm)	0.78		
Hata Alani(mm2)	0.91		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:478	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.72
Hatanin Geldigi Metre(m)	208
Hata Eni(mm)	1.12
Hata Boyu(mm)	0.78
Hata Alani(mm2)	0.87
Hata Sinifi	delik
Hatanin Geldigi Tarih	4.4.2023



Dok No:1600	Kalite No:RANFORCE		
Hatanin Yatay Konumu(cm)	10.4		
Hatanin Geldigi Metre(m)	2998		
Hata Eni(mm)	2.54	_	
Hata Boyu(mm)	2.69		
Hata Alani(mm2)	6.83		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1482	Kalite No:WF
Hatanin Yatay Konumu(cm)	11.91
Hatanin Geldigi Metre(m)	257
Hata Eni(mm)	1.42
Hata Boyu(mm)	1.22
Hata Alani(mm2)	1.73
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023



Dok No:1386	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	18.19		
Hatanin Geldigi Metre(m)	1651		
Hata Eni(mm)	2.05	_	
Hata Boyu(mm)	0.88		
Hata Alani(mm2)	1.8		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(I	S	
Hatanin Yatay Konumu(cm)	19.33		
Hatanin Geldigi Metre(m)	1883		
Hata Eni(mm)	2		
Hata Boyu(mm)	1.03		
Hata Alani(mm2)	2.06		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	11.59	
Hatanin Geldigi Metre(m)	2445	
Hata Eni(mm)	5.47	
Hata Boyu(mm)	12.6	
Hata Alani(mm2)	68.92	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1482	Kalite No:WF
Hatanin Yatay Konumu(cm)	11.91
Hatanin Geldigi Metre(m)	87
Hata Eni(mm)	1.12
Hata Boyu(mm)	1.76
Hata Alani(mm2)	1.97
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023




Dok No:1600	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	13.36		
Hatanin Geldigi Metre(m)	817		
Hata Eni(mm)	0.78	_	
Hata Boyu(mm)	0.83		
Hata Alani(mm2)	0.65		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS	S	
Hatanin Yatay Konumu(cm)	9.26		
Hatanin Geldigi Metre(m)	5896		
Hata Eni(mm)	2.64		
Hata Boyu(mm)	2		
Hata Alani(mm2)	5.28		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:745	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	6.05		
Hatanin Geldigi Metre(m)	228		
Hata Eni(mm)	1.81		
Hata Boyu(mm)	3.08		
Hata Alani(mm2)	5.57		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		


Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	6.64	
Hatanin Geldigi Metre(m)	5781	
Hata Eni(mm)	2.64	
Hata Boyu(mm)	1.42	
Hata Alani(mm2)	3.75	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	15.42
Hatanin Geldigi Metre(m)	2005
Hata Eni(mm)	0.83
Hata Boyu(mm)	2.25
Hata Alani(mm2)	1.87
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023




Dok No:4027	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	3.47		
Hatanin Geldigi Metre(m)	1551		
Hata Eni(mm)	1.56		
Hata Boyu(mm)	0.49		
Hata Alani(mm2)	0.76		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.9
Hatanin Geldigi Metre(m)	786
Hata Eni(mm)	3.47
Hata Boyu(mm)	12.45
Hata Alani(mm2)	43.2
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:4027	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	1.07	
Hatanin Geldigi Metre(m)	472	
Hata Eni(mm)	1.12	
Hata Boyu(mm)	0.73	
Hata Alani(mm2)	0.82	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	






Dok No:1823	Kalite No:SATEN(IS	S	
Hatanin Yatay Konumu(cm)	8.77		
Hatanin Geldigi Metre(m)	5574		
Hata Eni(mm)	1.17		
Hata Boyu(mm)	0.54		
Hata Alani(mm2)	0.63		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS	3	
Hatanin Yatay Konumu(cm)	17.25		
Hatanin Geldigi Metre(m)	5167		
Hata Eni(mm)	2.25		
Hata Boyu(mm)	0.93		
Hata Alani(mm2)	2.09		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.9
Hatanin Geldigi Metre(m)	926
Hata Eni(mm)	3.37
Hata Boyu(mm)	12.4
Hata Alani(mm2)	41.79
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:4027	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	1.09		
Hatanin Geldigi Metre(m)	2719		
Hata Eni(mm)	1.07		
Hata Boyu(mm)	1.07		
Hata Alani(mm2)	1.14		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:745	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	7.56	
Hatanin Geldigi Metre(m)	1841	
Hata Eni(mm)	1.17	
Hata Boyu(mm)	1.12	
Hata Alani(mm2)	1.31	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1386	Kalite No:RANFORCI	E
Hatanin Yatay Konumu(cm)	6.15	
Hatanin Geldigi Metre(m)	2833	
Hata Eni(mm)	0.88	
Hata Boyu(mm)	0.73	
Hata Alani(mm2)	0.64	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:745	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	3.36	
Hatanin Geldigi Metre(m)	351	
Hata Eni(mm)	1.37	
Hata Boyu(mm)	0.59	
Hata Alani(mm2)	0.81	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	9.59	
Hatanin Geldigi Metre(m)	5935	
Hata Eni(mm)	0.63	
Hata Boyu(mm)	0.68	
Hata Alani(mm2)	0.43	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	31.3.2023	


Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	9.65	
Hatanin Geldigi Metre(m)	5936	
Hata Eni(mm)	0.83	
Hata Boyu(mm)	0.73	
Hata Alani(mm2)	0.61	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:4027	Kalite No:RANFORO	E
Hatanin Yatay Konumu(cm)	11.22	
Hatanin Geldigi Metre(m)	166	
Hata Eni(mm)	1.95	
Hata Boyu(mm)	1.81	
Hata Alani(mm2)	3.53	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:745	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	3.04	
Hatanin Geldigi Metre(m)	1515	
Hata Eni(mm)	1.03	
Hata Boyu(mm)	1.17	
Hata Alani(mm2)	1.21	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1868	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	6.17	
Hatanin Geldigi Metre(m)	31	
Hata Eni(mm)	1.32	
Hata Boyu(mm)	2.05	
Hata Alani(mm2)	2.71	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	_

Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.91
Hatanin Geldigi Metre(m)	1952
Hata Eni(mm)	3.17
Hata Boyu(mm)	12.21
Hata Alani(mm2)	38.71
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	2.09
Hatanin Geldigi Metre(m)	1411
Hata Eni(mm)	1.42
Hata Boyu(mm)	5.57
Hata Alani(mm2)	7.91
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023




Dok No:1386	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	13.07	
Hatanin Geldigi Metre(m)	195	
Hata Eni(mm)	2.15	
Hata Boyu(mm)	1.37	
Hata Alani(mm2)	2.95	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1386	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	4.35		
Hatanin Geldigi Metre(m)	715		
Hata Eni(mm)	1.07		
Hata Boyu(mm)	1.76		
Hata Alani(mm2)	1.88		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1600	Kalite No:RANFORC	Έ	
Hatanin Yatay Konumu(cm)	16.67		
Hatanin Geldigi Metre(m)	1703		
Hata Eni(mm)	1.42		
Hata Boyu(mm)	0.68		
Hata Alani(mm2)	0.97		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1482	Kalite No:WF
Hatanin Yatay Konumu(cm)	11.91
Hatanin Geldigi Metre(m)	289
Hata Eni(mm)	1.46
Hata Boyu(mm)	1.32
Hata Alani(mm2)	1.93
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023



Dok No:1386	Kalite No:RANFORCE	Ξ
Hatanin Yatay Konumu(cm)	17.25	
Hatanin Geldigi Metre(m)	1406	
Hata Eni(mm)	1.95	
Hata Boyu(mm)	1.12	
Hata Alani(mm2)	2.18	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1386	Kalite No:RANFORCI	E
Hatanin Yatay Konumu(cm)	19.79	
Hatanin Geldigi Metre(m)	1081	
Hata Eni(mm)	1.17	
Hata Boyu(mm)	2.2	
Hata Alani(mm2)	2.57	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1386	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	16.73		
Hatanin Geldigi Metre(m)	1355		
Hata Eni(mm)	1.56		
Hata Boyu(mm)	0.78		
Hata Alani(mm2)	1.22		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS		
Hatanin Yatay Konumu(cm)	9.64		
Hatanin Geldigi Metre(m)	5509		
Hata Eni(mm)	1.37	_	
Hata Boyu(mm)	2.44		
Hata Alani(mm2)	3.34		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1600	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	2.92	
Hatanin Geldigi Metre(m)	3046	
Hata Eni(mm)	2.73	
Hata Boyu(mm)	5.18	
Hata Alani(mm2)	14.14	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:4027	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	6.69		
Hatanin Geldigi Metre(m)	2684		
Hata Eni(mm)	1.32		
Hata Boyu(mm)	1.37		
Hata Alani(mm2)	1.81		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:240	Kalite No:GB
Hatanin Yatay Konumu(cm)	2.79
Hatanin Geldigi Metre(m)	2446
Hata Eni(mm)	1.61
Hata Boyu(mm)	2.34
Hata Alani(mm2)	3.77
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1823	Kalite No:SATEN(IS	3	
Hatanin Yatay Konumu(cm)	17.85		
Hatanin Geldigi Metre(m)	5736		
Hata Eni(mm)	1.37		
Hata Boyu(mm)	2.98		
Hata Alani(mm2)	4.08		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:745	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	0.07	
Hatanin Geldigi Metre(m)	908	
Hata Eni(mm)	0.98	
Hata Boyu(mm)	1.03	
Hata Alani(mm2)	1.01	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:745	Kalite No:RANFORO	Œ	
Hatanin Yatay Konumu(cm)	2.05		
Hatanin Geldigi Metre(m)	3549		
Hata Eni(mm)	0.98		
Hata Boyu(mm)	0.98		
Hata Alani(mm2)	0.96		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		


Dok No:1386	Kalite No:RANFORO	Œ	
Hatanin Yatay Konumu(cm)	4.41		
Hatanin Geldigi Metre(m)	479		
Hata Eni(mm)	1.46		
Hata Boyu(mm)	2.83		
Hata Alani(mm2)	4.13		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1600	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	10.37		
Hatanin Geldigi Metre(m)	2598		
Hata Eni(mm)	1.07		
Hata Boyu(mm)	0.49		
Hata Alani(mm2)	0.52		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		


Dok No:745	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	12.37	
Hatanin Geldigi Metre(m)	3323	
Hata Eni(mm)	1.42	
Hata Boyu(mm)	1.32	
Hata Alani(mm2)	1.87	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:4027	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	2.92		
Hatanin Geldigi Metre(m)	2212		
Hata Eni(mm)	1.22		
Hata Boyu(mm)	1.07		
Hata Alani(mm2)	1.31		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.91
Hatanin Geldigi Metre(m)	924
Hata Eni(mm)	3.32
Hata Boyu(mm)	12.65
Hata Alani(mm2)	42
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:240	Kalite No:GB
Hatanin Yatay Konumu(cm)	15.66
Hatanin Geldigi Metre(m)	617
Hata Eni(mm)	1.27
Hata Boyu(mm)	3.08
Hata Alani(mm2)	3.91
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:1386	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	17.67	
Hatanin Geldigi Metre(m)	2086	
Hata Eni(mm)	3.47	
Hata Boyu(mm)	0.54	
Hata Alani(mm2)	1.87	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	





Dok No:1823	Kalite No:SATEN(IS	S	
Hatanin Yatay Konumu(cm)	7.31		
Hatanin Geldigi Metre(m)	1270		
Hata Eni(mm)	0.88	_	
Hata Boyu(mm)	3.08		
Hata Alani(mm2)	2.71		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:4027	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	16.77		
Hatanin Geldigi Metre(m)	339		
Hata Eni(mm)	1.71		
Hata Boyu(mm)	1.12		
Hata Alani(mm2)	1.92		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		


Dok No:4027	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	9.62	
Hatanin Geldigi Metre(m)	385	
Hata Eni(mm)	1.22	
Hata Boyu(mm)	1.86	
Hata Alani(mm2)	2.27	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	12.91	
Hatanin Geldigi Metre(m)	4936	
Hata Eni(mm)	0.73	
Hata Boyu(mm)	0.78	
Hata Alani(mm2)	0.57	
Hata Sinifi	delik	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	5.88
Hatanin Geldigi Metre(m)	1711
Hata Eni(mm)	0.93
Hata Boyu(mm)	2.39
Hata Alani(mm2)	2.22
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023



Dok No:240	Kalite No:GB
Hatanin Yatay Konumu(cm)	6.05
Hatanin Geldigi Metre(m)	3288
Hata Eni(mm)	1.37
Hata Boyu(mm)	0.78
Hata Alani(mm2)	1.07
Hata Sinifi	delik
Hatanin Geldigi Tarih	3.4.2023








Dok No:1823	Kalite No:SATEN(IS	S	
Hatanin Yatay Konumu(cm)	6.79		
Hatanin Geldigi Metre(m)	5611		
Hata Eni(mm)	1.27		
Hata Boyu(mm)	0.49		
Hata Alani(mm2)	0.62		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	9.09	
Hatanin Geldigi Metre(m)	5700	
Hata Eni(mm)	1.07	
Hata Boyu(mm)	2.73	
Hata Alani(mm2)	2.92	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:176	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.89
Hatanin Geldigi Metre(m)	921
Hata Eni(mm)	3.32
Hata Boyu(mm)	12.4
Hata Alani(mm2)	41.17
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023




Dok No:1823	Kalite No:SATEN(I	S	
Hatanin Yatay Konumu(cm)	11.14		
Hatanin Geldigi Metre(m)	2442		
Hata Eni(mm)	2.83		
Hata Boyu(mm)	6.4		
Hata Alani(mm2)	18.11		
Hata Sinifi	delik		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1386	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	10.37		
Hatanin Geldigi Metre(m)	1958		
Hata Eni(mm)	1.12		
Hata Boyu(mm)	2.78		
Hata Alani(mm2)	3.11		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1386	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	0.24		
Hatanin Geldigi Metre(m)	748		
Hata Eni(mm)	2		
Hata Boyu(mm)	0.88		
Hata Alani(mm2)	1.76		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		


Dok No:1386	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	18.6	
Hatanin Geldigi Metre(m)	1325	1
Hata Eni(mm)	2.44	
Hata Boyu(mm)	0.93	
Hata Alani(mm2)	2.27	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	_



Dok No:745	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	16.77		
Hatanin Geldigi Metre(m)	2729		
Hata Eni(mm)	1.42		
Hata Boyu(mm)	2.29		
Hata Alani(mm2)	3.25		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(IS		
Hatanin Yatay Konumu(cm)	5.97		
Hatanin Geldigi Metre(m)	492		
Hata Eni(mm)	4.39	<u> </u>	
Hata Boyu(mm)	0.88		
Hata Alani(mm2)	3.86		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:119	Kalite No:GB
Hatanin Yatay Konumu(cm)	4.9
Hatanin Geldigi Metre(m)	1956
Hata Eni(mm)	3.32
Hata Boyu(mm)	12.45
Hata Alani(mm2)	41.33
Hata Sinifi	leke
Hatanin Geldigi Tarih	3.4.2023




Dok No:1600	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	14.63	
Hatanin Geldigi Metre(m)	2482	
Hata Eni(mm)	1.12	
Hata Boyu(mm)	0.83	
Hata Alani(mm2)	0.93	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:4027	Kalite No:RANFORC	E	
Hatanin Yatay Konumu(cm)	16.67		
Hatanin Geldigi Metre(m)	1576		
Hata Eni(mm)	2.54		
Hata Boyu(mm)	1.37		
Hata Alani(mm2)	3.48		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:4027	Kalite No:RANFORO	CE
Hatanin Yatay Konumu(cm)	0.81	
Hatanin Geldigi Metre(m)	141	
Hata Eni(mm)	1.71	
Hata Boyu(mm)	2.83	
Hata Alani(mm2)	4.84	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:1386	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	7.18	
Hatanin Geldigi Metre(m)	1002	
Hata Eni(mm)	5.71	
Hata Boyu(mm)	1.46	
Hata Alani(mm2)	8.34	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	






Dok No:1823	Kalite No:SATEN(IS	
Hatanin Yatay Konumu(cm)	3.84	
Hatanin Geldigi Metre(m)	5919	
Hata Eni(mm)	1.66	
Hata Boyu(mm)	3.12	
Hata Alani(mm2)	5.18	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:745	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	1.85		
Hatanin Geldigi Metre(m)	2002		
Hata Eni(mm)	0.88		
Hata Boyu(mm)	1.22		
Hata Alani(mm2)	1.07		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:4027	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	4.89	
Hatanin Geldigi Metre(m)	1060	
Hata Eni(mm)	1.22	_
Hata Boyu(mm)	0.83	
Hata Alani(mm2)	1.01	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	_





Dok No:1823	Kalite No:SATEN(IS	S	
Hatanin Yatay Konumu(cm)	9.92		
Hatanin Geldigi Metre(m)	5407		
Hata Eni(mm)	3.08		
Hata Boyu(mm)	3.71		
Hata Alani(mm2)	11.43		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1823	Kalite No:SATEN(I	S	
Hatanin Yatay Konumu(cm)	11.07		
Hatanin Geldigi Metre(m)	5171		
Hata Eni(mm)	1.32		
Hata Boyu(mm)	0.68		
Hata Alani(mm2)	0.9		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:1386	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	16.68	
Hatanin Geldigi Metre(m)	1301	
Hata Eni(mm)	2.54	
Hata Boyu(mm)	1.07	
Hata Alani(mm2)	2.72	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	

Dok No:745	Kalite No:RANFORO	CE	
Hatanin Yatay Konumu(cm)	5.21		
Hatanin Geldigi Metre(m)	2965		
Hata Eni(mm)	2.39		
Hata Boyu(mm)	2		
Hata Alani(mm2)	4.78		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:745	Kalite No:RANFORO	E	
Hatanin Yatay Konumu(cm)	18.52		
Hatanin Geldigi Metre(m)	3524		
Hata Eni(mm)	1.42		
Hata Boyu(mm)	1.9		
Hata Alani(mm2)	2.7		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023	_	

Dok No:1386	Kalite No:RANFOR	CE	
Hatanin Yatay Konumu(cm)	4.5		
Hatanin Geldigi Metre(m)	725		
Hata Eni(mm)	1.03		
Hata Boyu(mm)	0.83		
Hata Alani(mm2)	0.85		
Hata Sinifi	leke		
Hatanin Geldigi Tarih	31.3.2023		

Dok No:745	Kalite No:RANFORCE	
Hatanin Yatay Konumu(cm)	18.65	
Hatanin Geldigi Metre(m)	2449	
Hata Eni(mm)	3.12	
Hata Boyu(mm)	1.27	
Hata Alani(mm2)	3.96	
Hata Sinifi	leke	
Hatanin Geldigi Tarih	31.3.2023	