
Merserize Makinesinde Tespit Edilen Kumas Hatalari

Tarih: 14.9.2023

Hafta	delik	leke
14.9.2023-14.9.2023	164	62



14.9.2023-14.9.2023'leri arasinda hata tespit turleri;

14.9.2023-14.9.2023'leri arasinda tespit edilen Delik ve Leke sayisi: 164-62 (Adet)


Merserize Makinesinde Tespit Edilen Kumas Hatalari


Tarih: 14.9.2023

Tarih	Dok No	Kalite No	Delik Sayisi	Leke Sayisi
14.9.2023	1	SATEN(IS	0	0

Merserize Makinesinde Tespit Edilen Kumas







menderes	Merserize Makinesinde Tespit Edilen Kumas Hatalari	

Merserize Makinesinde Tespit Edilen Kumas Hatalari

Dok No:1	Kalite No:SATEN(IS
Hatanin Yatay Konumu(cm)	101
Hatanin Geldigi Metre(m)	0
Hata Eni(mm)	168.65
Hata Boyu(mm)	45.12
Hata Alani(mm2)	7609.49
Hata Sinifi	iplik
Hatanin Geldigi Tarih	14.9.2023

