



a Overburden along the surveyed length (orange bands: skylights)



b Distribution (median 6.0 m)



c Thickness against span, with the clamped-strip stability limit

