# FASAL SURAKSHA

**AI Crop Health Screening Card**

**Issued:** 29 Oct 2026, 19:08
**Card ID:** FSC-281115
**Type:** AI screening - not a lab diagnosis


| Crop: | Mango | Likely disease: | Bacterial canker | Leaf severity: | 3.7% (Mild) | AI confidence: | 92.9% |
|---|---|---|---|---|---|---|---|

**Caution:** Low confidence (1.9%). Retake the photo or consult an expert.

## Leaf photo



## Model attention (Grad-CAM)



## Yield estimate

**Reference yield (healthy):** 15.06 t/acre
**Model estimate:** 14.96 t/acre
**Estimated shortfall:** 0.6%

*Statistical estimate from the inputs entered; it is not a measured loss and varies widely with weather, variety and management.*

*Heatmap shows where the AI looked. It helps a human check the result; it does not prove the diagnosis is correct.*

## Suggested Treatment (advisory - confirm locally)

| Type | Product | Dose | Frequency / safety |
|---|---|---|---|
| Organic / Bio | **Pseudomonas fluorescens (5 g/L) + Neem Oil 10,000 PPM** | - 4.0 mL (or g) / Liter water<br>- 60.0 mL (or g) for 15.0L tank | Every 8 days.<br>Spray on leaves showing water-soaked angular lesions. Disinfect pruning shears to prevent mechanical transmission. |
| Chemical | **Streptocycline (1 g/10 L) + Copper Oxychloride 50% WP (3.0 g/L)** | - 2.5 mL (or g) / Liter water<br>- 37.5 mL (or g) for 15.0L tank | Every 12 days.<br>Apply bactericide tank mix at first sign of angular black lesions with yellow halos on foliage and twigs. |

*Use only pesticides registered for this crop in India, follow the product label, and confirm the plan with a local agronomist or Krishi Vigyan Kendra (KVK).*

## Evidence Record (for crop-insurance reporting)

| | | | |
|---|---|---|---|
| **Record ID:**<br>EVD-20261029-1984B0 | **Farmer / insurance ID:**<br>KCC-UP-98214 | **Location:**<br>26.84670, 80.94620 | **Evidence status:**<br>**INCOMPLETE** |
| **Follow-up priority:**<br>LOW - monitor and treat early | **Still needed:**<br>Survey date; At least 3 photos (leaf close-up, plant, whole field) | **What to do:**<br>Record dated, geotagged photos of the affected leaves, plants and whole field before and after treatment. Keep input purchase bills. Report to the insurer / bank / Agriculture Office through the official channel. This app's severity number is an estimate from one leaf image and is not a loss assessment. | **Insurance:**<br>Crop insurance is settled under the scheme's own rules, not by this app. Contact your insurance company, bank branch or local Agriculture Office, and see pmfby.gov.in for the current guidelines and claim-intimation timelines. For localized calamities such as hailstorm, landslide, inundation, cloud burst or natural fire, report quickly (the scheme sets short intimation windows). |

*Generated by the FASAL SURAKSHA AI tool. Results are screening estimates from photos and entered data. This card does not decide any insurance claim or payout; those are determined by the insurer and the government under the scheme rules. For confirmation, contact your nearest Krishi Vigyan Kendra (KVK) or Agriculture Office.*