



Missing eye protection


AI-assisted photographic hazard assessment · SSO Ranchi · Conveyor C3

RISK LEVEL
HIGH

INCIDENT DETAILS

PLANT / UNIT SSO Ranchi	DEPARTMENT Safety	LOCATION Conveyor C3	DATE & TIME 03 Oct 2026, 11:48
REPORTED BY Audit	PERSONNEL NO. 1	OBSERVATION TYPE N/A	STATUS OPEN
REPORT TYPE AI Image Scan	WSA CATEGORY -	REFERENCE NO. AUDIT_TE	PEOPLE INVOLVED 0

EVIDENCE PHOTOGRAPH & INCIDENT SUMMARY




OVERALL RISK
HIGH
AI confidence 88%

12 / 25
L3 × S4 (L est.)

SUMMARY
Worker near running conveyor without eye protection; a small exposed item on the left.

CLOSE-UP OF MARKED AREAS



Exposed sharp item

2

HAZARDS

1

MARKED ON PHOTO

None

LINE OF FIRE

0

TO VERIFY

LINE OF FIRE: none identified in this photo

2 hazard(s) - 1 marked on photo, 1 not locatable in this view

HAZARDS IDENTIFIED - 2 TOTAL

#	HAZARD	SEVERITY	DESCRIPTION	REGULATION	CORRECTIVE ACTION
1	Missing eye protection <i>not marked on photo</i>	HIGH	Worker beside the conveyor without goggles.	FA 1948 S35	Issue goggles.
2	Exposed sharp item	MEDIUM	Small exposed item on the bench.	IS 14489	Remove.

REPORTED BY Audit P.No. 1 Signature & date	REVIEWED BY Safety Officer / HOD Name: Signature & date	APPROVED BY Plant Head / GM (Safety) Name: Signature & date
--	---	---

Generated by SAIL Safety Lens. AI observations are advisory and subject to verification by the Safety Department before any finding is recorded.