



Missing eye protection


AI-assisted photographic hazard assessment · Conveyor C3

RISK LEVEL
HIGH

INCIDENT DETAILS

PLANT / UNIT SSO Ranchi	DEPARTMENT Safety	LOCATION Conveyor C3	DATE & TIME 03 Oct 2026, 11:48
REPORTED BY Audit	PERSONNEL NO. 1	OBSERVATION TYPE N/A	STATUS OPEN
REPORT TYPE AI Image Scan	WSA CATEGORY -	REFERENCE NO. AUDIT_TE	PEOPLE INVOLVED 0

EVIDENCE PHOTOGRAPH & INCIDENT SUMMARY



12 hazard(s) - 12 marked on photo

OVERALL RISK

HIGH

AI confidence 88%


12 / 25

L3 x S4 (L est.)

SUMMARY

Worker near running conveyor without eye protection; a small exposed item on the left.

CLOSE-UP OF MARKED AREAS




Finding 1: Missing chin strap



Finding 2: Oil spill on floor



Finding 3: Unguarded pulley



Finding 4: Hose across walkway

12
HAZARDS12
MARKED ON PHOTO0
TO VERIFY

HAZARDS IDENTIFIED - 12 TOTAL

#	HAZARD	SEVERITY	DESCRIPTION	REGULATION	CORRECTIVE ACTION
1	Finding 1: Missing chin strap	HIGH	Detailed description of finding 1, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S20	Corrective action 1: isolate, barricade and brief the crew before restart.
2	Finding 2: Oil spill on floor	MEDIUM	Detailed description of finding 2, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S21	Corrective action 2: isolate, barricade and brief the crew before restart.
3	Finding 3: Unguarded pulley	LOW	Detailed description of finding 3, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S22	Corrective action 3: isolate, barricade and brief the crew before restart.
4	Finding 4: Hose across walkway	CRITICAL	Detailed description of finding 4, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S23	Corrective action 4: isolate, barricade and brief the crew before restart.



Missing eye protection

AI-assisted photographic hazard assessment · Conveyor C3

RISK LEVEL
HIGH

#	HAZARD	SEVERITY	DESCRIPTION	REGULATION	CORRECTIVE ACTION
5	Finding 5: Missing chin strap	HIGH	Detailed description of finding 5, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S24	Corrective action 5: isolate, barricade and brief the crew before restart.
6	Finding 6: Oil spill on floor	MEDIUM	Detailed description of finding 6, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S25	Corrective action 6: isolate, barricade and brief the crew before restart.
7	Finding 7: Unguarded pulley	LOW	Detailed description of finding 7, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S26	Corrective action 7: isolate, barricade and brief the crew before restart.
8	Finding 8: Hose across walkway	CRITICAL	Detailed description of finding 8, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S27	Corrective action 8: isolate, barricade and brief the crew before restart.
9	Finding 9: Missing chin strap	HIGH	Detailed description of finding 9, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S28	Corrective action 9: isolate, barricade and brief the crew before restart.
10	Finding 10: Oil spill on floor	MEDIUM	Detailed description of finding 10, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S29	Corrective action 10: isolate, barricade and brief the crew before restart.
11	Finding 11: Unguarded pulley	LOW	Detailed description of finding 11, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S30	Corrective action 11: isolate, barricade and brief the crew before restart.
12	Finding 12: Hose across walkway	CRITICAL	Detailed description of finding 12, long enough to wrap onto a second line in the hazards table so the table grows past one page.	FA 1948 S31	Corrective action 12: isolate, barricade and brief the crew before restart.

REPORTED BY

Audit

P.No. 1

Signature & date

REVIEWED BY

Safety Officer / HOD

Name:

Signature & date

APPROVED BY

Plant Head / GM (Safety)

Name:

Signature & date

Generated by SAIL Safety Lens. AI observations are advisory and subject to verification by the Safety Department before any finding is recorded.