



Missing eye protection


AI-assisted photographic hazard assessment · Conveyor C3

RISK LEVEL
HIGH

INCIDENT DETAILS

PLANT / UNIT SSO Ranchi	DEPARTMENT Safety	LOCATION Conveyor C3	DATE & TIME 03 Oct 2026, 11:48
REPORTED BY Audit	PERSONNEL NO. 1	OBSERVATION TYPE N/A	STATUS OPEN
REPORT TYPE AI Image Scan	WSA CATEGORY -	REFERENCE NO. AUDIT_TE	PEOPLE INVOLVED 0

EVIDENCE PHOTOGRAPH & INCIDENT SUMMARY



2 hazard(s) - 1 marked on photo, 1 not locatable in this view

OVERALL RISK

HIGH

AI confidence 88%

12 / 25

L3 × S4 (L est.)

SUMMARY

Worker near running conveyor without eye protection; a small exposed item on the left.

CLOSE-UP OF MARKED AREAS



Exposed sharp item

2
HAZARDS**1**
MARKED ON PHOTO**0**
TO VERIFY

HAZARDS IDENTIFIED - 2 TOTAL

#	HAZARD	SEVERITY	DESCRIPTION	REGULATION	CORRECTIVE ACTION
1	Missing eye protection <i>not marked on photo</i>	HIGH	Worker beside the conveyor without goggles.	FA 1948 S35	Issue goggles.
2	Exposed sharp item	MEDIUM	Small exposed item on the bench.	IS 14489	Remove.

REPORTED BY

Audit

P.No. 1

Signature & date

REVIEWED BY

Safety Officer / HOD

Name:

Signature & date

APPROVED BY

Plant Head / GM (Safety)

Name:

Signature & date

Generated by SAIL Safety Lens. AI observations are advisory and subject to verification by the Safety Department before any finding is recorded.