

Drone Inspection

Wind turbine blade & solar panel defect analysis

Generated September 6, 2026 at 7:15 PM · 4 of 4 images analysed · models: turbine turbine.onnx

Minor wear detected

0

Severe

0

Moderate

4

Minor

0


Clear

0

Rejected

0

Errors




blade_01.jpg

Minor wear · score 0.91

Wind turbine blade · 2 detections

- surface_peeling — 71.6%
- surface_peeling — 19.1%

No 'healthy' class by design: an image with no detections is the healthy result.



blade_02.jpg

Minor wear · score 0.58

Wind turbine blade · 2 detections

- surface_peeling — 44.4%
- surface_peeling — 13.4%

No 'healthy' class by design: an image with no detections is the healthy result.




blade_03.jpg

Minor wear · score 0.94

Wind turbine blade · 1 detection

■ surface_peeling — 94.0%

No 'healthy' class by design: an image with no detections is the healthy result.



blade_04.jpg

Minor wear · score 1.17

Wind turbine blade · 2 detections

■ crack — 20.7%

■ crack — 18.4%

No 'healthy' class by design: an image with no detections is the healthy result.

Inference runs locally with ONNX Runtime Web. Images are processed on your device and are never transmitted. Results are a screening aid, not a certified structural assessment — confirm findings before acting on them.