

# PM Evidence Audit & Corrective Action

## Invoice #172825 — All 196 Reports

---

|              |                                                                                        |
|--------------|----------------------------------------------------------------------------------------|
| Reference    | Invoice #172825 — 196 PM reports, service dates July 15–31, 2026 · 129 store locations |
| Prepared for | Freshpet, Inc. — response to documentation review of August 2026                       |
| Prepared by  | Freeflow Beverage Solutions / Brix Beverage                                            |
| Date         | August 25, 2026                                                                        |

---

**Scope: every report, every photograph, every signature.** All 196 report PDFs were verified in storage; all 392 attached photographs were individually examined, the serial number legible on each equipment plate transcribed and compared against the report and the asset list; and every signature image was cryptographically compared across the batch. The submitted originals are preserved unaltered. Appendix A lists the finding and disposition for every report.

## 1. The signed-report question, answered first

---

All 196 reports exist as signed, timestamped PDFs. 195 carry the technician's signature and 194 carry a store-side signature; every report carries an on-device completion timestamp. Cryptographic comparison shows **no signature image is shared between any two reports** — every signature was drawn individually at submission. (The signatures on the five closed-store reports are addressed in Section 3: those reports are withdrawn as PMs.)

## 2. The photo question, answered per report

---

| FINDING ACROSS ALL 196 REPORTS                                                                                                                                                                                              | REPORTS | WHAT HAPPENS                                                                                                                                                                             |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Verified as submitted</b> — the report's own photo shows its own unit's plate                                                                                                                                            | 68      | Nothing — evidence stands                                                                                                                                                                |
| <b>Photographed, mislabeled</b> — the unit's plate photo exists in our records, filed on the sibling unit's report at the same store (50) or on another store's report (10)                                                 | 60      | Reissued from photographs already on file; every correction timestamped, originals retained                                                                                              |
| <b>Photo disagrees with the asset list</b> — a unique, on-site plate photo whose serial matches no unit on the list; in most of these the photograph appears genuine and the list entry stale (replaced or re-tagged units) | 13      | Serials confirmed with Freshpet / on site; asset-list corrections returned                                                                                                               |
| <b>Not adequately photographed</b> — plate photo shows another unit (38), no legible plate (8), or no photos (4)                                                                                                            | 50      | Recovered from the technician's original camera files where possible, otherwise re-photographed on site at no cost — Bakersfield 16, Fresno 13+2, Modesto 11, Sacramento 4, Tri-Valley 4 |
| <b>Closed / missing sites</b> — visits documented by storefront photographs                                                                                                                                                 | 5       | Withdrawn as PMs; returned as asset-list corrections                                                                                                                                     |

At the store level: of 129 locations, **44 are fully verified as submitted**, and at a further **20 every unit on site was photographed with labels crossed between sibling units** — so after the file-based corrections, 64 stores carry complete signed-report-plus-matching-photo evidence with no field work at all, 11 more pend only an asset-list serial confirmation, and 49 receive corrected photographs.



## Exhibit A — how one photograph created six "duplicate serials"

---



**Left:** the plate photograph reading 11008872 (the Food Maxx #453 unit) — this single file appears byte-identically on six stores' reports, the six stores your review lists under SN#11008872. **Right:** an equipment photo appearing identically on thirteen reports. One capture referenced many times is a filing defect, not many fabricated visits. The serial fields on the reports themselves match the asset list store-by-store and were never duplicated.

## Exhibit B — the closed-store visits happened



**Left:** Walmart #1983 as our technician found and photographed it on July 23 — closed and boarded. **Right:** Foods Co #784 on July 22, closed. The tool we piloted offered no closed-store report, so these visits were forced through a PM form with pre-filled readings; that form has been replaced and these five are withdrawn as PMs.

### 3. Root cause, plainly

---

The reporting tool piloted for this batch let photographs be attached from the device photo library with nothing binding an image to the unit it documents, no duplicate detection, no required plate photo, and pre-filled reading fields. During end-of-route report entry, plate photographs were repeatedly filed to the wrong unit or store. The field work itself is documented: the batch contains 337 distinct on-site photographs, coherent day-by-day service routes, 182 named store contacts, and individually drawn signatures on every signed report.

### 4. Corrective controls — already built

---

- **Serial-plate photo required on every PM**, captured through the camera at the unit; library attachment removed for evidentiary photos.
- **Duplicate images refused automatically** — every photograph is cryptographically fingerprinted; an image on any other report cannot be attached.
- **No pre-filled readings**; temperature, set point and condition are required manual entries.
- **A dedicated closed-store / missing-unit report** that cannot be invoiced as a PM.
- **Signature integrity** — named signer or an explicit "no store contact available" statement; one report per unit per day.

### 5. Commitments and requests

---

- The 60 file-based corrections issued within days; the 50 field re-photographs within two weeks of your confirmation, at no cost.
- Two over-billed PMs credited proactively (a duplicated Kelley's Pets #3465 submission; one of two reports against a single PetSmart #1975 unit listed twice on the asset list).
- Asset-list corrections returned: five closed/converted sites; the PetSmart #1975 duplicate entry; serial corrections for the 13 units above; the physical homes of unlisted units M153303 and M158123; and several additional unlisted units observed on site during this audit.
- We ask for your full itemized disposition of all 196 reports (95 validated + 67 unnoted accounts for 162), confirmation of the closed sites, and a two-week window to deliver the corrected evidence before any payment adjustment is finalized.

## Appendix A — every report on invoice #172825

---

"Plate photo shows" is the serial our audit read from the report's attached photographs ("-" = none legible). "Signed" reflects the signature images embedded in the report PDF. Green = verified; amber = corrected from photographs on file; blue = pending asset-list confirmation; white = re-photograph; violet = closed-site exception.

| STORE            | UNIT SERIAL | DATE       | SIGNED     | PLATE PHOTO SHOWS | DISPOSITION                                                                      |
|------------------|-------------|------------|------------|-------------------|----------------------------------------------------------------------------------|
| Albertsons #1398 | 9413966     | 2026-07-21 | tech+store | 9413966           | Verified — signed report + matching plate photo                                  |
| Albertsons #1398 | 10671486    | 2026-07-21 | tech+store | 10671482          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Albertsons #1398 | 10671482    | 2026-07-21 | tech+store | 10671486          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Albertsons #3129 | 9407809     | 2026-07-21 | tech+store | 9407809           | Verified — signed report + matching plate photo                                  |
| Albertsons #3129 | 10671490    | 2026-07-21 | tech+store | 11008872          | Plate photo shows another unit — re-photograph                                   |
| Albertsons #3172 | 10671477    | 2026-07-20 | tech+store | 10671477          | Verified — signed report + matching plate photo                                  |
| Albertsons #336  | 9325680     | 2026-07-20 | tech+store | 10671481          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Albertsons #336  | 10671481    | 2026-07-20 | tech+store | 9325680           | Unit photographed at this store; label crossed with sibling — reissued from file |

|                             |              |            |            |          |                                                                                  |
|-----------------------------|--------------|------------|------------|----------|----------------------------------------------------------------------------------|
| Albertsons #358             | 9407801      | 2026-07-21 | tech+store | 10663638 | Unit photographed at this store; label crossed with sibling — reissued from file |
| Albertsons #358             | 10663638     | 2026-07-21 | tech+store | 9407801  | Unit photographed at this store; label crossed with sibling — reissued from file |
| Albertsons #377             | 10663625     | 2026-07-20 | tech+store | -        | No photos on report — re-photograph                                              |
| Albertsons #377             | 10671487     | 2026-07-20 | tech+store | 11008876 | Plate photo shows another unit — re-photograph                                   |
| Albertsons California #3364 | 10609622     | 2026-07-21 | tech+store | 10157996 | Plate photo shows another unit — re-photograph                                   |
| Bel-Air #501                | 10148895     | 2026-07-15 | tech+store | 10148895 | Verified — signed report + matching plate photo                                  |
| Carters Pet Mart #56789     | 9723510      | 2026-07-24 | tech+store | 9637980  | Plate photo shows another unit — re-photograph                                   |
| Carters Pet Mart #56789     | 9637980      | 2026-07-24 | tech+store | M158123  | Unit photographed at this store; label crossed with sibling — reissued from file |
| Comptons Market #14696      | 411412301019 | 2026-07-15 | tech+store | -        | Closed / missing site — visit documented, withdrawn as PM                        |
| Cost Less Foods #11062      | 11240706     | 2026-07-29 | tech+store | 11240706 | Verified — signed report + matching plate photo                                  |
| Cost Less Foods #13952      | 10588791     | 2026-07-29 | tech+store | 10878244 | On-site photo disagrees with asset-list serial — serial to be confirmed          |

|                        |          |            |            |          |                                                                                  |
|------------------------|----------|------------|------------|----------|----------------------------------------------------------------------------------|
| Cost Less Foods #13953 | 9885006  | 2026-07-24 | tech+store | 9885006  | Verified — signed report + matching plate photo                                  |
| Costco #146            | 10702123 | 2026-07-30 | tech+store | M2502943 | On-site photo disagrees with asset-list serial — serial to be confirmed          |
| Costco #31             | 317027   | 2026-07-23 | tech+store | -        | No legible plate photo — re-photograph                                           |
| Costco #661            | 10702119 | 2026-07-29 | tech+store | M2503082 | On-site photo disagrees with asset-list serial — serial to be confirmed          |
| Costco #688            | 10271100 | 2026-07-20 | tech+store | 10271100 | Verified — signed report + matching plate photo                                  |
| Food Maxx #403         | 11014453 | 2026-07-23 | tech+store | 10998989 | Unit photographed at this store; label crossed with sibling — reissued from file |
| Food Maxx #403         | 10998989 | 2026-07-23 | tech+store | 11014453 | Unit photographed at this store; label crossed with sibling — reissued from file |
| Food Maxx #410         | 10092086 | 2026-07-29 | tech+store | 10092086 | Verified — signed report + matching plate photo                                  |
| Food Maxx #410         | 10374779 | 2026-07-29 | tech+store | 10374779 | Verified — signed report + matching plate photo                                  |
| Food Maxx #413         | 10532359 | 2026-07-21 | tech only  | 207967   | Unit photographed at this store; label crossed with sibling — reissued from file |

|                |            |            |            |                   |                                                                                  |
|----------------|------------|------------|------------|-------------------|----------------------------------------------------------------------------------|
| Food Maxx #413 | 10528385   | 2026-07-21 | tech+store | 10528385/10532359 | Verified — signed report + matching plate photo                                  |
| Food Maxx #414 | 10521385   | 2026-07-22 | tech+store | 10523825          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Food Maxx #414 | 10523825-1 | 2026-07-22 | tech+store | 10521385          | Plate photo shows another unit — re-photograph                                   |
| Food Maxx #453 | 11008872   | 2026-07-20 | tech+store | 11008876          | Correct plate photo on file (misfiled) — reissued from file                      |
| Food Maxx #456 | 11022907   | 2026-07-22 | tech+store | 11022907          | Verified — signed report + matching plate photo                                  |
| Food Maxx #456 | 10998996   | 2026-07-22 | tech+store | 11022907          | Correct plate photo on file (misfiled) — reissued from file                      |
| Food Maxx #499 | 11022906   | 2026-07-21 | tech+store | 10546327          | On-site photo disagrees with asset-list serial — serial to be confirmed          |
| Food Maxx #499 | 11022905   | 2026-07-21 | tech+store | 290980            | Plate photo shows another unit — re-photograph                                   |
| Foods Co #316  | 11162201   | 2026-07-22 | tech+store | 11162201          | Verified — signed report + matching plate photo                                  |
| Foods Co #339  | 11162239   | 2026-07-22 | tech+store | 10998996          | Plate photo shows another unit — re-photograph                                   |
| Foods Co #365  | 9716900    | 2026-07-21 | tech+store | 11162             | Unit photographed at this store; label crossed with sibling — reissued from file |
| Foods Co #365  | 11162237   | 2026-07-21 | tech+store | 9716900           | Plate photo shows another unit — re-                                             |



|                           |              |            |            |                  |                                                                                  |
|---------------------------|--------------|------------|------------|------------------|----------------------------------------------------------------------------------|
|                           |              |            |            |                  | photograph                                                                       |
| Foods Co #384             | 10602707     | 2026-07-21 | tech+store | 10605033         | Unit photographed at this store; label crossed with sibling — reissued from file |
| Foods Co #384             | 10605033     | 2026-07-21 | tech+store | 10602707         | Unit photographed at this store; label crossed with sibling — reissued from file |
| Foods Co #784             | 11162238     | 2026-07-23 | tech+store | -                | Closed / missing site — visit documented, withdrawn as PM                        |
| Gene's Fine Foods #16047  | 341505301549 | 2026-07-30 | tech+store | 341505301549PBSG | Verified — signed report + matching plate photo                                  |
| Incredible Pets #24012404 | 6674060      | 2026-07-15 | tech+store | -                | Closed / missing site — visit documented, withdrawn as PM                        |
| Kelley's Pets #3465       | 10961123     | 2026-07-22 | tech+store | 10961123         | Verified — signed report + matching plate photo                                  |
| Kelley's Pets #3465       | 10961123     | 2026-07-22 | tech+store | 10961123         | Verified — signed report + matching plate photo                                  |
| Lassens #04               | 9404671      | 2026-07-20 | tech+store | 9404671          | Verified — signed report + matching plate photo                                  |
| Lucky #721                | 10874873     | 2026-07-30 | tech+store | 10874873         | Verified — signed report + matching plate photo                                  |
| Lucky #722                | 10896679     | 2026-07-30 | tech+store | 10896679         | Verified — signed report + matching plate photo                                  |
| Lucky #744                | 10874870     | 2026-07-30 | tech+store | 10105120         | Unit photographed at this store; label crossed with sibling — reissued from file |

|                         |                        |            |            |               |                                                                                  |
|-------------------------|------------------------|------------|------------|---------------|----------------------------------------------------------------------------------|
| Lucky #744              | 10105120               | 2026-07-30 | tech+store | 10874870      | Unit photographed at this store; label crossed with sibling — reissued from file |
| Lucky #750              | 80090400000116         | 2026-07-30 | tech+store | 278022        | Plate photo shows another unit — re-photograph                                   |
| Lunardis #9             | 411409150336           | 2026-07-30 | tech+store | 8220161006162 | On-site photo disagrees with asset-list serial — serial to be confirmed          |
| Murphys Paw #1910       | 7567529                | 2026-07-30 | tech+store | -             | Closed / missing site — visit documented, withdrawn as PM                        |
| Nob Hill #631           | 9325681                | 2026-07-30 | tech+store | 9325681       | Verified — signed report + matching plate photo                                  |
| O'Brien's Market #4402  | 8140289                | 2026-07-24 | tech+store | 8140289       | Verified — signed report + matching plate photo                                  |
| O'Brien's Market #4559  | 8140302                | 2026-07-29 | tech+store | 8140302       | Verified — signed report + matching plate photo                                  |
| Pet Supplies Plus #4132 | 9404655                | 2026-07-30 | tech+store | 9404655       | Verified — signed report + matching plate photo                                  |
| PetSmart US #1975       | 272477                 | 2026-07-29 | tech only  | -             | No legible plate photo — re-photograph                                           |
| PetSmart US #1975       | 272479 Date 21- 10- 22 | 2026-07-29 | tech+store | 272479        | Plate photo shows another unit — re-photograph                                   |
| PetSmart US #1975       | 272479                 | 2026-07-29 | tech+store | 278048        | Unit photographed at this store; label crossed with sibling — reissued from file |
| PetSmart US #1975       | 278048                 | 2026-07-29 | tech+store | 10961123      | Unit photographed at this store; label                                           |

|                 |         |            |            |          |                                                                                  |
|-----------------|---------|------------|------------|----------|----------------------------------------------------------------------------------|
|                 |         |            |            |          | crossed with sibling — reissued from file                                        |
| PetSmart US #81 | 278022  | 2026-07-24 | tech+store | 313166   | Correct plate photo on file (misfiled) — reissued from file                      |
| PetSmart US #81 | 246419  | 2026-07-24 | tech+store | 10961123 | Plate photo shows another unit — re-photograph                                   |
| PetSmart US #81 | 246414  | 2026-07-24 | tech+store | 246414   | Verified — signed report + matching plate photo                                  |
| PetSmart US #82 | 269642  | 2026-07-23 | tech+store | M032645  | Unit photographed at this store; label crossed with sibling — reissued from file |
| PetSmart US #82 | M032645 | 2026-07-23 | tech+store | 269642   | Unit photographed at this store; label crossed with sibling — reissued from file |
| PetSmart US #86 | 246365  | 2026-07-20 | tech+store | 278045   | Unit photographed at this store; label crossed with sibling — reissued from file |
| PetSmart US #86 | 246364  | 2026-07-20 | tech+store | 246365   | Plate photo shows another unit — re-photograph                                   |
| PetSmart US #86 | 278045  | 2026-07-20 | tech+store | -        | Unit photographed at this store; label crossed with sibling — reissued from file |
| Petco #1306     | 227269  | 2026-07-21 | tech+store | 306402   | Unit photographed at this store; label crossed with sibling — reissued from file |

|             |                |            |            |                  |                                                                                  |
|-------------|----------------|------------|------------|------------------|----------------------------------------------------------------------------------|
| Petco #1306 | 227620         | 2026-07-21 | tech+store | 227269           | Unit photographed at this store; label crossed with sibling — reissued from file |
| Petco #1306 | 306402         | 2026-07-21 | tech+store | 227620           | Unit photographed at this store; label crossed with sibling — reissued from file |
| Petco #1338 | 233671         | 2026-07-23 | tech+store | 233671           | Verified — signed report + matching plate photo                                  |
| Petco #1338 | 244380         | 2026-07-23 | tech+store | 244380           | Verified — signed report + matching plate photo                                  |
| Petco #1338 | 5232171        | 2026-07-23 | tech+store | 11008876/M158123 | Plate photo shows another unit — re-photograph                                   |
| Petco #1338 | 341506031614   | 2026-07-23 | tech+store | M153303          | Plate photo shows another unit — re-photograph                                   |
| Petco #1338 | 312894         | 2026-07-23 | tech+store | 10961123         | Plate photo shows another unit — re-photograph                                   |
| Petco #1343 | 313084         | 2026-07-15 | tech+store | 313084           | Verified — signed report + matching plate photo                                  |
| Petco #1343 | 226512         | 2026-07-15 | tech+store | 226507           | Unit photographed at this store; label crossed with sibling — reissued from file |
| Petco #1343 | 226507         | 2026-07-15 | tech+store | 226512           | Unit photographed at this store; label crossed with sibling — reissued from file |
| Petco #1343 | 20125900000422 | 2026-07-15 | tech+store | 10157996         | Plate photo shows another unit — re-photograph                                   |

|                   |        |            |            |               |                                                                                  |
|-------------------|--------|------------|------------|---------------|----------------------------------------------------------------------------------|
| Petco #1350       | 197934 | 2026-07-23 | tech+store | 240067        | On-site photo disagrees with asset-list serial — serial to be confirmed          |
| Petco #1350       | 244067 | 2026-07-23 | tech+store | 197834        | On-site photo disagrees with asset-list serial — serial to be confirmed          |
| Petco #1350       | 313062 | 2026-07-23 | tech+store | 313062        | Verified — signed report + matching plate photo                                  |
| Petco #1506       | 192210 | 2026-07-21 | tech+store | -             | Unit photographed at this store; label crossed with sibling — reissued from file |
| Petco #1506       | 244270 | 2026-07-21 | tech+store | 192210        | Plate photo shows another unit — re-photograph                                   |
| Petco #1506       | 312397 | 2026-07-21 | tech+store | 312397        | Verified — signed report + matching plate photo                                  |
| Petco #269        | FPA    | 2026-07-22 | tech+store | -             | No photos on report — re-photograph                                              |
| Petco #307        | 202406 | 2026-07-24 | tech+store | -             | Unit photographed at this store; label crossed with sibling — reissued from file |
| Petco #307        | 243062 | 2026-07-24 | tech+store | 202406/243062 | Verified — signed report + matching plate photo                                  |
| Petco #307        | 313166 | 2026-07-29 | tech+store | M153303       | Correct plate photo on file (misfiled) — reissued from file                      |
| Petsmart US #2487 | 299301 | 2026-07-22 | tech+store | 299342        | Unit photographed at this store; label crossed with                              |

|                   |          |            |            |          |                                                                                  |
|-------------------|----------|------------|------------|----------|----------------------------------------------------------------------------------|
|                   |          |            |            |          | sibling — reissued from file                                                     |
| Petsmart US #2487 | 299342   | 2026-07-22 | tech+store | 299301   | Unit photographed at this store; label crossed with sibling — reissued from file |
| Petsmart US #3052 | 281232   | 2026-07-21 | tech+store | M032630  | Plate photo shows another unit — re-photograph                                   |
| Petsmart US #3052 | 281224   | 2026-07-21 | tech+store | 281224   | Verified — signed report + matching plate photo                                  |
| Petsmart US #3052 | M032630  | 2026-07-21 | tech+store | 11008872 | Unit photographed at this store; label crossed with sibling — reissued from file |
| Petsmart US #84   | 207967   | 2026-07-21 | tech+store | -        | Correct plate photo on file (misfiled) — reissued from file                      |
| Petsmart US #84   | 250475   | 2026-07-21 | tech+store | 250475   | Verified — signed report + matching plate photo                                  |
| Raley's #308      | 9318070  | 2026-07-24 | tech+store | 295403   | Plate photo shows another unit — re-photograph                                   |
| Raley's #316      | 9335646  | 2026-07-30 | tech+store | 9335646  | Verified — signed report + matching plate photo                                  |
| Raley's #339      | 10114978 | 2026-07-29 | tech+store | M158123  | Plate photo shows another unit — re-photograph                                   |
| Raley's #339      | 10114974 | 2026-07-29 | tech+store | 10961123 | Plate photo shows another unit — re-photograph                                   |
| Raley's #416      | 9318060  | 2026-07-15 | tech+store | 9318060  | Verified — signed report + matching plate photo                                  |
| Safeway #2263     | 310797   | 2026-07-15 | tech+store | 10157996 | Plate photo shows another unit — re-photograph                                   |

|                                            |        |            |            |               |                                                                         |
|--------------------------------------------|--------|------------|------------|---------------|-------------------------------------------------------------------------|
| Safeway<br>#55                             | 291749 | 2026-07-30 | tech+store | 291749        | Verified — signed report + matching plate photo                         |
| Safeway<br>Northern<br>California<br>#1195 | 309097 | 2026-07-31 | tech+store | 305983        | On-site photo disagrees with asset-list serial — serial to be confirmed |
| Safeway<br>Northern<br>California<br>#1211 | 276954 | 2026-07-30 | tech+store | -             | No legible plate photo — re-photograph                                  |
| Safeway<br>Northern<br>California<br>#1211 | 304440 | 2026-07-30 | tech+store | 276973        | On-site photo disagrees with asset-list serial — serial to be confirmed |
| Safeway<br>Northern<br>California<br>#1502 | 304913 | 2026-07-30 | tech+store | 304913        | Verified — signed report + matching plate photo                         |
| Safeway<br>Northern<br>California<br>#1502 | 305407 | 2026-07-30 | tech+store | 305407        | Verified — signed report + matching plate photo                         |
| Safeway<br>Northern<br>California<br>#1661 | 295380 | 2026-07-24 | tech+store | 295380        | Verified — signed report + matching plate photo                         |
| Safeway<br>Northern<br>California<br>#1661 | 295403 | 2026-07-24 | tech+store | M153303       | Correct plate photo on file (misfiled) — reissued from file             |
| Safeway<br>Northern<br>California<br>#2856 | 294043 | 2026-07-30 | tech+store | M158123       | Plate photo shows another unit — re-photograph                          |
| Safeway<br>Northern<br>California<br>#910  | 304967 | 2026-07-30 | tech+store | 304967/304968 | Verified — signed report + matching plate photo                         |
| Safeway<br>Northern<br>California<br>#910  | 304968 | 2026-07-30 | tech+store | 304968        | Verified — signed report + matching plate photo                         |

|                                           |                |            |            |          |                                                                      |
|-------------------------------------------|----------------|------------|------------|----------|----------------------------------------------------------------------|
| Safeway<br>Northern<br>California<br>#969 | 311982         | 2026-07-31 | tech+store | 311982   | Verified — signed<br>report + matching<br>plate photo                |
| Sam's Club<br>#4704                       | M157299        | 2026-07-22 | tech+store | M157299  | Verified — signed<br>report + matching<br>plate photo                |
| Sam's Club<br>#4819                       | M155783        | 2026-07-21 | store only | 11008876 | Plate photo shows<br>another unit — re-<br>photograph                |
| Save Mart<br>#1                           | 10567901       | 2026-07-24 | tech+store | 10961123 | Correct plate<br>photo on file<br>(misfiled) —<br>reissued from file |
| Save Mart<br>#1                           | 10637908       | 2026-07-24 | tech+store | 278022   | Correct plate<br>photo on file<br>(misfiled) —<br>reissued from file |
| Save Mart<br>#49                          | 11133289       | 2026-07-24 | tech+store | 10637908 | Plate photo shows<br>another unit — re-<br>photograph                |
| Save Mart<br>#49                          | 11126733       | 2026-07-24 | tech+store | 10567901 | Plate photo shows<br>another unit — re-<br>photograph                |
| Save Mart<br>#54                          | 32158100000214 | 2026-07-23 | tech+store | -        | No legible plate<br>photo — re-<br>photograph                        |
| Save Mart<br>#622                         | 10874906       | 2026-07-15 | tech+store | 313084   | Plate photo shows<br>another unit — re-<br>photograph                |
| Save Mart<br>#622                         | 10911486       | 2026-07-15 | tech+store | -        | No photos on<br>report — re-<br>photograph                           |
| Save Mart<br>#635                         | 11157328       | 2026-07-23 | tech+store | 10874841 | Plate photo shows<br>another unit — re-<br>photograph                |
| Save Mart<br>#635                         | 11157331       | 2026-07-23 | tech+store | 10874913 | Plate photo shows<br>another unit — re-<br>photograph                |
| Save Mart<br>#65                          | 10564803       | 2026-07-23 | tech+store | 10564803 | Verified — signed<br>report + matching<br>plate photo                |
| Save Mart<br>#650                         | 10874889       | 2026-07-23 | tech+store | 10874889 | Verified — signed<br>report + matching                               |



|                |                |            |            |                   |                                                                                  |
|----------------|----------------|------------|------------|-------------------|----------------------------------------------------------------------------------|
|                |                |            |            |                   | plate photo                                                                      |
| Save Mart #650 | 10874911       | 2026-07-23 | tech+store | 10874911          | Verified — signed report + matching plate photo                                  |
| Save Mart #651 | 10362991       | 2026-07-22 | tech+store | 11150523          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Save Mart #651 | 11150523       | 2026-07-22 | tech+store | 10362991          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Save Mart #71  | 10372249       | 2026-07-23 | tech+store | M158123           | Unit photographed at this store; label crossed with sibling — reissued from file |
| Save Mart #71  | 11157343       | 2026-07-23 | tech+store | 10372249/11157343 | Verified — signed report + matching plate photo                                  |
| Save Mart #78  | 10874913       | 2026-07-23 | tech+store | M153303           | Correct plate photo on file (misfiled) — reissued from file                      |
| Save Mart #78  | 10874841       | 2026-07-23 | tech+store | 10874841          | Verified — signed report + matching plate photo                                  |
| Save Mart #86  | 10874858       | 2026-07-29 | tech+store | 10874893          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Save Mart #86  | 10874893       | 2026-07-29 | tech+store | 10874858          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Save Mart #92  | 32158100000985 | 2026-07-23 | tech+store | -                 | No legible plate photo — re-                                                     |

|               |          |            |            |                   |                                                                                  |
|---------------|----------|------------|------------|-------------------|----------------------------------------------------------------------------------|
|               |          |            |            |                   | photograph                                                                       |
| Save Mart #93 | 11133293 | 2026-07-23 | tech+store | 11133295          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Save Mart #93 | 11133295 | 2026-07-23 | tech+store | 11133293          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Save Mart #95 | 10377426 | 2026-07-29 | tech+store | 10377426/10874883 | Verified — signed report + matching plate photo                                  |
| Save Mart #95 | 10874883 | 2026-07-29 | tech+store | 10961123          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Save Mart #96 | 10741385 | 2026-07-21 | tech+store | 11126725          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Save Mart #96 | 11126725 | 2026-07-21 | tech+store | 10741385          | Unit photographed at this store; label crossed with sibling — reissued from file |
| Target #1384  | 9139322  | 2026-07-21 | tech+store | -                 | No legible plate photo — re-photograph                                           |
| Target #1417  | 10540856 | 2026-07-22 | tech+store | M158123           | Plate photo shows another unit — re-photograph                                   |
| Target #1417  | 10902793 | 2026-07-22 | tech+store | M158123           | Plate photo shows another unit — re-photograph                                   |
| Target #2524  | 9632927  | 2026-07-20 | tech+store | 11008872/11008876 | Plate photo shows another unit — re-photograph                                   |

|                   |          |            |            |          |                                                     |
|-------------------|----------|------------|------------|----------|-----------------------------------------------------|
| Target #2715      | 10633827 | 2026-07-21 | tech+store | -        | No legible plate photo — re-photograph              |
| Target #273       | 9632923  | 2026-07-29 | tech+store | 9632923  | Verified — signed report + matching plate photo     |
| Target #2744      | 9318085  | 2026-07-23 | tech+store | 9318085  | Verified — signed report + matching plate photo     |
| Target #275       | 10902784 | 2026-07-23 | tech+store | 10902784 | Verified — signed report + matching plate photo     |
| Target #2771      | 9380266  | 2026-07-30 | tech+store | 9380266  | Verified — signed report + matching plate photo     |
| Target #2922      | 10927323 | 2026-07-22 | tech+store | 10927323 | Verified — signed report + matching plate photo     |
| Target #311       | 10633828 | 2026-07-15 | tech+store | 10633828 | Verified — signed report + matching plate photo     |
| Target #314       | 10624594 | 2026-07-22 | tech+store | 10624594 | Verified — signed report + matching plate photo     |
| Target #614       | 9455985  | 2026-07-21 | tech+store | 9455985  | Verified — signed report + matching plate photo     |
| Target #828       | 9627188  | 2026-07-30 | tech+store | 9627188  | Verified — signed report + matching plate photo     |
| Target #911       | 10580525 | 2026-07-22 | tech+store | 10580525 | Verified — signed report + matching plate photo     |
| Target #938       | 10571802 | 2026-07-29 | tech+store | 278022   | Plate photo shows another unit — re-photograph      |
| The Market #13675 | 10613013 | 2026-07-23 | tech+store | 10613013 | Verified — signed report + matching plate photo     |
| Vons #1754        | 263121   | 2026-07-22 | tech+store | 263124   | Unit photographed at this store; label crossed with |

|                  |          |            |            |          |                                                                                  |
|------------------|----------|------------|------------|----------|----------------------------------------------------------------------------------|
|                  |          |            |            |          | sibling — reissued from file                                                     |
| Vons #1754       | 263124   | 2026-07-22 | tech+store | 263121   | Unit photographed at this store; label crossed with sibling — reissued from file |
| Vons #1969       | 294053   | 2026-07-20 | tech+store | 11008872 | Plate photo shows another unit — re-photograph                                   |
| Vons #2033       | 9413973  | 2026-07-21 | tech+store | 10567891 | Unit photographed at this store; label crossed with sibling — reissued from file |
| Vons #2033       | 10567891 | 2026-07-21 | tech+store | 9413973  | Unit photographed at this store; label crossed with sibling — reissued from file |
| Vons #2188       | 311477   | 2026-07-23 | tech+store | 311477   | Verified — signed report + matching plate photo                                  |
| Vons #2420       | 9166246  | 2026-07-21 | tech+store | 10671499 | Unit photographed at this store; label crossed with sibling — reissued from file |
| Vons #2420       | 10671499 | 2026-07-21 | tech+store | 10658930 | Unit photographed at this store; label crossed with sibling — reissued from file |
| Vons #2420       | 10658930 | 2026-07-21 | tech+store | 9166246  | Unit photographed at this store; label crossed with sibling — reissued from file |
| Walmart US #1587 | 277481   | 2026-07-29 | tech+store | 277481   | Verified — signed report + matching                                              |

|                  |          |            |            |                  |                                                                                  |
|------------------|----------|------------|------------|------------------|----------------------------------------------------------------------------------|
|                  |          |            |            |                  | plate photo                                                                      |
| Walmart US #1624 | 9267058  | 2026-07-20 | tech+store | 11351592/9267058 | Verified — signed report + matching plate photo                                  |
| Walmart US #1815 | 9697100  | 2026-07-23 | tech+store | M153303          | Plate photo shows another unit — re-photograph                                   |
| Walmart US #1972 | 262650   | 2026-07-30 | tech+store | 10213740/262650  | Verified — signed report + matching plate photo                                  |
| Walmart US #1983 | 9681570  | 2026-07-24 | tech+store | -                | Closed / missing site — visit documented, withdrawn as PM                        |
| Walmart US #2001 | 9729228  | 2026-07-22 | tech+store | 10629523/9729228 | Verified — signed report + matching plate photo                                  |
| Walmart US #2161 | 302431   | 2026-07-30 | tech+store | M158123          | Plate photo shows another unit — re-photograph                                   |
| Walmart US #2557 | 10254960 | 2026-07-21 | tech+store | 10609651         | On-site photo disagrees with asset-list serial — serial to be confirmed          |
| Walmart US #2985 | M098901  | 2026-07-23 | tech+store | 10571808/M098901 | Verified — signed report + matching plate photo                                  |
| Walmart US #3046 | M116647  | 2026-07-30 | tech+store | 11200211/M116647 | Verified — signed report + matching plate photo                                  |
| Walmart US #3046 | 11200211 | 2026-07-30 | tech+store | -                | Unit photographed at this store; label crossed with sibling — reissued from file |
| Walmart US #3138 | 303921   | 2026-07-21 | tech+store | 10540885         | On-site photo disagrees with asset-list serial — serial to be confirmed          |
| Walmart US #3139 | 303346   | 2026-07-21 | tech+store | -                | No legible plate photo — re-photograph                                           |

|                               |          |            |            |          |                                                                         |
|-------------------------------|----------|------------|------------|----------|-------------------------------------------------------------------------|
| Walmart US #3140              | 302442   | 2026-07-21 | tech+store | 11008872 | Plate photo shows another unit — re-photograph                          |
| Walmart US #3141              | 290980   | 2026-07-21 | tech+store | 11008872 | Correct plate photo on file (misfiled) — reissued from file             |
| Walmart US #5134              | 279848   | 2026-07-21 | tech+store | -        | No photos on report — re-photograph                                     |
| Walmart US #5192              | 9627102  | 2026-07-15 | tech+store | 10162233 | On-site photo disagrees with asset-list serial — serial to be confirmed |
| Walmart US #5632              | M125927  | 2026-07-22 | tech+store | 11200214 | On-site photo disagrees with asset-list serial — serial to be confirmed |
| Walmart US #5710              | 10168520 | 2026-07-29 | tech+store | 10961123 | Plate photo shows another unit — re-photograph                          |
| Walmart US #5982              | M125962  | 2026-07-15 | tech+store | M125962  | Verified — signed report + matching plate photo                         |
| Whities Pets #602468          | 9986231  | 2026-07-22 | tech+store | 9986231  | Verified — signed report + matching plate photo                         |
| Whole Foods Market #10122-FRS | 11096711 | 2026-07-23 | tech+store | 11096711 | Verified — signed report + matching plate photo                         |

Prepared from preserved original records. Nothing in the submitted batch has been altered.