Annex 1:

Accessibility Testing Bug Reports

Test site: C3 Consulting – https://c3consulting.dk/en/home
Tester: Maria Christensen
Date: 10 April 2026

A. Screen Reader Bug Reports

Eight non-image bugs were found during the screen reader scan, 7 of which have also been identified by the semi-automated and automated tests. BUG-SS-03 was not identified by Wave, axe DevTools, and axe-core as an issue.

Bug ID:	BUG-SS-01
Title	“Learn More” Buttons Lack Content
WCAG	2.4.4 Link Purpose (In Context) – Level A
Severity	🔶 Major
Priority	🔶 Medium
Description	Six ”Learn More” buttons on one page are not descriptive for screen reader users or other assistive gadgets. Similar button titles do not readily indicate the content or action specific to the 6 cards
Steps to reproduce	1. Navigate to https://c3consulting.dk/en/home. 2. Tab through the homepage cards containing “Learn More” buttons 3. Observe/listen to screen reader output.
Expected result	Screen reader should announce descriptive accessible names, e.g. “Learn More about Cultural GPS Course” button
Actual result	Screen reader only announces “Learn More”
Affected users	Blind users; users with low vision, cognitive disabilities or motor impairments
Accessibility impact	Can be confusing when multiple buttons are present. Screen reader users cannot distinguish between multiple “Learn More” buttons thus reducing usability and a confusing UX.
Recommendation	Use aria-label for unique description or aria-labelledby to reference surrounding text
Environment	Windows 11, Google Chrome (latest)
Attachment	screen_reader_bug report_screenshot_bug-ss-01.png



screen_reader_bug report_screenshot_bug-ss-01.png
Sample page with generic button titles

Reported by: Maria Christensen
Date: 10 April 2026

Accessibility Testing Assignment

Bug ID:	BUG-SS-02
Title	Improper heading structure on homepage
WCAG	1.3.1 Info and Relationships – Level A: Headings must convey meaningful structure. 2.4.1 Bypass Blocks (Level A) 2.4.6 Headings and Labels – Level AA: Users must be able to navigate efficiently via headings.
Severity	🔶Major
Priority	🔶Medium
Description	Headings are structured incorrectly: h1 → h3 → h5 → h4. H2 is entirely missing and h4 comes after h5. Some headings are also active links, e.g.: ● H5 is a subtitle link ● H4 is a card/article link When navigating with a screen reader, only the h5 element is announced clearly.
Steps to reproduce	1. Navigate to https://c3consulting.dk/en/home. 2. Inspect headings using DevTools and screen reader. 3. Note the heading levels and order. 4. Tab through headings using a screen reader,
Expected result	Headings should follow a logical hierarchical order: h1 → h2 → h3 → h4 → h5 → h6, reflecting the document structure.
Actual result	Headings are ordered h1 → h3 → h5 → h4. H2 is missing; Screen reader only announces h5 reliably due to it being an active link.
Affected users	Users of assistive technologies; with learning disabilities; on mobile devices; keyboard-only users
Accessibility impact	Screen reader users may have difficulty understanding the page's structure because headings are out of logical order. Active headings can obscure the hierarchy making it harder to navigate and perceive relationships between sections. Users relying on heading navigation may miss important content or get lost in the page.
Recommendation	Identify skipped levels, multiple uses. And misuses. Restructure headings in hierarchical, outline-style rather than visual style.
Environment	Windows 11, Google Chrome (latest)
Attachments	screen_reader_bug report_screenshot_bug-ss-02.png

Reported by: Maria Christensen
Date: 10 April 2026

Accessibility Testing Assignment



screen_reader_bug report_screenshot_bug-ss-02.png
Headings with incorrect structure

Bug ID:	BUG-SS-03 (not identified by Wave, axe DevTools, and axe-core)
Title	Card elements not grouped into a single accessible unit
WCAG	1.3.1 Info and Relationships – Level A 2.4.3 Focus Order – Level A 2.4.4 Link Purpose (In Context) – Level A
Severity	🔶 Major
Priority	🔶 Medium
Description	Image link and title link are separate interactive elements, even while leading to the same URL. Card components consist of a clickable image within a *<figure>* element and a separate h4 title link below it. The image has an empty *alt* attribute but an accessible name is correctly provided via *<figcaption>*.
Steps to reproduce	1. Navigate to https://c3consulting.dk/en/home. 2. Locate a card or blog post with an image and h4 title. 3. Inspect the element structure in DevTools (see description). 4. Use keyboard navigation (Tab). 5. Observe focus stops on both image and title separately. 6. Use screen reader and observe announcements.
Expected result	Each card should be exposed as a single interactive element with one clear accessible name (combining image and title into one link).
Actual result	The image link and title link are separate focusable elements with similar or identical accessible names.
Affected users	Screen reader users, keyboard-only users, visually impaired, mobile users, users with tremors
Accessibility impact	Separate interactive elements with the same destination create duplicate and fragmented navigation. Users must tab through multiple elements for the same content, which introduces redundancy and makes the relationship between the image and its title unclear.
Recommendation	Group related card elements ; use ‘aria-label’ or ‘aria-labelledby’
Environment	Windows 11, Google Chrome (latest)
Attachments	screen_reader_bug report_screenshot_bug-ss-03.png



screen_reader_bug report_screenshot_bug-ss-03.png
Card elements not grouped into a single accessible unit

Bug ID:	BUG-SS-04
Title	Missing accessible labels on email input
WCAG	1.3.1 Info and Relationships – Level A 3.3.2 Labels or Instructions – Level A 4.1.2 Name, Role, Value – Level A
Severity	🔴 Critical
Priority	🔴 High
Description	In the “Sign up for newsletter” section, the email input field is not properly announced by screen reader. It does not have an associated label or accessible names. The voice output is unclear. As a result, assistive technologies such as screen readers cannot determine the purpose of this input.
Steps to reproduce	1. Navigate to https://c3consulting.dk/en/home. 2. Focus on the email field using tab navigation. 3. Listen to the screen reader announcement.
Expected result	Email input fields should have a clearly defined accessible label that is announced by screen readers.
Actual result	Email input field is announced without context (e.g. “edit field”) with no indication of purpose.
Affected users	Screen reader users Users with cognitive impairments
Accessibility impact	Users cannot understand or interact with email form field effectively blocking form submission
Recommendation	Associate each input with a <label> element or provide an accessible name using aria-label or aria-labelledby.
Environment	Windows 11, Google Chrome (latest)
Attachment	screen_reader_bug report_screenshot_bug-ss-04.png



screen_reader_bug report_screenshot_bug-ss-04.png
Missing accessible labels on email input

Bug ID:	BUG-SS-05
Title	Missing accessible labels on search input
WCAG	3.3.2 Labels or Instructions – Level A 4.1.2 Name, Role, Value – Level A
Severity	🔴 Critical
Priority	🔴 High
Description	The search input field does not have an accessible name. The screen reader announces it as “edit blank”. Which makes it difficult to determine the purpose of this input.
Steps to reproduce	1. Navigate to https://c3consulting.dk/en/home. 2. Focus on the search field using tab navigation. 3. Listen to the screen reader announcement.
Expected result	Search input fields should have a clearly defined accessible label that is announced by screen readers.
Actual result	Search input field is announced without context (e.g. “edit field”) with no indication of purpose.
Affected users	Screen reader users Users with cognitive impairments
Accessibility impact	Users cannot determine the purpose of the input field, This creates confusion and may prevent users from using the search functionality.
Recommendation	Associate each input with a <label> element or provide an accessible name using aria-label or aria-labelledby.
Environment	Windows 11, Google Chrome (latest)
Attachment	None

Bug ID:	BUG-SS-06
Title	Generic “Click here” link lacks meaningful context
WCAG	2.4.4 Link Purpose (In Context) – Level A
Severity	🔶 Major
Priority	🔶 Medium
Description	The link is visually indistinguishable from surrounding paragraph text due to lack of underline and insufficient contrast, making it difficult for users to identify it as an interactive element.
Steps to reproduce	1. Navigate to https://c3consulting.dk/en/home. 2. Locate the section “Buy our book”. 3. Locate the test mentioning bulk purchase or book information. 4. Tab to the “Click here” link. 5. Listen to the screen reader announcement.
Expected result	The link should have a descriptive name or use an ARIA-label to clarify the destination.
Actual result	Screen reader announces only “Click here” without context.
Affected users	Users relying on assistive technologies, visually impaired
Accessibility impact	Screen reader users cannot determine the purpose or destination of the link when navigating via keyboard or link lists. This creates confusion and reduces usability, as users must rely on surrounding context that may not be available.
Recommendation	Use ‘aria-label’ or ‘aria-labelledby; improve color contrast, Use underline style to differentiate from static text element.
Environment	Windows 11, Google Chrome (latest)
Attachment	screen_reader_bug report_screenshot_bug-ss-06a.png, screen_reader_bug report_screenshot_bug-ss-06a.png

Reported by: Maria Christensen
Date: 10 April 2026

Accessibility Testing Assignment



screen_reader_bug report_screenshot_bug-ss-06a.png
Generic “Click here”



screen_reader_bug report_screenshot_bug-ss-06b.png
Insufficient contrast and link style

Bug ID:	BUG-SS-07
Title	Social media icon links on footer lack accessible names
WCAG	4.1.2 Name, Role, Value – Level A 2.4.4 Link Purpose (In Context) – Level A
Severity	🔶 Major
Priority	🔶 Medium
Description	In the footer section under the heading “Follow Us,” LinkedIn and Vevo icons are presented as links. Screen readers announce these links only as “link” or “visited link,” without specifying the platform. The visible text “Follow Us” does not programmatically associate with the icons.
Steps to reproduce	1. Navigate to https://c3consulting.dk/en/home. 2. Tab to the footer section 3. Tab to LinkedIn and Vevo icons 4. Listen to the screen reader announcement.
Expected result	Screen reader should announce each link with a descriptive name, e.g., “LinkedIn – Follow Us,” “Vevo – Follow Us.”
Actual result	Screen reader announces only “link” or “visited link.”
Affected users	Everyone
Accessibility impact	Users cannot determine which social media platform each icon represents, reducing navigation clarity and accessibility.
Recommendation	Remove empty link or provide text within the link to describe functionality and/or target of the link.
Environment	Windows 11, Google Chrome (latest)
Attachment	screen_reader_bug report_screenshot_bug-ss-07.png

Reported by: Maria Christensen
Date: 10 April 2026

Accessibility Testing Assignment


wave.webaim.org/report#/https://c3consulting.dk/en/home
WAVE
web accessibility evaluation tool
powered by WebAIM
Address: https://c3consulting.dk/en/home
Styles: OFF ON
Summary
Details
Reference
Order
Structure
Contrast
4 Missing form label
2 Empty link
16 Broken ARIA reference
The following apply to the entire page:
en-GB
aria-label="submit form"
aria-controls="navbarSupportedContent"
aria-label="Toggle navigation"
CONSULTING
CULTURE COMMUNICATION COLLABORATION
Code
<ul class="social-icons justi -between justify-content-sm-end">
<li>
<a href="https://www.linkedin.com/company/c3consulting/" target="_blank" class="linkdin">

</a>
</li>
<li>
<a href="https://vimeo.com/c3consulting" target="_blank" class="vimeo">
</</</

Bug ID:	BUG-SS-08
Title	Footer company logo link lacks accessible names
WCAG	4.1.2 Name, Role, Value – Level A 2.4.4 Link Purpose (In Context) – Level A
Severity	🔶 Major
Priority	🔶 Medium
Description	In the footer section of the homepage, the C3 logo acts as a link to return to the top of the homepage but has no associated accessible name. Screen reader announces it only as “link” providing no context about its destination or function.
Steps to reproduce	1. Navigate to https://c3consulting.dk/en/home. 2. Tab to the footer section 3. Locate theC3 logo. 4. Listen to the screen reader announcement.
Expected result	Screen reader should announce:“C3 Consulting – homepage link”
Actual result	Screen reader announces only “link” or “visited link.”
Affected users	Visually-impaired, motor-impaired, voice-control users, etc.
Accessibility impact	Users cannot tell that the logo link returns them to the homepage, making navigation less efficient and confusing for assistive technology users.
Recommendation	Remove empty link or provide text within the link to describe functionality and/or target of the link.
Environment	Windows 11, Google Chrome (latest)
Attachment	None

Reported by: Maria Christensen
Date: 10 April 2026

Accessibility Testing Assignment

B. Image Bug Reports

Application under test: https://c3consulting.dk/en/home

Title : Missing alt text on homepage images
WCAG Bases : 1.1.1 Non-text Content (A), 4.1.2 Name, Role, Value (A)
Severity: 🔴 Critical
Priority: 🔴 High
Steps to Reproduce :
1. Open homepage
2. Inspect main banner image, logo, card, and image links
3. Evaluate if the alt text describes the image meaningfully.

Expected Result : Image should have meaningful alt text.
Actual Result : Alt attribute is empty.
Affected Users: Visually-impaired, users with cognitive disabilities, low bandwidth/slow network users, colorblind, screen readers
Accessibility Impact : Screen reader users cannot understand the banner content.
Recommendation: See “suggested alt text” on the table below:
Environment: Windows 11, Google Chrome (latest)
Screenshot attachments : None, as all images in the homepage have issues.

Bug ID	Image / Section	Description of Issue	Suggested Alt Text
BUG-SS-09	Logo (top)	alt="" – no descriptive alt	“C3 Consulting logo – link to homepage”
BUG-SS-10	4R Model Image	Empty alt	“5 diverse people in informal meeting, representing 4R cultural model”
BUG-SS-11	Country-specific Cultural Training		“Directional signpost with arrows showing different countries and flags”
BUG-SS-12	Global Mobility		“Global mobility illustration of people and arrows”
BUG-SS-13	Why C3 Consulting		“Team discussing project in office”
BUG-SS-14	How the training achieves objectives		“Illustration of training objectives with icons”
BUG-SS-15	Meet our Trainers		“Portraits of C3 trainers smiling”
BUG-SS-16	Card / Blog image	Empty alt, not complemented by h4 title	“CEO Annette Dahl”
BUG-SS-17			“Trainer portrait”
BUG-SS-18			“Newsletter graphic”
BUG-SS-19			“Illustration of two perspectives”
BUG-SS-20			“Blog post image – Warsaw, Poland”
BUG-SS-21			“Blog post image – Wooden door with dragon handles”
BUG-SS-22	Mockup Image	Empty alt	“Book on Global Perspective”
BUG-SS-23	Footer Logo		“C3 Consulting footer logo – link to homepage”