
East service block · kitchen, laundry, maid wing · layout study (V10.0; the maid's wing layout D, 10 Nov 2026)

Taif / Palm House · Ground floor V7.1 · block = CSV x 8.95–13.311, y 0–13.0 (NE corner cut) · 49.22 m² · scale 1 m = 1.15 cm · north up



Rooms

Room	w × d (m)	m²
Maid bath	sloped (to the cut wall)	2.94
Maid room	sloped (to the cut wall)	10.17
Laundry	sloped (to the cut wall)	7.77
Kitchen	4.36 × 6.5	28.35
Leftover slivers along the cut		0
Block		**49.22**

✓ **All rooms inside the block, no overlaps**

Route

Family: living (normal height) · dining → kitchen (south door).
Maid (D): kitchen → laundry → her room → her bath. No external door and no other door: all her movement passes through the kitchen and the laundry.
Cooking: sink on the courtyard wall under its window (y 7.3–8.9, looking at the courtyard's fountain and tree; the outdoor TV on the courtyard face of the wall further south), hob and hood on the east (outside) wall, so heat and smoke leave the house; fridge and tall storage at the south-east, next to the dining door; the east duct in the north-east corner.

Rules

- Kitchen isolated: doors only to the dining area (south) and the laundry (north). No door to the courtyard, riwaq or women's majlis.
- Kitchen 4.361 × 6.0 m on axes (26.17 m², ≈ 24.0 m² clear, ≈ 4.136 m clear wide), y 7.0–13.0 (V6.4: its north wall is a non-load-bearing partition 0.5 m south of the structural line y 6.5, so the maid room reaches the municipal minimum). No island: two parallel counter runs, the sink run 5.4 m on the courtyard wall and the cooking run 3.0 m (y 8.2–11.2, the hob and hood at y 10.2–11.2 south of the east window) plus the fridge and tall storage on the east outside wall; ≈ 2.94 m between the counter fronts. The heavy (dirty) kitchen; the hospitality kitchen in the west block is the light one.
- **Laundry (layout D, 10 Nov 2026; `studies/maid_wing.typ` adopted):** across the whole width from the kitchen, y 4.7–6.5 (11 Nov 2026, owner: the kitchen wall on the structural line y 6.5, in line with the majlis wall; 1.8 m deep, ≈ 6.6 m² clear): two washers and a stacked dryer, the tall cupboards and the steam station in one run on the kitchen wall (x 1.75–4.23), the folding / ironing table 1.5 × 0.6 on the majlis wall, a 1.0 m passage, the ceiling drying rack at the east window (y 5.35–6.25, insect screen) with the extract fan (humidity sensor) above it, a floor drain; the door 0.90 from the kitchen on y 6.5 (was an open entrance); no sink, no yard door.
- **Maid room (D):** north of the bath, the north tip and the majlis wall: the bed 0.9 × 2.0 on the majlis wall, the main wardrobe 1.35 × 0.6 on the north wall, the shelf wedge in the north tip (front on x 1.7), the bed in the north corner with its head on the north wall, the wardrobe on the majlis wall south of it, the small desk under the escape casement on the cut's north part (y 1.5–2.5: 1.14 × 1.00, sill +1.10, obscured below +1.60, no screen); its one door 0.90 from the laundry at the south-west; ≈ 10.2 m² on axes, ≈ 8.9 m² clear (≥ the 7.28 the house adopted as the municipal minimum; the bath 1.5 m deep since the refinement of 10 Nov 2026).
- **Maid bath (D):** against the south part of the cut wall next to the laundry (x 1.7 to the cut, y 3.2–4.7; ≈ 2.8 m² on axes, ≈ 2.5 m² clear): a simple wet room like the guest WC: a wall-mounted shower and mixer in the obtuse south-east corner over a floor drain with falls (tanked and tiled, no tray, no cubicle; a short 10 cm wall only if the WC needs keeping dry), the WC under the window on the cut (y 3.35–3.95, obscured), the basin on the west partition; the door 0.70 from her room only; the drains straight out through the cut wall (≈ 1 m) to the east branch; an extract fan.
- Main cross walls: y 6.5 (kitchen / laundry, 11 Nov 2026: ON the structural line, under beam B6, one straight line with the women's majlis wall; the V6.4 partition at y 7.0 and its 0.5 m jog are gone) and y 13.0 (dining). Exterior walls and

the air tower fixed; all interior walls straight and square. Walls: the maid bath block with waterproofing (wet room); 100 mm for the dry laundry / maid partition; 150–200 mm for walls carrying pipes (maid bath, laundry sink wall).

- Solid wall (no door, no window) between the maid wing and the women's majlis.
- The malqaf (V10.0, L5) is at the courtyard's north-west corner: nothing of the air system in this block; no breeze channel under the maid wing.
- No store (D): the cut tip is inside the maid room (the shelf wedge).
- Plumbing: kitchen, laundry and maid bath drain under the slab straight out to the east, to a manhole in the east service yard; no east duct; the vent stack runs up the outside face of the east wall and the kitchen extract leaves straight through the east wall at the hood. Coordinate drain depths with the air tunnel (also under the east side).
- Service door (owner decision): a lockable 0.90 m door in the kitchen's east wall at its north end (y 7.2–8.1, V6.4), near the laundry, to the east service yard (rubbish, deliveries, gas); the cooking counter starts 0.1 m south of it (y 8.2); the stack outside the east wall sits between the door and the kitchen window (y 8.1–8.7, 0.6 m: MEP to confirm); the hood (y 10.2–11.2) is clear of the door and of column C32 (y 5.7–6.3). Gas (if used): cylinder cabinet outside the east wall in the service yard.