




RESULTS SUMMARY

Date 2023-10-23
Assessor garyw@spectrumgroup.co.nz
Farm Waybrooke Farms
Irrigator Wiper Farm rd
Irrigation Type Center Pivot

DISTRIBUTION UNIFORMITY



RESULTS

Sections	Distribution Uniformity (DU)		Applied Depth Average (mm)		Intensity (mm/hour)
Pivot	0.63	N	8.76	!	
Pivot - Inner Span	0.63	N	9.41	Y	
Pivot - End Span	0.68	!	8.38	!	40.37
End Gun 1			5.23	N	

RESULTS EXPLANATION

Y - Test Passed
No further action required

! - Attention Needed
Check system to resolve

N - Test Did Not Pass
Redo the test or get professional assistance



LOGGED DATA

Pivot Length (m)	590	Inlet Pressure (kPa)	399	Speed (m/min)	1.15
Corner Arm (m)		Wetted Width (m)	14	Speed Test Time	4m 22s
With Endgun	Yes	Bucket Diameter (mm)	245	Speed Test Distance (m)	5
		Bucket Open Area (m2)	0.047	Target Depth (mm)	10.4

RECORDED BUCKET VOLUMES

 Inner Span	 End Span	 End Gun
1 270 mL	16 450 mL	30 350 mL
2 400 mL	17 450 mL	31 300 mL
3 300 mL	18 300 mL	32 90 mL
4 320 mL	19 340 mL	
5 300 mL	20 260 mL	
6 250 mL	21 400 mL	
7 360 mL	22 270 mL	
8 430 mL	23 510 mL	
9 800 mL	24 370 mL	
10 1050 mL	25 500 mL	
11 400 mL	26 500 mL	
12 380 mL	27 450 mL	
13 400 mL	28 400 mL	
14 400 mL	29 230 mL	
15 500 mL		





INTERPRETING YOUR RESULTS

Distribution Uniformity (DU)

Is the measure of how evenly water is being applied along the wetted area of the irrigator. A good DU (> 0.8) is critical to both pasture/crop production and irrigation efficiency.

Measured Application Depth

Is the assessment of the measured irrigation applied depth compared against your target applied depth. Measured application depths should be within 10% of the target depth (this does not include any end gun)

Application Intensity

Is the measure of the intensity in which the water is being applied to the soil. High irrigation application intensities are a common cause of drainage and leaching of nutrients.

Results	Distribution Uniformity (DU)	Measured Depth to Target Depth
Y - Test Passed	0.8 or higher	Within 10%
! - Attention Needed	0.65 - 0.79	Within 25%
N - Test did Not Pass	Less than 0.65	Greater than 25%

Disclaimer

This test is designed to give basic overview of your irrigator performance. It should not be used for commissioning purpose. For more details, refer to the full terms and conditions on the Bucket Test website: www.buckettest.co.nz