Enter a fragment of this exterior pedement gerson remains.


Tourty preserved with cracking, we ather sing and now moss growing as the modeling and at the crevice other the raking some and fascae formerly met.

No side is preserved entirely, but the underside shows 3 casetles flow gurlich are full and 3 modifiens and part fano their mediclesing Enough of the mediclesing some of fascae, Atthe top of the block a small portion of the rise has been preserved with the comma above the cyma vector. The seturn of the fascae, Internal side, and the potent rating some of the latent side, are bridged in industrying their placement.


The three plus medillins would have libely had 2 parallel lines as decoration and to con fluis can be seen on enter edge of the left and second to left medilling as their outer of face. The care's medilling which spans this corner, and the remaining protein of the Cateral medillin are too broken to drips of the remaining protein of the Cateral medillin are too broken to drips of the remaining the same.

All caseths are floral in deconstron with all petals pointed.
The two front facing casethes look a middle circle in their flower do sign. The laft casethe has a 4-petaled flower and the right casethe (which is cut as a trupe joid to occamendate the corner. Contains a 3-petaled flower. The lateral casethe has a 4 petaled flower with a center circle or button.

The foscer of the rating sima and the dispedge show why the finishest of tooth chischmarks in a few places. Point chisch was used a the small exchange between the two. The underside contains more tooth chisch prants than the exposed free of the monthing, with some even within the casettes.



k 0.14 × 0.22 × 0.14 ×



3.5

-10 1 +19 LS

AT 127

GERALDINE DOBOS

6 July 2012

Pediment Gaison

\* Check for photos

\* resting our face. - lateral. - horizontal.