


June 23, 2017



PSLC King County 2016-2017 LiDAR

Final Technical Data Report



Puget Sound Regional Council

Andy Norton

Puget Sound LiDAR Consortium 1011 Western Avenue, Suite 500 Seattle, WA 98104 PH: 206-971-3283



QSI Corvallis

517 SW 2nd St., Suite 400 Corvallis, OR 97333 PH: 541-752-1204

TABLE OF CONTENTS

Introduction	5
Deliverable Products	6
Acquisition	8
Planning	8
Airborne LiDAR Survey	8
Ground Control	10
Monumentation	10
Ground Survey Points (GSPs)	12
Processing	15
LiDAR Data	15
RESULTS & DISCUSSION	17
LiDAR Density	17
LiDAR Accuracy Assessments	18
Cumulative LiDAR Absolute Accuracy	18
Cumulative LiDAR Relative Vertical Accuracy	20
GLOSSARY	21
APPENDIX A - ACCURACY CONTROLS	22
Appendix B – Individual Delivery Results	23
LiDAR First Return and Ground Classified Density Results	23
LiDAR Absolute Accuracy Results	29
LiDAR Relative Vertical Accuracy Results	35

Cover Photo: A view looking east near Granite Mountain in the King County project area. The image was created from the LiDAR bare earth model, overlaid with the 3D point cloud, and colored by NAIP imagery.

Introduction

This photo taken by QSI acquisition staff shows static GNSS equipment set up over monument PSLC_KNG_04 inside the PSLC King County site in Washington.



In February 2016, Quantum Spatial (QSI) was contracted by the Puget Sound LiDAR Consortium (PSLC) in association with the Kitsap County Department of Emergency Management to collect Light Detection and Ranging (LiDAR) data in 2016 and 2017 for the PSLC King County sites in Washington. Data were collected to aid PSLC in assessing the topographic and geophysical properties of the study area to support a variety of tasks including municipal planning, change detection and geomorphic mapping, and hazard mitigation.

This report accompanies the King County Delivery 4, Block 2 LiDAR data, the final delivery of the PSLC King County LiDAR dataset, and documents contract specifications, data acquisition procedures, processing methods, and analysis including LiDAR accuracy and density for the project in its entirety. Acquisition dates and acreage by delivery are shown in Table 1, a complete list of contracted deliverables provided to PSLC is shown in Table 2, and the project extent is shown in Figure 1.

Table 1: Acquisition dates, acreage, and data types collected for the King County deliveries

Project Site	Contracted Acres	Buffered Acres	Acquisition Dates	Data Type
Delivery 1	180,108	185,031	02/24/2016 - 02/26/2016, 03/02/2016, 03/05/2016, 03/08/2016, 03/11/2016, 03/18/2016, 03/19/2016, and 03/28/2016	LiDAR
Delivery 2	118,589	121,690	02/25/2016, 03/08/2016, 03/11/2016, 03/18/2016, 03/19/2016, 03/28/2016	LiDAR
Delivery 3	181,919	184,695	03/02/2016, 03/05/2016, 03/11/2016, 03/17/2016, 03/19/2016, 03/26/2016, 03/29/2016	LiDAR
Delivery 4 - Block 1	93,671	98,769	03/26/2016, 03/30/2016, 08/13/2016 – 08/21/2016, 08/25/2016 – 08/27/2016	LiDAR
Delivery 4 - Block 2	129,774	135,742	03/17/2016, 03/26/2016, 03/29/2016, 08/19/2016, 08/20/2016, 08/24/2016 – 08/26/2016, 08/28/2016, 04/21/2017, 05/09/2017, 05/25/2017	LiDAR

Deliverable Products

Table 2: Products delivered to PSLC for the King County sites

King County LiDAR Products Projection: Washington State Plane North Horizontal Datum: NAD83 (HARN)* Vertical Datum: NAVD88 (GEOID03) Units: US Survey Feet		
Points	 LAS v 1.2 All Returns Comma Delimited ASCII Files All Returns (*asc) Ground Returns (*gnd) 	
Rasters	 3 Foot ESRI Floating Point Grid Bare Earth Model Highest Hit Model 1.5 Foot GeoTiffs Normalized Intensity Images 	
Vectors	Shapefiles (*.shp) Site Boundary LiDAR Tile Index DEM Tile Index Ground Control and Check Points Ground Control Monuments Smooth Best Estimate Trajectory (SBETs)	

^{*}The data were created in NAD83 (CORS96), but for GIS purposes are defined as NAD83 (HARN) as per PSLC specifications.




Figure 1: Location map of the King County site in Washington

Acquisition

QSI's Cessna Caravan



Planning

In preparation for data collection, QSI reviewed the project area and developed a specialized flight plans to ensure complete coverage of the King County LiDAR study area at the target point density of ≥8.0 points/m² (0.74 points/ft²). Acquisition parameters including orientation relative to terrain, flight altitude, pulse rate, scan angle, and ground speed were adapted to optimize flight paths and flight times while meeting all contract specifications.

Factors such as satellite constellation availability and weather windows must be considered during the planning stage. Any weather hazards or conditions affecting the flights were continuously monitored due to their potential impact on the daily success of airborne and ground operations. In addition, logistical considerations including private property access and potential air space restrictions were reviewed.

Airborne LiDAR Survey

The LiDAR survey was accomplished using both a Leica ALS70 (Service Pack 2) and ALS80 system mounted in a Cessna Caravan. Table 3 summarizes the settings used to yield an average pulse density of ≥8 pulses/m² (0.74 pulses/ft²) over the King County project areas. Both laser systems can record unlimited range measurements (returns) per pulse. It is not uncommon for some types of surfaces (e.g., dense vegetation or water) to return fewer pulses to the LiDAR sensor than the laser originally emitted. The discrepancy between first return and overall delivered density will vary depending on terrain, land cover, and the prevalence of water bodies. All discernible laser returns were processed for the output dataset.

Table 3: LiDAR specifications and survey settings for the King County LIDAR Acquisition

LiDAR Survey Settings & Specifications					
Acquisition Dates	03/08/2016, 03/11/2016, 03/19/2016, 03/26/2016, 03/30/2016	02/24/2016- 02/26/2016, 03/02/2016, 03/05/2016, 03/17/2016, 03/18/2016, 03/28/2016, 03/29/2016, 08/20/2016, 08/24/2016 - 08/26/2016, 08/28/2016, 04/21/2017, 05/09/2017,	08/13/2016, 08/14/2016, 08/21/2016	08/14/2016, 08/15/2016, 08/16/2016, 08/17/2016, 8/18/2016, 8/19/2016, 8/20/2016,	08/25/2016, 08/26/2016, 8/27/2016
Aircraft Used	Cessna Caravan 208B	Cessna Caravan 208B	Cessna Caravan 208B	Cessna Caravan 208B	Cessna Caravan 208B
Sensor	Leica ALS80	Leica ALS80	Leica ALS80	Leica ALS70 Service Pack 2	Leica ALS70 Service Pack 2
Survey Altitude (AGL)	1200 m	1600 m	1450 m	1450 m	1650 m
Swath Width	874 m	857 m	777 m	777 m	701 m
Target Pulse Rate	400 kHz	340 kHz	190.8 kHz	192.6 kHz	340 kHz
Pulse Mode	Multi Pulse in Air (MPiA)	Multi Pulse in Air (MPiA)	Single Pulse in Air (SPiA)	Single Pulse in Air (SPiA)	Single Pulse in Air (SPiA)
Laser Pulse Diameter	26 cm	35 cm	31.9 cm	31.9 cm	36.3 cm
Mirror Scan Rate	50Hz/53 Hz	53 Hz	53.4 Hz	53.6 Hz	53.2 Hz
Field of View	40°	30°	30°	30°	24°
GPS Baselines	≤13 nm	≤13 nm	≤13 nm	≤13 nm	≤13 nm
GPS PDOP	≤3.0	≤3.0	≤3.0	≤3.0	≤3.0
GPS Satellite Constellation	≥6	≥6	≥6	≥6	≥6
Maximum Returns	Unlimited	Unlimited	Unlimited	Unlimited	Unlimited
Intensity	8-bit	8-bit	8-bit	8-bit	8-bit
Resolution/Den sity	Average 8 pulses/m ²	Average 8 pulses/m ²	Average 8 pulses/m ²	Average 8 pulses/m ²	Average 8 pulses/m ²
Accuracy	$RMSE_z \le 15 cm$	$RMSE_z \le 15 cm$	$RMSE_Z \le 15 cm$	$RMSE_Z \le 15 cm$	RMSE _z ≤ 15 cm

All areas were surveyed with an opposing flight line side-lap of ≥63% (≥100% overlap) in order to reduce laser shadowing and increase surface laser painting. To accurately solve for laser point position (geographic coordinates x, y and z), the positional coordinates of the airborne sensor and the attitude of the aircraft were recorded continuously throughout the LiDAR data collection mission. Position of the aircraft was measured twice per second (2 Hz) by an onboard differential GPS unit, and aircraft attitude was measured 200 times per second (200 Hz) as pitch, roll and yaw (heading) from an onboard inertial measurement unit (IMU). To allow for post-processing correction and calibration, aircraft and sensor position and attitude data are indexed by GPS time.

Ground Control

Ground control surveys, including monumentation and ground survey points (GSPs), were conducted to support the airborne acquisition. Ground control data were used to geospatially correct the aircraft positional coordinate data and to perform quality assurance checks on final LiDAR data.

QSI-Established Monument

Monumentation

The spatial configuration of ground survey monuments and utilized CORS stations provided redundant control within 13 nautical miles of the PSLC KNG 16 mission areas for LiDAR flights. Monuments were also used for collection of ground survey points using real time kinematic (RTK) and post processed kinematic (PPK) survey techniques.

Monument locations were selected with consideration for satellite visibility, field crew safety, and optimal location for GSP coverage. QSI established 16 new monuments and utilized 14 existing monuments for the King County LiDAR project area (Table 4, Figure 2). New monumentation was set using 5/8" x 30" rebar topped with stamped 2 1/2" aluminum caps). QSI also utilized coordinates from one Washington State Reference Network (WSRN) station within the project area to provide additional control (Table 6).

Table 4: Monuments used for the King County LiDAR acquisitions. Coordinates are on the NAD83 (HARN) datum

Monument ID	Latitude	Longitude	Ellipsoid (meters)
CEDAR_9	47° 48' 30.30271"	-121° 59' 57.61062"	-11.421
CEDAR_12	47° 19' 50.83444"	-121° 54' 15.83024"	237.535
KCJJ_01	47° 17' 01.32634"	-122° 03' 10.77785"	31.851
KCJJ_02	47° 35' 09.70140"	-121° 57' 15.17980"	11.943
KING_CO_RM	47° 19' 15.53516"	-121° 54' 28.06793"	207.9475
KNG_09	47° 42' 40.43164"	-121° 20' 27.14593"	281.095
KNG_11	47° 20' 23.65277"	-122° 12' 27.27308"	-5.038
KNG_16	47° 28' 08.78000"	-121° 42' 57.48000"	60.916

Monument ID	Latitude	Longitude	Ellipsoid (meters)
KNG_CO_01	47° 24' 42.01975"	-122° 16' 37.11827"	-12.535
KNG_CO_NEAL	47° 34' 12.84977"	-121° 53' 15.65745"	6.457
MGRC_SOOS_01	47° 19' 44.52155"	-122° 09' 54.37518"	127.153
PSLC_KNG_01	47° 46' 22.86514"	-121° 29' 09.79972"	212.816
PSLC_KNG_02B	47° 44' 51.59788"	-121° 05' 14.09694"	1215.455
PSLC_KNG_03	47° 25' 19.70000"	-121° 37' 45.10000"	618.345
PSLC_KNG_04R	47° 25' 32.58441"	-121° 25' 00.08129"	890.344
PSLC_KNG_05	47° 09' 16.96698"	-121° 34' 22.31206"	1320.272
PSLC_KNG_06	47° 09' 53.15612"	-121° 44' 42.66633"	437.461
PSLC_KNG_07	47° 40' 08.43367"	-122° 04' 44.58168"	-2.920
PSLC_KNG_08	47° 39' 37.71847"	-122° 06' 25.05828"	-11.009
PSLC_KNG_09	47° 36' 02.74424"	-122° 17' 07.36536"	-14.428
PSLC_KNG_10	47° 35' 32.19072"	-122° 18' 12.28435"	27.116
PSLC_KNG_11	47° 38' 28.04519"	-122° 18' 40.28866"	-15.545
PSLC_KNG_12	47° 38' 48.10630"	-122° 20' 17.49197"	-13.211
PSLC_KNG_13	47° 35' 31.59330"	-121° 57' 30.81496"	8.390
PSLC_KNG_14	47° 27' 49.89049"	-122° 29' 32.44791"	45.903
PSLC_KNG_15	47° 24' 24.79988"	-122° 19' 21.88588"	21.086
PSLC_KNG_16	47° 50' 20.37391"	-122° 12' 54.69201"	60.916
SX1472	47° 31' 10.05371"	-121° 48' 00.45212"	108.367
SY0513	47° 20' 43.06372"	-122° 07' 15.11845"	82.180

To correct the continuously recorded onboard measurements of the aircraft position, QSI concurrently conducted multiple static Global Navigation Satellite System (GNSS) ground surveys (1 Hz recording frequency) over each monument. During post-processing, the static GPS data were triangulated with nearby Continuously Operating Reference Stations (CORS) using the Online Positioning User Service (OPUS¹) for precise positioning. Multiple independent sessions over the same monument were processed to confirm antenna height measurements and to refine position accuracy.

Monuments were established according to the national standard for geodetic control networks, as specified in the Federal Geographic Data Committee (FGDC) Geospatial Positioning Accuracy Standards for geodetic networks.² This standard provides guidelines for classification of monument quality at the 95% confidence interval as a basis for comparing the quality of one control network to another. The monument rating for this project is shown in Table 5.

Table 5: Federal Geographic Data Committee monument rating for network accuracy

Direction	Rating
1.96 * St Dev _{NE} :	0.020 m
1.96 * St Dev _z :	0.050 m

For the King County LiDAR project area, the monument coordinates contributed no more than 5.4 cm of positional error to the geolocation of the final ground survey points and LiDAR, with 95% confidence.

Table 6: WSRN station utilized for the King County acquisitions. Coordinates are on the NAD83 (HARN) datum

Station ID	Latitude	Longitude	Ellipsoid (meters)
NINT	47° 29' 42.33526"	-121° 47' 49.44545"	127.615

Ground Survey Points (GSPs)

Ground survey points were collected using real time kinematic and post-processed kinematic (PPK) survey techniques. A Trimble R7 base unit was positioned at a nearby monument to broadcast kinematic corrections to roving Trimble R6 or Trimble R8 GNSS receiver. All GSP measurements were made during periods with a Position Dilution of Precision (PDOP) of \leq 3.0 with at least six satellites in view of the stationary and roving receivers. When collecting RTK and PPK data, the rover records data while stationary for five seconds, then calculates the pseudorange position using at least three one-second epochs. Relative errors for any GSP position must be less than 1.5 cm horizontal and 2.0 cm vertical in order to be accepted. See Table 7 for Trimble unit specifications.

¹ OPUS is a free service provided by the National Geodetic Survey to process corrected monument positions. http://www.ngs.noaa.gov/OPUS.

² Federal Geographic Data Committee, Geospatial Positioning Accuracy Standards (FGDC-STD-007.2-1998). Part 2: Standards for Geodetic Networks, Table 2.1, page 2-3. http://www.fgdc.gov/standards/projects/FGDC-standards-projects/accuracy/part2/chapter2

GSPs were collected in areas where good satellite visibility was achieved on paved roads and other hard surfaces such as gravel or packed dirt roads. GSP measurements were not taken on highly reflective surfaces such as center line stripes or lane markings on roads due to the increased noise seen in the laser returns over these surfaces. GSPs were collected within as many flightlines as possible; however, the distribution of GSPs depended on ground access constraints and monument locations and may not be equitably distributed throughout the study area (Figure 2).

Table 7: Trimble equipment identification

Receiver Model	Antenna	OPUS Antenna ID	Use
Trimble R6	Integrated GNSS Antenna R6	TRM_R6	Rover
Trimble R7	Zephyr GNSS Geodetic Model 2 RoHS	TRM57971.00	Static
Trimble R8 GNSS	Integrated Antenna R8 Model 2	TRM_R8_GNSS	Static, Rover




Figure 2: PSLC King County LiDAR ground survey location map

PROCESSING



LiDAR Data

Upon completion of data acquisition, QSI processing staff initiated a suite of automated and manual techniques to process the data into the requested deliverables. Processing tasks included GPS control computations, smoothed best estimate trajectory (SBET) calculations, kinematic corrections, calculation of laser point position, sensor and data calibration for optimal relative and absolute accuracy, and LiDAR point classification (Table 8). Processing methodologies were tailored for the landscape. Brief descriptions of these tasks are shown in Table 9.


Table 8: ASPRS LAS classification standards applied to the King County dataset

Classification Number	Classification Name	Classification Description
1	Default/Unclassified	Laser returns that are not included in the ground class, composed of vegetation and human-made structures
2	Ground	Laser returns that are determined to be ground using automated and manual cleaning algorithms

Table 9: LiDAR processing workflow

LiDAR Processing Step	Software Used
Resolve kinematic corrections for aircraft position data using kinematic aircraft GPS and static ground GPS data. Develop a smoothed best estimate of trajectory (SBET) file that blends post-processed aircraft position with sensor head position and attitude recorded throughout the survey.	Waypoint Inertial Explorer v.8.6
Calculate laser point position by associating SBET position to each laser point return time, scan angle, intensity, etc. Create raw laser point cloud data for the entire survey in *.las (ASPRS v. 1.2) format. Convert data to orthometric elevations by applying a geoid correction.	Waypoint Inertial Explorer v.8.6 Leica Cloudpro v. 1.2.2
Import raw laser points into manageable blocks to perform manual relative accuracy calibration and filter erroneous points. Classify ground points for individual flight lines.	TerraScan v.17
Using ground classified points per each flight line, test the relative accuracy. Perform automated line-to-line calibrations for system attitude parameters (pitch, roll, heading), mirror flex (scale) and GPS/IMU drift. Calculate calibrations on ground classified points from paired flight lines and apply results to all points in a flight line. Use every flight line for relative accuracy calibration.	TerraMatch v.17
Classify resulting data to ground and other client designated ASPRS classifications (Table 8). Assess statistical absolute accuracy via direct comparisons of ground classified points to ground control survey data.	TerraScan v.17 TerraModeler v.17
Generate bare earth models as triangulated surfaces. Generate highest hit models as a surface expression of all classified points. Export all surface models as ESRI GRIDs format at a 3 foot pixel resolution.	TerraScan v.17 TerraModeler v.17 ArcMap v. 10.2.2
Export intensity images as GeoTIFFs at a 1.5 foot pixel resolution.	Las Monkey (QSI proprietary) LAS Product Creator (QSI proprietary) TerraScan v.17 TerraModeler v.17 ArcMap v. 10.2.2

RESULTS & DISCUSSION



LiDAR Density

The acquisition parameters were designed to acquire an average first-return density of 0.74 points/ft² (8.0 points/m²). First return density describes the density of pulses emitted from the laser that return at least one echo to the system. Multiple returns from a single pulse were not considered in first return density analysis. Some types of surfaces (e.g., breaks in terrain, water and steep slopes) may have returned fewer pulses than originally emitted by the laser. First returns typically reflect off the highest feature on the landscape within the footprint of the pulse. In forested or urban areas the highest feature could be a tree, building or power line, while in areas of unobstructed ground, the first return will be the only echo and represents the bare earth surface.

The density of ground-classified LiDAR returns was also analyzed for this project. Terrain character, land cover, and ground surface reflectivity all influenced the density of ground surface returns. In vegetated areas, fewer pulses may penetrate the canopy, resulting in lower ground density.

The average first-return density of LiDAR data for the King County project area was 1.40 points/ft² (15.02 points/m²) while the average ground classified density was 0.20 points/ft² (2.20 points/m²) (Table 10). Individual delivery area density statistics are documented in Appendix B (Table 13, Figure 8 through Figure 17).

Table 10: Cumulative average LiDAR point densities

Classification	Point Density
First-Return	1.40 points/ft ² 15.02 points/m ²
Ground Classified	0.20 points/ft ² 2.20 points/m ²

LiDAR Accuracy Assessments

The accuracy of the LiDAR data collection can be described in terms of absolute accuracy (the consistency of the data with external data sources) and relative accuracy (the consistency of the dataset with itself). See Appendix A for further information on sources of error and operational measures used to improve relative accuracy.

Cumulative LiDAR Absolute Accuracy

Absolute accuracy was assessed using Non-Vegetated Vertical Accuracy (NVA) reporting designed to meet guidelines presented in the FGDC National Standard for Spatial Data Accuracy³. NVA compares known ground quality assurance point data collected on open, bare earth surfaces with level slope (<20°) to the triangulated surface generated by the LiDAR points. NVA is a measure of the accuracy of LiDAR point data in open areas where the LiDAR system has a high probability of measuring the ground surface and is evaluated at the 95% confidence interval (1.96 * RMSE), as shown in Table 11. The absolute accuracy statistics for the individual King County deliveries are documented in Appendix B (Table 14 and Table 15, Figure 18 through Figure 27).


The mean and standard deviation (sigma σ) of divergence of the ground surface model from quality assurance point coordinates are also considered during accuracy assessment. These statistics assume the error for x, y and z is normally distributed, and therefore the skew and kurtosis of distributions are also considered when evaluating error statistics. For the King County survey area, 217 quality assurance points were withheld in total resulting in a non-vegetated vertical accuracy of 0.204 feet (0.062 meters) (Figure 5).

QSI also assessed absolute accuracy using 4046 ground control points. Although these points were used in the calibration and post-processing of the LiDAR point cloud, they may still provide a good indication of the overall accuracy of the LiDAR dataset, and therefore have been provided in Table 11 and Figure 6.

Table 11: Cumulative absolute accuracy results


Cumulative Absolute Accuracy					
	Quality Assurance Points (NVA)	Ground Control Points			
Sample	217 points	4046 points			
NVA (1.96*RMSE)	0.204 ft	0.198 ft			
NVA (1.96 · KIVISE)	0.062 m	0.060 m			
Average	-0.040 ft	-0.041 ft			
Average	-0.012 m	-0.013 m			
Median	-0.027 ft	-0.036 ft			
Wedian	-0.008 m	-0.11 m			
RMSE	0.104 ft	0.101 ft			
KIVISE	0.032m	0.031 m			
Standard Deviation (1σ)	0.096 ft	0.092 ft			
Standard Deviation (10)	0.029 m	0.028 m			

³ Federal Geographic Data Committee, ASPRS POSITIONAL ACCURACY STANDARDS FOR DIGITAL GEOSPATIAL DATA EDITION 1, Version 1.0, NOVEMBER 2014. http://www.asprs.org/PAD-Division/ASPRS-POSITIONAL-ACCURACY-STANDARDS-FOR-DIGITAL-GEOSPATIAL-DATA.html.



Cumulative PSLC King County LiDAR Non-Vegetated Vertical Accuracy LiDAR Surface Deviation from Survey (ft)

Figure 5: Frequency histogram for LiDAR surface deviation from quality assurance point values



LiDAR Surface Deviation from Ground Control Survey (ft)

Figure 6: Frequency histogram for LiDAR surface deviation from ground control point values

Cumulative LiDAR Relative Vertical Accuracy

Relative vertical accuracy refers to the internal consistency of the data set as a whole: the ability to place an object in the same location given multiple flight lines, GPS conditions, and aircraft attitudes. When the LiDAR system is well calibrated, the swath-to-swath vertical divergence is low (<0.10 meters). The relative vertical accuracy was computed by comparing the ground surface model of each individual flight line with its neighbors in overlapping regions. The average (mean) line to line relative vertical accuracy for the King County LiDAR project area is 0.153 feet (0.047 meters) (Table 12, Figure 7). The relative vertical accuracy statistics for the individual King County LiDAR delivery areas are documented in Appendix B (Table 16, Figure 28 through Figure 32).

Table 12: Cumulative King County LiDAR relative accuracy results

Cumulative Relative Accuracy				
Sample	1,111 surfaces			
Average	0.135 ft 0.041 m			
Median	0.205 ft 0.062 m			
RMSE	0.224 ft 0.068 m			
Standard Deviation (1σ)	0.091 ft 0.028 m			
1.96σ	0.178 ft 0.054 m			




Figure 7: Cumulative frequency plot for the PSLC King County LiDAR area relative vertical accuracy between flight lines

GLOSSARY

<u>1-sigma (σ) Absolute Deviation</u>: Value for which the data are within one standard deviation (approximately 68th percentile) of a normally distributed data set.

1.96 * RMSE Absolute Deviation: Value for which the data are within two standard deviations (approximately 95th percentile) of a normally distributed data set, based on the FGDC standards for Non-vegetated Vertical Accuracy (NVA) reporting.

Accuracy: The statistical comparison between known (surveyed) points and laser points. Typically measured as the standard deviation (sigma σ) and root mean square error (RMSE).

Absolute Accuracy: The vertical accuracy of LiDAR data is described as the mean and standard deviation (sigma σ) of divergence of LiDAR point coordinates from ground survey point coordinates. To provide a sense of the model predictive power of the dataset, the root mean square error (RMSE) for vertical accuracy is also provided. These statistics assume the error distributions for x, y and z are normally distributed, and thus we also consider the skew and kurtosis of distributions when evaluating error statistics.

Relative Accuracy: Relative accuracy refers to the internal consistency of the data set; i.e., the ability to place a laser point in the same location over multiple flight lines, GPS conditions and aircraft attitudes. Affected by system attitude offsets, scale and GPS/IMU drift, internal consistency is measured as the divergence between points from different flight lines within an overlapping area. Divergence is most apparent when flight lines are opposing. When the LiDAR system is well calibrated, the line-to-line divergence is low (<10 cm).

Root Mean Square Error (RMSE): A statistic used to approximate the difference between real-world points and the LiDAR points. It is calculated by squaring all the values, then taking the average of the squares and taking the square root of the average.

Data Density: A common measure of LiDAR resolution, measured as points per square meter.

<u>Digital Elevation Model (DEM)</u>: File or database made from surveyed points, containing elevation points over a contiguous area. Digital terrain models (DTM) and digital surface models (DSM) are types of DEMs. DTMs consist solely of the bare earth surface (ground points), while DSMs include information about all surfaces, including vegetation and man-made structures.

Intensity Values: The peak power ratio of the laser return to the emitted laser, calculated as a function of surface reflectivity.

Nadir: A single point or locus of points on the surface of the earth directly below a sensor as it progresses along its flight line.

<u>Overlap</u>: The area shared between flight lines, typically measured in percent. 100% overlap is essential to ensure complete coverage and reduce laser shadows.

<u>Pulse Rate (PR)</u>: The rate at which laser pulses are emitted from the sensor; typically measured in thousands of pulses per second (kHz).

<u>Pulse Returns</u>: For every laser pulse emitted, the number of wave forms (i.e., echos) reflected back to the sensor. Portions of the wave form that return first are the highest element in multi-tiered surfaces such as vegetation. Portions of the wave form that return last are the lowest element in multi-tiered surfaces.

<u>Real-Time Kinematic (RTK) Survey</u>: A type of surveying conducted with a GPS base station deployed over a known monument with a radio connection to a GPS rover. Both the base station and rover receive differential GPS data and the baseline correction is solved between the two. This type of ground survey is accurate to 1.5 cm or less.

<u>Post-Processed Kinematic (PPK) Survey</u>: GPS surveying is conducted with a GPS rover collecting concurrently with a GPS base station set up over a known monument. Differential corrections and precisions for the GNSS baselines are computed and applied after the fact during processing. This type of ground survey is accurate to 1.5 cm or less.

<u>Scan Angle</u>: The angle from nadir to the edge of the scan, measured in degrees. Laser point accuracy typically decreases as scan angles increase.

Native LiDAR Density: The number of pulses emitted by the LiDAR system, commonly expressed as pulses per square meter.

APPENDIX A - ACCURACY CONTROLS

Relative Accuracy Calibration Methodology:

Manual System Calibration: Calibration procedures for each mission require solving geometric relationships that relate measured swath-to-swath deviations to misalignments of system attitude parameters. Corrected scale, pitch, roll and heading offsets were calculated and applied to resolve misalignments. The raw divergence between lines was computed after the manual calibration was completed and reported for each survey area.

<u>Automated Attitude Calibration</u>: All data were tested and calibrated using TerraMatch automated sampling routines. Ground points were classified for each individual flight line and used for line-to-line testing. System misalignment offsets (pitch, roll and heading) and scale were solved for each individual mission and applied to respective mission datasets. The data from each mission were then blended when imported together to form the entire area of interest.

<u>Automated Z Calibration</u>: Ground points per line were used to calculate the vertical divergence between lines caused by vertical GPS drift. Automated Z calibration was the final step employed for relative accuracy calibration.

LiDAR accuracy error sources and solutions:

Type of Error	Source	Post Processing Solution
GPS	Long Base Lines	None
(Static/Kinematic)	Poor Satellite Constellation	None
	Poor Antenna Visibility	Reduce Visibility Mask
Relative Accuracy	Poor System Calibration	Recalibrate IMU and sensor offsets/settings
	Inaccurate System	None
Laser Noise	Poor Laser Timing	None
	Poor Laser Reception	None
	Poor Laser Power	None
	Irregular Laser Shape	None

Operational measures taken to improve relative accuracy:

<u>Low Flight Altitude</u>: Terrain following was employed to maintain a constant above ground level (AGL). Laser horizontal errors are a function of flight altitude above ground (about 1/3000th AGL flight altitude).

<u>Focus Laser Power at narrow beam footprint</u>: A laser return must be received by the system above a power threshold to accurately record a measurement. The strength of the laser return (i.e., intensity) is a function of laser emission power, laser footprint, flight altitude and the reflectivity of the target. While surface reflectivity cannot be controlled, laser power can be increased and low flight altitudes can be maintained.

Reduced Scan Angle: Edge-of-scan data can become inaccurate. The scan angle was reduced to a maximum of $\pm 15^{\circ}$ from nadir, creating a narrow swath width and greatly reducing laser shadows from trees and buildings.

Quality GPS: Flights took place during optimal GPS conditions (e.g., 6 or more satellites and PDOP [Position Dilution of Precision] less than 3.0). Before each flight, the PDOP was determined for the survey day. During all flight times, a dual frequency DGPS base station recording at 1 second epochs was utilized and a maximum baseline length between the aircraft and the control points was less than 13 nm at all times.

<u>Ground Survey</u>: Ground survey point accuracy (<1.5 cm RMSE) occurs during optimal PDOP ranges and targets a minimal baseline distance of 4 miles between GPS rover and base. Robust statistics are, in part, a function of sample size (n) and distribution. Ground survey points are distributed to the extent possible throughout multiple flight lines and across the survey area.

50% Side-Lap (100% Overlap): Overlapping areas are optimized for relative accuracy testing. Laser shadowing is minimized to help increase target acquisition from multiple scan angles. Ideally, with a 50% side-lap, the nadir portion of one flight line coincides with the swath edge portion of overlapping flight lines. A minimum of 50% side-lap with terrain-followed acquisition prevents data gaps.


Opposing Flight Lines: All overlapping flight lines have opposing directions. Pitch, roll and heading errors are amplified by a factor of two relative to the adjacent flight line(s), making misalignments easier to detect and resolve.

APPENDIX B — INDIVIDUAL DELIVERY RESULTS

LiDAR First Return and Ground Classified Density Results


Table 13: King County LiDAR point densities by delivery

Classification			Point Density		
	Delivery 1	Delivery 2	Delivery 3	Delivery 4 – Block 1	Delivery 4 – Block 2
First-Return	1.07 points/ft ² 11.51 points/m ²	1.13 points/ft ² 12.20 points/m ²	1.29 points/ft ² 13.91 points/m ²	2.38 points/ft2 25.57 points/m2	1.50 points/ft ² 16.17 points/m ²
Ground Classified	0.24 points/ft ² 2.61 points/m ²	0.24 points/ft ² 2.58 points/m ²	0.23 points/ft ² 2.46 points/m ²	0.12 points/ft2 1.34 points/m2	0.14 points/ft ² 1.56 points/m ²




King County Delivery 1 First Return Point Density Value (points/ft²)

Figure 8: Frequency distribution of Delivery 1 first return point density values per 100 ft x 100 ft cell



King County Delivery 1 Ground Classified Return Point Density Value (points/ft²)

Figure 9: Frequency distribution of Delivery 1 ground classified point density values per 100 ft x 100 ft cell



King County Delivery 2 First Return Point Density Value (points/ft²)

Figure 10: Frequency distribution of Delivery 2 first return point density values per 100 ft x 100 ft cell




Figure 11: Frequency distribution of Delivery 2 ground classified point density values per 100 ft x 100 ft cell




Figure 12: Frequency distribution of Delivery 3 first return point density values per 100 ft x 100 ft cell




Figure 13: Frequency distribution of Delivery 3 ground classified point density values per 100 ft x 100 ft cell




Figure 14: Frequency distribution of Delivery 4 – Block 1 first return point density values per 100 ft x 100 ft cell




Figure 15: Frequency distribution of Delivery 4 – Block 1 ground classified point density values per 100 ft x 100 ft cell





Figure 16: Frequency distribution of Delivery 4 – Block 2 first return point density values per 100 ft x 100 ft cell

(points/ft2)



King County Delivery 4 - Block 2 Ground Classified Return Point Density Value (points/ft²)

Figure 17: Frequency distribution of Delivery 4 – Block 2 ground classified point density values per 100 ft x 100 ft cell


LiDAR Absolute Accuracy Results

Table 14: King County Quality Assurance Points Absolute Accuracies by Delivery

King County Absolute Accuracies						
	Delivery 1 Quality Assurance Points (NVA)	Delivery 2 Quality Assurance Points (NVA)	Delivery 3 Quality Assurance Points (NVA)	Delivery 4- Block 1 Quality Assurance Points (NVA)	Delivery 4- Block 2 Quality Assurance Points (NVA)	
Sample	20 points	43 points	35 points	66 points	53 points	
NVA (1.96*RMSE)	0.172 ft	0.260 ft	0.154 ft	0.217 ft	0.174 ft	
	0.052 m	0.079 m	0.047 m	0.066 m	0.053 m	
Average	-0.030 ft	-0.089 ft	-0.030 ft	-0.025 ft	-0.031 ft	
	-0.009 m	-0.027 m	-0.009 m	-0.008 m	-0.009 m	
Median	-0.015 ft	-0.075 ft	-0.036 ft	-0.008 ft	-0.020 ft	
	-0.004 m	-0.023 m	-0.011 m	-0.003 m	-0.006 m	
RMSE	0.088 ft	0.133 ft	0.079 ft	0.110 ft	0.089 ft	
	0.027 m	0.040 m	0.024 m	0.034 m	0.027 m	
Standard	0.166 ft	0.100 ft	0.074 ft	0.108 ft	0.084 ft	
Deviation (1σ)	0.051 m	0.030 m	0.022 m	0.033 m	0.026 m	


Table 15: King County Ground Control Points Absolute Accuracies by Delivery

King County Absolute Accuracies					
	Delivery 1 Ground Control Points	Delivery 2 Ground Control Points	Delivery 3 Ground Control Points	Delivery 4 – Block 1 Ground Control Points	Delivery 4 – Block 2 Ground Control Points
Sample	379 points	784 points	673 points	1245 points	965 points
1.96*RMSE	0.199 ft	0.258 ft	0.162 ft	0.200 ft	0.156 ft
	0.061 m	0.079 m	0.049 m	0.061 m	0.048 m
Average	-0.055 ft	-0.071 ft	-0.043 ft	-0.024 ft	-0.033 ft
	-0.017 m	-0.022 m	-0.013 m	-0.007 m	-0.010 m
Median	-0.064 ft	-0.060 ft	-0.043 ft	-0.020 ft	-0.026 ft
	-0.020 m	-0.018 m	-0.013 m	-0.006 m	-0.008 m
RMSE	0.102 ft	0.132 ft	0.083 ft	0.102 ft	0.080 ft
	0.031 m	0.040 m	0.025 m	0.031 m	0.024 m
Standard	0.168 ft	0.111 ft	0.071 ft	0.099 ft	0.073 ft
Deviation (1σ)	0.051 m	0.034 m	0.022 m	0.030 m	0.022 m




PSLC King County Delivery 1 Non-Vegetated Vertical Accuracy LiDAR Surface Deviation from Survey (ft)

Figure 18: Frequency histogram for LiDAR surface deviation from Delivery 1 quality assurance point values




PSLC King County Delivery 1 Absolute Accuracy LiDAR Surface Deviation from Survey (ft)

Figure 19: Frequency histogram for LiDAR surface deviation from Delivery 1 ground control point values




PSLC King County Delivery 2 Non-Vegetated Vertical Accuracy LiDAR Surface Deviation from Survey (ft)

Figure 20: Frequency histogram for LiDAR surface deviation from Delivery 2 quality assurance point values




PSLC King County Delivery 2 Absolute Accuracy LiDAR Surface Deviation from Survey (ft)

Figure 21: Frequency histogram for LiDAR surface deviation from Delivery 2 ground control point values




King County Delivery 3 Non-vegetated Vertical Accuracy (NVA)
LiDAR Surface Deviation from Survey (ft)

Figure 22: Frequency histogram for LiDAR surface deviation from Delivery 3 quality assurance point values



King County Delivery 3 Absolute Vertical Accuracy LiDAR Surface Deviation from Survey (ft)

Figure 23: Frequency histogram for LiDAR surface deviation from Delivery 3 ground control point values



King County Delivery 4, Block 1 Non-Vegetated Vertical Accuracy LiDAR Surface Deviation from Survey (ft)

Figure 24: Frequency histogram for LiDAR surface deviation from Delivery 4 – Block 1 quality assurance point values






Figure 25: Frequency histogram for LiDAR surface deviation from Delivery 4 – Block 1 ground control point values

LiDAR Surface Deviation from Ground Control Survey (ft)



King County Delivery 4 Block 2 Non-Vegetated Vertical Accuracy LiDAR Surface Deviation from Survey (ft)

Figure 26: Frequency histogram for LiDAR surface deviation from Delivery 4 – Block 2 quality assurance point values




King County Delivery 4 Block 2 Absolute Accuracy LiDAR Surface Deviation from Ground Control Survey (ft)

Figure 27: Frequency histogram for LiDAR surface deviation from Delivery 4 – Block 2 ground control point values

LiDAR Relative Vertical Accuracy Results


Table 16: King County Relative Accuracy Results by Delivery

King County Relative Accuracies						
	Delivery 1	Delivery 2	Delivery 3	Delivery 4 – Block 1	Delivery 4 – Block 2	
Sample	146 surfaces	113 surfaces	104 surfaces	434 surfaces	400 surfaces	
Average	0.103 ft	0.104 ft	0.114 ft	0.258 ft	0.153 ft	
	0.031 m	0.032 m	0.035 m	0.079 m	0.047 m	
Median	0.102 ft	0.102 ft	0.113 ft	0.268 ft	0.199 ft	
	0.031 m	0.031 m	0.035 m	0.082 m	0.061 m	
RMSE	0.113 ft	0.113 ft	0.124 ft	0.282 ft	0.209 ft	
	0.035 m	0.034 m	0.038 m	0.086 m	0.064 m	
Standard	0.029 ft	0.028 ft	0.025 ft	0.077 ft	0.073 ft	
Deviation (1σ)	0.009 m	0.009 m	0.008 m	0.023 m	0.022 m	
1.96σ	0.058 ft	0.055 ft	0.048 ft	0.151 ft	0.142 ft	
	0.018 m	0.017 m	0.015 m	0.046 m	0.043 m	



King County Delivery 1 Relative Vertical Accuracy (ft)
Total Compared Points (n = 9,350,619,644)

Figure 28: Frequency plot for the PSLC King County LiDAR project Delivery 1 area relative vertical accuracy between flight lines



King County Delivery 2 Relative Vertical Accuracy (ft)
Total Compared Points (n = 7,233,970,730)

Figure 29: Frequency plot for the PLSC King County project Delivery 2 area relative vertical accuracy between flight lines





Figure 30: Frequency plot for the PSLC King County LiDAR project Delivery 3 area relative vertical accuracy between flight lines



King County Delivery 4, Block 1 Relative Vertical Accuracy (ft)
Total Compared Points (n = 3,309,451,656)

Figure 31: Frequency plot for the PSLC King County LiDAR project Delivery 4 - Block 1 area relative vertical accuracy between flight lines




Figure 32: Frequency plot for the PSLC King County LiDAR project Delivery 4 - Block 2 area relative vertical accuracy between flight lines