

## M22B INY1

## 19/10/22 MAÑANA

		-Tol D	esviación +/-	
1,0000	1,0000	-0,6000	1,4430 🜑 📖	0,4430
	1,0000	1,0000 1,0000	1,0000 1,0000 -0,6000	1,0000 1,0000 -0,6000 1,4430 🛑 🖂 🔠


## NO SE PUEDE CAMBIAR EN MÁQUINA






	Name	Measured valueNomin	al value	+Tol	-Tol De	esviación +/-	
Δ	FP1SQ1	2,1756	0,0000	1,5000	0,0000	2,1756	0,6756
	forme flanc de palier 1 / ZYX						

SOLO SE PUEDE LIMPIAR ALUMINIO






## V1102SQG







Faltas material pieza:

Quitar material con piedra fina