

INY3 M25B

FALTA MATERIAL EN EL LAMADO

| 3072L2 | | | | -0.5512 |
|-------------------------------|----------|----------|----------|---------|
| 182.1488 loc face 3072 / X | 183.3000 | 183.9000 | 182.7000 | -1.1512 |
| | | | | |



CAMBIAR PIN



LIMPIAR ZONA DEL MOLDE

| 412 | 21SQ1 | | | 0.0034 |
|---------|----------------------------------|-----------|--------|---------|
| | 1.2034 | 0.0000 | 1.2000 | 1.2034 |
| X | -105.8293 | -105.8293 | | 0.0000 |
| γ | -95.8422 | -95.2668 | | -0.5754 |
| Z fo | -143.4823 ime face 4121 / ZYX | -143.6582 | | 0.1759 |

CAMBIAR PIN

| | 4140L2 | | | | 0.1186 |
|--------|------------------------------|---------|---------|---------|--------|
| \sim | 57.1186 loc fond 4140 / Y | 56.4000 | 57.0000 | 55.8000 | 0.7186 |

APORTAR MATERIAL AL MOLDE

