
INY3 M09B

REMIDO LA C100 PORQUE SALIA MAL LAA MEDICIO N EN LA MAQUINA 4



NO SE PUEDE CAMBIAR EN MAQUINA

Ø	5032ED1 11.2913 diam emb 5032 (12,07)	12.0700	12.2700	11.8700	-0.5787 -0.7787
Ф	5032EL1 1.6028 X 169.2138 Y -47.8446 loc emb 5032 / YX (12,07)	0.0000 170.0000 -48.0000	1.0000		0.6028 1.6028 -0.7862 0.1554
Ø	5032D1 8.8081 diam 5032 (8,81)	8.8100	9.0100	8.6100	-l -0.0019
Ф	5032L1 0.3060 X 170.0005 Y -47.8470 loc 5032 / YX (8,81)	0.0000 170.0000 -48.0000	1.0000		0.3060 0.0004 0.1530
Ø	5032D2 6.4377 diam 5032 (6,13)	6.1300	6.3300	5.9300	0.1077 0.3077
Ф	5032L2 1.6388 X 170.7556 Y 47.6830 loc 5032 / YX (6,13)	0.0000 170.0000 -48.0000	1.0000		0.6388 1.6388 0.7556 0.3170

SOLO SE PUEDE LIMPIAR ALUMINIO

FP:	3SQ4			0.2009
	1.0009	0.0000	0.8000	1.0009
X	-7.9910	-7.9910		0.0000
	-162.1303	-162.1259		-0.0044
Z fo	-11.3222 me flanc de palier 3 / 2	-10.8218		-0.5004