
M17B INY4

15/11/2022

Name	Measured valueNomin	al value	+Tol	-Tol	Desviación +/-	
_ 2024L3	79,9566	79,0000	0,9000	-0,6	000 0,9566 🔴 🗀 🖂	0,0566




NO SE PUEDE CAMBIAR EN MÁQUINA





	Name	Measured valueNomina	l value	+Tol	-Tol De	esviación +/-	
Φ	6031L1 loc 6031 / YX (8,23)	1,4728	0,0000	1,2000	0,0000	1,4728	0,2728
Φ	6031L2 loc 6031 / ZYX (6.84)	1,9214	0,0000	1,6000	0,0000	1,9214	0,3214


NO SE PUEDE CAMBIAR EN MÁQUINA


	Name	Measured valueNomina	value	+Tol	-Tol D	Desviación +/-	
Δ	3015SQ1	1,5395	0,0000	1,2000	0,0000	1,5395	0,3395
	forme face 3015 / X						













Faltas material pieza: SOLO SE PUEDE LIMPIAR ALUMINIO Exceso material pieza: NO TOCAR