

M21B INY7 21/10/22 MAÑANA

	Valor real	Valor nom.	Tol. inf.	Tol. sup.	Desviación		
807SQ1					0.4517		
	1.6517	0.0000	1.2000		1.6517		
X	98.2877	98.2661			0.0216		
Y	-178.5303	-179.3558			0.8256		
Z fo	78.7350 rme section 807 /ZYX	78.7350			0.0000		

807SQ1





Valor real Valor nom. Tol. inf. Tol. sup. Desulation 807SQ1 1.908 0.000 1.908 0.025 1.78.610 1.79.564 0.953 7.977 0.000

Exceso material pieza:

valor real (absoluto) menor que 179.564 (nominal)

Aportar material con Spark Depo Ej: 178.610 (valor absoluto)

Faltas material pieza:

valor real (absoluto) mayor que 179.564 (nominal)

Quitar material con piedra fina Ej: 180.015 (valor absoluto)

Name	Measured valueN	ominal value	+Tol	-Tol	Desviación +/-	
AV2L1Z	198,3944	199,0000	0,6000	-0,6000	-0,6056	-0,0056
AV2L1	1,2553	0,0000	1,2000	0,0000	1,2553	0,0553

NO SE PUEDE TOCAR