



Pure asbestos minerals — USGS splib07a (ASD, 2151 ch)




Asbestos-cement roof (modelled, Cilia 2015 mixing) vs roof confusers




What each sensor sees — signatures resampled with Gaussian SRF


SuperDove (8b VNIR)




Sentinel-2 (11b)



WV-3 SWIR (8b)



SAM separability: 'AC roof weathered' vs confusers (higher = more separable)



Mg-OH 2.31 μm feature — only asbestos-cement shows real depth
(seen by WV-3 SWIR S8; washed out by S2 B12, FWHM 175 nm; invisible to SuperDove)

