3:51 PM Mon 9 May

→ 57% ■




Photo:1	Date:06/16/2022	Location:WL: 1, FL: 18
Condition Description: BROKEN RAILING		Recommendation: REPLACE BROKEN RAILING
Causes: AGE & WEATHERING OR MECHANICAL IMPACT		Quantity: 87