
GY 3-7 source

First picture, upper panel: continuum maps

First picture, bottom panel: line fitting at the centre of emission


Second picture: flux map


OI line




no fitting → to close to a telluric line → another telluric lines correction needed


C+ line










CO 17-16







CO 22-21





CO 14-13





CO 16-15

