

STR

Software Test Report



Delivered by: Amit Raz

Verified by: Gal Matalon (המכללה לאוטומציה)

Table of contents

Purpose.....	1
Website overview.....	1
Tests Scope.....	1
Metrics.....	2
Recommendations.....	3
Conclusion.....	3
STD.....	5
Displaying bugs details from the JIRA system.....	16

Purpose

This document is meant to display the test planning, bug findings, and metrics of the homepage of the Wobi website.

Website overview

The homepage of the Wobi website contains links, buttons, information, and more, aimed at helping the user choose and purchase an insurance package tailored to their needs and personal requirements. The website deals with various types of insurance, including car insurance, home insurance, travel insurance, life and health insurance, mortgage insurance, and general insurance. In some cases, the user can independently start and complete the selection and purchase process on the website, while in other cases, this can only be done by contacting a company representative.


In addition, the website encourages users to learn and research the type of insurance they wish to purchase by providing important tips and other information in the form of articles and more, helping them make an informed decision that aligns with their goals.

Tests Scope


The tests were performed on the home page of the Wobi's website only on www.wobi.co.il. The other pages on the website were not tested. Most of the tests were functional, including checking the responsiveness of all links, buttons and forms. Besides functional tests, I performed UX and GUI tests, internationalization tests and accessibility tests. Other types of tests were not included in the scope of this document.

Metrics


Overall, I conducted 85 different tests. 67 of the tests passed successfully and 18 of them failed:



While conducting the tests I managed to review 40 different bugs. The following chart displays their severity:



This chart shows the bug's priority to be fixed:



Recommendations

1. From a functional perspective, most tests were successfully completed.
2. The majority of links, buttons, and forms are responsive and function as expected.
3. Visual inconsistencies were detected on the homepage, with design elements changing unexpectedly after clicking multiple links.
4. The website lacks support for English-speaking users, as its content cannot be fully translated into English or other major languages.
5. All Contact forms are not suitable for international users, as they do not accept non-Israeli phone numbers.
6. Phone icon links are completely unresponsive, making it difficult for users unfamiliar with email and social networks to contact company representatives.

Conclusion

Considering that the homepage suffers from recurring visibility issues during use of key elements that are significant to the user experience should be part of the decision of going live. Because the website's goal is to encourage users to purchase insurance independently, the user experience plays a crucial role in the decision to launch the site.

Although the vast majority of the detected bugs have low severity and priority levels, I do not recommend releasing the website version as it is before thoroughly addressing the identified issues.

STD basic functionality tests for <https://www.wobi.co.il/> homepage

Test Number	Test Description	Expected Test outcome	Fail/Passed/ Bug's ID in Jira
Home page			
1	Verify that the homepage loads successfully.	Homepage loads successfully.	Passed
2	Check that "בִּיטוֹה רַכֶּב" dropdown List is opening and showing the right possibilities.	The "בִּיטוֹה רַכֶּב" dropdown List is opening and showing the right possibilities.	Passed
3	Check that "בִּיטוֹה רַכֶּב" navigation link direct to the correct page.	The "בִּיטוֹה רַכֶּב" navigation link direct to the correct page.	Failed/ THWCIFB-2
4	"בִּיטוֹה נְסִיעוֹת לְחוּל" navigation link direct to the correct page.	The "בִּיטוֹה נְסִיעוֹת לְחוּל" navigation link direct to the correct page.	Passed
5	Check that "בִּיטוֹה דִּירָה" navigation link direct to the correct page.	The "בִּיטוֹה דִּירָה" navigation link direct to the correct page.	Passed
6	Check that "בִּיטוֹה מִשְׁכָנָתָא" navigation link direct to the correct page.	The "בִּיטוֹה מִשְׁכָנָתָא" navigation link direct to the correct page.	Passed
7	"בִּיטוֹה בָּרִיאָות וְחַיִם" navigation link direct to the correct page.	The "בִּיטוֹה בָּרִיאָות וְחַיִם" navigation link direct to the correct page.	Passed
8	Check that "בִּיטוֹה בּוּובי" navigation link direct to the correct page.	The "בִּיטוֹה בּוּובי" navigation link direct to the correct page.	Passed
9	Check that "בִּיטוֹה לְקוֹחוֹת" navigation link	The "בִּיטוֹה לְקוֹחוֹת" navigation link direct to the correct page.	Passed

Test Number	Test Description	Expected Test outcome	Fail/passed/ Bug's ID in Jira
	direct to the correct page.		
10	Check that "השارة פרטם" button response and directs to the right page	The "השارة פרטם" button response and directs to the right page	Passed
11	Check that "*2744" navigation link direct to the correct page.	The "*2744" navigation link direct to the correct page.	Failed/ THWCIFB-16
12	Check there is a possibility to translate the website into English on the top of the home page	There is a possibility to translate the website to English on the top of the home page	Failed/ THWCIFB-17
13	Check that clicking the "חווייה חדשה" link directs to the relevant information	Clicking the "חווייה חדשה" link directs the relevant information	Passed
14	Check that clicking the "משווים בין 10 חברות" link directs to the relevant information	Clicking "משווים בין 10 חברות" link directs to the relevant information	Passed
15	Check that clicking the "קונים וחותכים" link directs to the relevant information	Clicking the "קונים וחותכים" link directs the relevant information	Passed
16	Check that clicking the "צור קשר" link directs to the relevant information	Clicking the "צור קשר" link directs the relevant information	Passed
17	Check that clicking the "שירותות ללקוחות WhatsApp" WhatsApp button	Clicking the "שירותות ללקוחות WhatsApp" WhatsApp button opens the WhatsApp service	Passed

Test Number	Test Description	Expected Test outcome	Fail/passed/ Bug's ID in Jira
	opens the WhatsApp service		
18	Check that the Scroll to Bottom Button functions properly	The Scroll to Bottom Button functions properly	Passed
19	Check that "בִּיטוֹה רַכֶּב" button directs to the correct page.	The "בִּיטוֹה רַכֶּב" button directs to the correct page.	Passed
20	Check that "בִּיטוֹה נְסִיעוֹת לְחוּל" button directs to the correct page.	The "בִּיטוֹה נְסִיעוֹת לְחוּל" button directs to the correct page.	Passed
21	Check that "בִּיטוֹה דִּירָה" button directs to the correct page.	The "בִּיטוֹה דִּירָה" button directs to the correct page.	Passed
22	Check that "בִּיטוֹה מַשְׁכֶנֶתָא" button directs to the correct page.	The "בִּיטוֹה מַשְׁכֶנֶתָא" button directs to the correct page.	Passed
23	Check that "בִּיטוֹה בְּרִיאוֹת וְחַיִם" button directs to the correct page.	The "בִּיטוֹה בְּרִיאוֹת וְחַיִם" button directs to the correct page.	Passed
24	Check that the navigation arrows on the "קֻנוּים וְחוֹסְכִים" section are working properly	The navigation arrows on the "קֻנוּים וְחוֹסְכִים" section are working properly	Passed
25	On the "צָור קִשְׁר" section check that clicking the selection list button opens the list on "נֹשָׂא" selection field	Clicking the selection list button opens the list on "נֹשָׂא" selection field	Passed
26	On the "צָור קִשְׁר" section check that you can input a full name in Hebrew in the "שם מלא" field	You can input a full name in Hebrew in the "שם מלא" field	Passed

Test Number	Test Description	Expected Test outcome	Fail/passed/ Bug's ID in Jira
27	On the "צור קשר" section check that you can input a full name in English in the "שם מלא" field	You can input a full name in English in the "שם מלא" field	Failed/ THWCIFB-24
28	On the "צור קשר" section check that you can input numbers and other keyboard symbols in the "שם מלא" field	you can't input numbers and other keyboard symbols in the "שם מלא" field	Passed
29	On the "צור קשר" section check that trying to input numbers and other keyboard symbols in the "שם מלא" field leads to a relevant message	Trying to input numbers and other keyboard symbols in the "שם מלא" field leads to a relevant message	Failed/ THWCIFB-25
30	On the "צור קשר" section check that you can sign the checkbox on the "אני מאשר/ת את תנאי השימוש ומאשר/ת קבלת תוכן פרסומי כאמור"	You can sign the checkbox on the "אני מאשר/ת את תנאי השימוש ומאשר/ת קבלת תוכן פרסומי כאמור"	Passed
31	Check that clicking the " בהתנאים המפורטים " link opens and directs to the relevant information	Clicking the " בהתנאים המפורטים " link opens and directs to the relevant information	Passed
32	On the "צור קשר" section check that trying to input letters and other keyboard symbols in the "טלפון" field leads to a relevant message	Trying to input numbers and other keyboard symbols in the "טלפון" field leads to a relevant message	Failed/ THWCIFB-27

Test Number	Test Description	Expected Test outcome	Fail/passed/ Bug's ID in Jira
33	On the "צורך קשר" section check that clicking the "התקשרו אלינו" button when the "אני מאשר/ת את תנאי השימוש ומאשר/ת קבלת תוכן פורסומי כאמור" checkbox is not checked leads to a relevant message	clicking the "התקשרו אלינו" button when the "אני מאשר/ת את תנאי השימוש ומאשר/ת קבלת תוכן פורסומי כאמור" checkbox is not checked leads to a relevant message	Passed
34	On the "לא מצאתה את מה שchipשת?" section check that clicking on " moked@wobi.co.il " opens the Desktop email application in order to send a message	clicking on " moked@wobi.co.il " opens the Desktop email application in order to send a message	Passed
35	On the "לא מצאתה את מה שchipשת?" section check that clicking on " pniot@wobi.co.il " opens the Desktop email application in order to send a message	clicking on " pniot@wobi.co.il " opens the Desktop email application in order to send a message	Passed
36	On the "לא מצאתה את מה שchipשת?" section check that clicking on " 050-656-5902 " WhatsApp link opens the customer service WhatsApp Web interface	Clicking on " 050-656-5902 " WhatsApp link opens the customer service WhatsApp Web interface	Passed
37	On the "לא מצאתה את מה שchipשת?" section check that clicking on " חניון "	Clicking on " חניון " link responds	Failed/ THWCIFB-29

Test Number	Test Description	Expected Test outcome	Fail/passed/ Bug's ID in Jira
	2744* " link responds		
Home page – The bottommost part			
38	Check that "בִּיטוֹה רַכֶּב" navigation link direct to the correct page.	The "בִּיטוֹה רַכֶּב" navigation link direct to the correct page.	Passed
39	Check that "בִּיטוֹה מָקוֹם" navigation link direct to the correct page.	The "בִּיטוֹה מָקוֹם" navigation link direct to the correct page.	Passed
40	Check that "בִּיטוֹחַ צְדִיקָה" navigation link direct to the correct page.	The "בִּיטוֹחַ צְדִיקָה" navigation link direct to the correct page.	Passed
41	Check that "בִּיטוֹחַ חֻמֶּה" navigation link direct to the correct page.	The "בִּיטוֹחַ חֻמֶּה" navigation link direct to the correct page.	Passed
42	Check that "כְּדַאי לְדַעַת" navigation link direct to the correct page.	The "כְּדַאי לְדַעַת" navigation link direct to the correct page.	Passed
43	Check that "טִיפִים לְבִיטוֹה רַכֶּב" navigation link direct to the correct page.	The "טִיפִים לְבִיטוֹה רַכֶּב" navigation link direct to the correct page.	Passed
44	Check that "מָנוֹחִים" navigation link direct to the correct page.	The "מָנוֹחִים" navigation link direct to the correct page.	Passed
45	Check that "כְּתָבוֹת נּוֹסְפָּה" navigation link direct to the correct page.	The "כְּתָבוֹת נּוֹסְפָּה" navigation link direct to the correct page.	Passed
46	Check that "בִּיטוֹחַ נְסִיעֹות לְחוּלָה" navigation link direct to the correct page.	The "בִּיטוֹחַ נְסִיעֹות לְחוּלָה" navigation link direct to the correct page.	Passed

Test Number	Test Description	Expected Test outcome	Fail/passed/ Bug's ID in Jira
47	Check that "סוגי כיסויים" navigation link direct to the correct page.	The "סוגי כיסויים" navigation link direct to the correct page.	Passed
48	Check that "טיפים לביטוח נסיעות לחו"ל" navigation link direct to the correct page.	The "טיפים לביטוח נסיעות לחו"ל" navigation link direct to the correct page.	Passed
49	Check that "השוואת ביטוח" נסיעות לחו"ל" navigation link direct to the correct page.	The "השוואת ביטוח נסיעות לחו"ל" navigation link direct to the correct page.	Passed
50	Check that "ביטוח כבודה" navigation link direct to the correct page.	The "ביטוח כבודה" navigation link direct to the correct page.	Passed
51	Check that "ביטוח נסיעות לחו"ל – כיסוי קורונה" navigation link direct to the correct page.	The "ביטוח נסיעות לחו"ל – כיסוי קורונה" navigation link direct to the correct page.	Passed
52	Check that "ביטוח חופשת סקי" navigation link direct to the correct page.	The "ביטוח חופשת סקי" navigation link direct to the correct page.	Passed
53	Check that "פספורט קארד" navigation link direct to the correct page.	The "פספורט קארד" navigation link direct to the correct page.	Passed
54	Check that "כתבות נוספות" navigation link direct to the correct page.	The "כתבות נוספות" navigation link direct to the correct page.	Passed
55	Check that "ביטוח דירה" navigation link direct to the correct page.	The "ביטוח דירה" navigation link direct to the correct page.	Passed

Test Number	Test Description	Expected Test outcome	Fail/passed/ Bug's ID in Jira
56	Check that "תאולה ומבנה" navigation link direct to the correct page.	The "תאולה ומבנה" navigation link direct to the correct page.	Passed
57	Check that "טיפים לביטוח דירה" navigation link direct to the correct page.	The "טיפים לביטוח דירה" navigation link direct to the correct page.	Passed
58	Check that "הקטנות" navigation link direct to the correct page.	The "הקטנות" navigation link direct to the correct page.	Passed
59	Check that "השוואת ביטוח דירה" navigation link direct to the correct page.	The "השוואת ביטוח דירה" navigation link direct to the correct page.	Passed
60	Check that "ביטוח מבנה – המדריך המלא" navigation link direct to the correct page.	The "ביטוח מבנה – המדריך המלא" navigation link direct to the correct page.	Passed
61	Check that "ביטוח תאולה" navigation link direct to the correct page.	The "ביטוח תאולה" navigation link direct to the correct page.	Passed
62	Check that "כתובות נוספות" navigation link direct to the correct page.	The "כתובות נוספות" navigation link direct to the correct page.	Passed
63	Check that "ביטוח משכנתא" navigation link direct to the correct page.	The "ביטוח משכנתא" navigation link direct to the correct page.	Passed
64	Check that "יעוז משכנתא" navigation link direct to the correct page.	The "יעוז משכנתא" navigation link direct to the correct page.	Passed
65	Check that "משכנתא – בטחנות וערבות" navigation link direct to the correct page.	The "משכנתא – בטחנות וערבות" navigation link direct to the correct page.	Passed

Test Number	Test Description	Expected Test outcome	Fail/passed/ Bug's ID in Jira
	navigation link direct to the correct page.		
66	Check that "בִּיטוֹה מְשֻׁכְנָתָא: הרחבה" navigation link direct to the correct page.	The "בִּיטוֹה מְשֻׁכְנָתָא: הרחבה" navigation link direct to the correct page.	Passed
67	Check that "כְּתָבוֹת נוֹסְפּוֹת" navigation link direct to the correct page.	The "כְּתָבוֹת נוֹסְפּוֹת" navigation link direct to the correct page.	Passed
68	Check that "בִּיטוֹה בָּרַיאָה וְחַיִם" navigation link direct to the correct page.	The "בִּיטוֹה בָּרַיאָה וְחַיִם" navigation link direct to the correct page.	Passed
69	Check that "טִיפִים" navigation link direct to the correct page.	The "טִיפִים" navigation link direct to the correct page.	Passed
70	Check that "בִּיטוֹה כָּלְלִי" navigation link direct to the correct page.	The "בִּיטוֹה כָּלְלִי" navigation link direct to the correct page.	Passed
71	Check that "שִׁירּוֹת לְקוֹחוֹת" navigation link direct to the correct page.	The "שִׁירּוֹת לְקוֹחוֹת" navigation link direct to the correct page.	Failed/ THWCIFB-30
72	Check that "מַילּוֹן מְנוּחֵי בִּיטוֹה" navigation link direct to the correct page.	The "מַילּוֹן מְנוּחֵי בִּיטוֹה" navigation link direct to the correct page.	Failed/ THWCIFB-31
73	Check that "כְּתָבוֹת" navigation link direct to the correct page.	The "כְּתָבוֹת" navigation link direct to the correct page.	Failed/ THWCIFB-32
74	Check that "אמָנוֹת שִׁירּוֹת" navigation link direct to the correct page.	The "אמָנוֹת שִׁירּוֹת" navigation link direct to the correct page.	Failed/ THWCIFB-33

Test Number	Test Description	Expected Test outcome	Fail/passed/ Bug's ID in Jira
75	Check that "תנאי שימוש" navigation link direct to the correct page.	The "תנאי שימוש" navigation link direct to the correct page.	Failed/ THWCIFB-34
76	Check that "הצלה גישות" navigation link direct to the correct page.	The "הצלה גישות" navigation link direct to the correct page.	Failed/ THWCIFB-35
77	Check that "מפת האתר" navigation link direct to the correct page.	The "מפת האתר" navigation link direct to the correct page.	Failed/ THWCIFB-36
78	Check that "קוריירה" button direct to the correct page.	The "קוריירה" button direct to the correct page.	Passed

Contact Icons on the bottom left

79	Check that "*2744" navigation link direct to the correct page.	The "*2744" navigation link direct to the correct page.	Failed/ THWCIFB-38
80	Check that the envelope mail to icon is opening an email message using the internal mailing software	The envelope mail to icon is opening an email message using the internal mailing software	Passed
81	Check that the telephone receiver icon link responds correctly	The telephone receiver icon link responds correctly	Failed/ THWCIFB-39
82	Check that the WhatsApp receiver icon link respond correctly	The WhatsApp icon link respond correctly	Passed
83	Check that the Facebook receiver icon link responds correctly	The Facebook icon link respond correctly	Passed

Test Number	Test Description	Expected Test outcome	Fail/passed/ Bug's ID in Jira
84	Check that any statement which is not supposed to be a link is a link for no reason	Any statement on the home page which is not supposed to be a link is a link for no reason	Failed/ THWCIFB-37
85	Check that the text is clear and not hidden	All the text is clear and not hidden	Failed/ THWCIFB-3-11,13-15, 18-23, 26,

Displaying bugs details from the JIRA system

[THWCIFB-2] [The ביטוח רכב navigation link on the home page does not direct to the correct page.](#) Created: 02/Mar/25 Updated: 02/Mar/25

Status:	To Do		
Project:	Testing https://www.wobi.co.il/ for bugs		
Components:	None		
Affects versions:	None		
Fix versions:	None		
Type:	Bug	Priority:	Medium
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 Check that ביטוח רכב navigation link on the home page direct to the correct page2.png  Check that ביטוח רכב navigation link on the home page direct to the correct page1.png
Severity:	Major

Description

Steps to Reproduce the Bug:


1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>
2. Press the ביטוח רכב link on the head toolbar on the top-right of the home page.

Actual result:

The navigation link on the home page does not direct to the correct page. Instead, it opens a window saying “**ביטוח חובה**” that does not response.

Expected result:

The navigation link direct to the correct page.



[THWCIFB-3] יררכות נסיעות לחו"ל link

Created: 04/Mar/25 Updated: 04/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Medium
Reporter:	עמית רן	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	  Check that ביטוח נסיעות לחו"ל navigation link on the home page direct to the correct page.png irrelevant red frame around the travel abroad insurance link.png
Severity:	Low

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the ביטוח נסיעות לחו"ל link on the head toolbar on the top-right of the home page.

Actual result:

The ביטוח נסיעות לחו"ל navigation link has a irrelevant red frame around it.

Expected result:

The ביטוח נסיעות לחו"ל navigation link should not have a irrelevant red frame around it



[THWCIFB-4] **Irrelevant red frame around the ביטוח דירה link when pressing it** Created: 04/Mar/25 Updated: 04/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 Check that ביטוח דירה navigation link on the home page direct to the correct page1.png  irrelevant red frame around the department insurance link.png
Severity:	Low

Description

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the ביטוח דירה link on the head toolbar on the top-right of the home page.

Actual result:

The ביטוח דירה navigation link has a irrelevant red frame around it when pressing it.

Expected result:

The ביטוח דירה navigation link should not have a irrelevant red frame around it when pressing it.



[THWCIFB-5] Irrelevant red frame around the link when pressing it on the home page Created: 05/Mar/25 Updated: 05/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None

Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	  Check that ביטוח משכנתא navigation link on the home page direct to the correct page.png irrelevant red frame around the ביטוח משכנתא link.png
Severity:	Low

Description

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the ביטוח משכנתא link on the head toolbar on the top-right of the home page.

Actual result:

The ביטוח משכנתא navigation link has a irrelevant red frame around it.

Expected result:

The ביטוח משכנתא navigation link should not have a irrelevant red frame around it



[THWCIFB-6] Irrelevant red frame around the link when pressing it on the home page Created: 05/Mar/25 Updated: 05/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 ביטוח בריאות וחימם link.png Check that ביטוח בריאות וחימם navigation link on the home page direct to the correct page.png
Severity:	Low

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the ביטוח בריאות וחימם link on the head toolbar on the top-right of the home page.

Actual result:

The ביטוח בריאות וחימם navigation link has a irrelevant red frame around it.

Expected result:

The ביטוח בריאות וחימם navigation link should not have a irrelevant red frame around it



[THWCIFB-7] **Irrelevant red frame around the קריירה ב-wobi link when pressing it on the home page** Created: 05/Mar/25 Updated: 05/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	  Check that קריירה ב-wobi navigation link on the home page direct to the correct page.png irrelevant red frame around the קריירה ב-wobi link.png
Severity:	Low

Description

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the “קריירה ב-wobi” link on the head toolbar on the top-right of the home page.

Actual result:

The “קריירה ב-wobi” navigation link has a irrelevant red frame around it.

Expected result:

The “קריירה ב-wobi” navigation link should not have a irrelevant red frame around it



[THWCIFB-8] **שירותות ללקוחות link when pressing it on the home page** Created: 05/Mar/25 Updated: 05/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 irrelevant red frame around the link.png  Check that navigation link on the home page direct to the correct page.png
Severity:	Low

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the **שירותות לקוחות link** on the head toolbar on the top-right of the home page.

Actual result:

The **שירותות לקוחות navigation link** has an irrelevant red frame around it.

Expected result:

The **שירותות לקוחות navigation link** should not have an irrelevant red frame around it



[THWCIFB-9] Irrelevant red frame around the details input form for contact purposes that is opened after pressing "השارة פרטימ" on the home page Created: 05/Mar/25 Updated: 05/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 Check that השارة פרטימ navigation link on the home page direct to the correct page2.png  Check that השارة פרטימ navigation link on the home page direct to the correct page1.png
Severity:	Low

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the **השارة פרטימ** link on the head toolbar on the top-right of the home page.

Actual result:

The details input form for contact purposes that is opened after pressing "השارة פרטימ" on the home page has an irrelevant red frame around it.

Expected result:

The details input form for contact purposes that is opened after pressing "השارة פרטימ" on the home page does not have a red frame around it.



[THWCIFB-10] Irrelevant red frame around the subject field in the "השارة פרט" form on the home page Created: 06/Mar/25 Updated: 06/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
-------	-----	-----------	-----

Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 Irrelevant red frame around the subject field in the form on the home page2.png  Irrelevant red frame around the subject field in the form on the home page1.png
Severity:	Low

Description

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the link **השارة פרטימ** on the head toolbar on the top-right of the home page.
3. Press the “ נושא ” selection list.

Actual result:

The “ נושא ” selection list is opened with an irrelevant red frame around it.

Expected result:

The “ נושא ” selection list is opened without an irrelevant red frame around it.



[THWCIFB-11] Irrelevant red frame around the "שם מלא" field in the "השارة פרטיים" form on the home page Created: 06/Mar/25 Updated: 06/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 Irrelevant red frame around the שם מלא field in the form on the home page1.png  Irrelevant red frame around the השאהרת פרטיהם שם מלא field in the form on the home page2.png
Severity:	Low

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the link on the head toolbar on the top-right of the home page.
3. Fill in the “שם מלא” field .

Actual result:

The “שם מלא” field is shown with an irrelevant red frame around it when trying to fill it

Expected result:

The “שם מלא” field is not shown with an irrelevant red frame around it when trying to fill it



[THWCIFB-12] [You can't fill in an english name in the "שם מלא" field in the "השارة פרטיים" form on the home page](#) Created: 06/Mar/25 Updated: 06/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	High
Reporter:	עמית רז	Assignee:	Unassigned

Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 
Severity:	Major

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the link **השارة פרטיים** on the head toolbar on the top-right of the home page.
3. Try to Fill in the “**שם מלא**” field with English name.

Actual result:

The “**שם מלא**” field can not include English letters.

Expected result:

The “**שם מלא**” field should be able to include English letters.





[THWCIFB-13] Irrelevant red frame around the "טלפון" "השارة פרטיים" form on the home page Created: 06/Mar/25 Updated: 06/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned

Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 Irrelevant red frame around the form in the home page1.png  Irrelevant red frame around the form in the home page2.png
Severity:	Low

Description

Steps to Reproduce the Bug:



1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Press the link **השارة פרטיים** on the head toolbar on the top-right of the home page.
3. Fill in the “טלפון” field.

Actual result:

The “טלפון” field is shown with an irrelevant red frame around it when trying to fill it

Expected result:

The “טלפון” field is not shown with an irrelevant red frame around it when trying to fill it



[THWCIFB-14] Irrelevant red frame around button on the home page after pressing the "חזור" link on the "המשך פתרום" form Created: 06/Mar/25 Updated: 06/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
-------	-----	-----------	-----

Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 Irrelevant red frame around the 'השارة פרט' button after closing the the form on the home page1.png  Irrelevant red frame around the 'השارة פרט' button after closing the the 'צרכיים עזרה' form on the home page2.png
Severity:	Low

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the 'השارة פרט' link on the head toolbar on the top-right of the home page.
3. Pressing the "חזור" link on the "צרכיים עזרה" form back to the home page.

Actual result:

Irrelevant red frame around "השارة פרט" button on the home page after pressing the "חזור" link on the "צרכיים עזרה" form

Expected result:

Irrelevant red frame should not be shown around "השارة פרט" button on the home page after pressing the "חזור" link on the "צרכיים עזרה" form



[THWCIFB-15] Irrelevant red frame around the *2744 telephone number link

Created: 10/Mar/25 Updated: 10/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רן	Assignee:	Unassigned

Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome Browser		

Attachments:	 irrelevant red frame around the 2744 telephone number link.png  irrelevant red frame around the 2744 telephone number link2.png
Severity:	Low

Description

Steps to Reproduce the Bug:


1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the *2744 link on the head toolbar on the top-right of the home page

Actual result:

Irrelevant red frame around *2744 link on the home page after pressing the *2744 link.

Expected result:

Irrelevant red frame should not be shown around the *2744 link on the home page after pressing the *2744 link



[THWCIFB-16] The *2744 telephone number link on the home page is not responding Created: 10/Mar/25 Updated: 17/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	High
Reporter:	עמית רן	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0

Labels:	None
Remaining Estimate:	Not Specified
Time Spent:	Not Specified
Original estimate:	Not Specified
Environment:	Google Chrome Browser

Attachments:	The 2744 telephone number link is not responding.png
Severity:	Critical

Description

Steps to Reproduce the Bug:


1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the *2744 link on the head toolbar on the top-right of the home page

Actual result:

Pressing the *2744 link on the home page does not respond by opening an external contact service.

Expected result:

Pressing the *2744 link on the home page should respond by opening an external contact service.



[THWCIFB-17] **There is no possibility to translated the website to English on the top of the home page** Created: 10/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Medium
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome Browser		

Attachments:	 There is no possibility to translated the website to English on the top of the home page.png
Severity:	Minor

Description

Steps to Reproduce the Bug:


1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.

Actual result:

Translating the website to English is impossible on the top of the home page.

Expected result:

There is a possibility to translate the website to English on the top of the home page.



[THWCIFB-18] חויה חדשה link on the home page

Created: 10/Mar/25 Updated: 10/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome Browser		

Attachments:	irrelevant red frame around the link on the home page.png
Severity:	Low

Description

Steps to Reproduce the Bug:


1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the “חוויה חדשה” link on the head toolbar on the top-right of the home page

Actual result:

Irrelevant red frame around the “חוויה חדשה” link on the home page after pressing the “חוויה חדשה” link.

Expected result:

Irrelevant red frame should not be shown around the “חוויה חדשה” link on the home page after pressing the “חוויה חדשה” link



[THWCIFB-19] irrelevant red frame around the link on the home page

Created: 10/Mar/25 Updated: 10/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רן	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		

Remaining Estimate:	Not Specified
Time Spent:	Not Specified
Original estimate:	Not Specified
Environment:	Google Chrome Browser

Attachments:	 irrelevant red frame around the link on the home page.png
Severity:	Low

Description

Steps to Reproduce the Bug:


1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the “חוויה חדשה” link on the head toolbar on the top-right of the home page

Actual result:

Irrelevant red frame around “חוויה חדשה” link on the home page after pressing the “חוויה חדשה” link.

Expected result:

Irrelevant red frame should not be shown around the “חוויה חדשה” link on the home page after pressing the “חוויה חדשה” link



[THWCIFB-20] [Irrelevant red frame around the “צור קשר” link on the home page](#) Created: 10/Mar/25 Updated: 10/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome Browser		

Attachments:	 Irrelevant red frame around the “צור קשר” link on the home page.png
Severity:	Low

Description

Steps to Reproduce the Bug:



1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the “צור קשר” link on the home page.

Actual result:

Irrelevant red frame around “צור קשר” link on the home page after pressing the “צור קשר” link.

Expected result:

Irrelevant red frame should not be shown around the “צור קשר” link on the home page after pressing the “צור קשר” link



[THWCIFB-21] Irrelevant red frame around the scroll to bottom button on the home page Created: 10/Mar/25 Updated: 10/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רן	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome Browser		

Attachments:	Irrelevant red frame around the scroll to Bottom Button on the home page.png
Severity:	Low

Description

Steps to Reproduce the Bug:


1. Browse with Google Chrome to Wobi website at <https://www.wobi.co.il/>.
2. Press the Scroll to Bottom Button on the home page.

Actual result:

Irrelevant red frame around Scroll to Bottom Button on the home page after pressing the Scroll to Bottom Button.

Expected result:

An irrelevant red frame should not be shown around the Scroll to Bottom Button on the home page after pressing the Scroll to Bottom Button.



[THWCIFB-22] Irrelevant red frame around the purpose of contacting selection list on the home page when opened

Created: 10/Mar/25 Updated: 10/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
-------	-----	-----------	-----

Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome Browser		

Attachments:	 Irrelevant red frame around the נושא selection list on the home page.png
Severity:	Low

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Press the “צור קשר” link on the home page.
3. Open the נושא purpose of contacting selection list.

Actual result:

Irrelevant red frame around the נושא purpose of contacting selection list when opened.

Expected result:

Irrelevant red frame should not be shown around the נושא purpose of contacting the selection list when opened



[THWCIFB-23] Irrelevant red frame around the שם מלא field on the contact form

Created: 11/Mar/25 Updated: 11/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google chrome browser		

Attachments:	Irrelevant red frame around the שם מלא field on the contact form.png
Severity:	Low

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Press the “צור קשר” link on the home page.
3. Fill in the “שם מלא” field on the “צור קשר” link

Actual result:

Irrelevant red frame around the “שם מלא” field on the contact form.

Expected result:

Irrelevant red frame should not appear around the “שם מלא” field on the contact form.



[THWCIFB-24] [You can not input a full name in English in the “שם מלא” field on the contact form](#)

Created: 11/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Medium
Reporter:	עמית רן	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		

Remaining Estimate:	Not Specified
Time Spent:	Not Specified
Original estimate:	Not Specified
Environment:	Google chrome browser

Attachments:	
Severity:	Minor

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Press the “צור קשר” link on the home page.
3. Fill in the “שם מלא” field on the “צור קשר” link with the name “Amit Raz”.

Actual result:

You can not input the name in “Amit Raz” in the “שם מלא” field on the contact form.

Expected result:



You can input the name “ Amit Raz ”in the “שם מלא” field on the contact form



[THWCIFB-25] [Input numbers and other keyboard symbols in the שם מלא field does not produce error message](#) Created: 11/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google chrome browser		

Attachments:	 input numbers and other keyboard symbols in the שם מלא field does not produce error message.png  input numbers and other keyboard symbols in the שם מלא field does not produce error message1.png
Severity:	Low

Description

Steps to Reproduce the Bug:



1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Press the “צור קשר” link on the home page.
3. Try to type in the “שם מלא” field with the following expression: 12\$87%

Actual result:

Blocking typing numbers and other keyboard symbols in the שם מלא field does not produce an error message

Expected result:

Blocking typing numbers and other keyboard symbols in the שם מלא field does produce an error message



[THWCIFB-26] Irrelevant red frame around the link on the contact form Created: 11/Mar/25 Updated: 11/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רן	Assignee:	Unassigned

Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google chrome browser		

Attachments:	 Irrelevant red frame around the link on the contact form.png
Severity:	Low

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Press the “צור קשר” link on the home page.
3. Press the “בנתאים המפורטים” link.

Actual result:

Irrelevant red frame around the “בנתאים המפורטים” link on the contact form.

Expected result:

Irrelevant red frame should not appear around the “בנתאים המפורטים” link on the contact form.



[THWCIFB-27] [Typing letters and other keyboard symbols in the field does not produce error message](#)

Created: 11/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google chrome browser		

Attachments:	Typing letters and other keyboard symbols in the field does not produce error message.png input letters and other keyboard symbols in the field does not produce an error message1 - עותק.png
Severity:	Low

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Press the “**צור קשר**” link on the home page.
3. Try to type in the “**טלפון**” field the following expression: fwm*)a


Actual result:

Blocking typing letters and other keyboard symbols in the **טלפון** field does not produce an error message

Expected result:

Blocking typing numbers and other keyboard symbols in the **טלפון** field does produce an error message





[THWCIFB-28] The field on the contact form can not include a full non israeli telephone number

Created: 11/Mar/25 Updated: 11/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google chrome browser		

Attachments:	The field on the contact form can not include a non israeli telephone number.png
Severity:	Low

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Press the “**צור קשר**” link on the home page.
3. Try to type in the “**טלפון**” field the following non Israeli telephone number: +492215556417

Actual result:

The **טלפון** field can not include a full non Israeli telephone number.

Expected result:

The **טלפון** field should be able to include a full non Israeli telephone number.



[THWCIFB-29] [On the “**לא מצאת את מה שאתה מחפש?**” section clicking on “**2744**” link does not responds](#) Created: 11/Mar/25 Updated: 17/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	High
Reporter:	עמית רן	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		

Remaining Estimate:	Not Specified
Time Spent:	Not Specified
Original estimate:	Not Specified
Environment:	Google chrome browser

Attachments:	 The telephone number link 2744 on the page does not respond.png
Severity:	Critical

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the "לא מצאת את מה שchipset?" section.
3. click the " 2744 *חינו " link.

Actual result:

" 2744 *חינו " link does not respond.

Expected result:

" 2744 *חינו " link does respond.



[THWCIFB-30] **The customer service link on the bottom right of the home page leads to a wrong destination** Created: 12/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Medium
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 The customer service link on the bottom right of the home page leads to a wrong destination2.png  The customer service link on the bottom right of the home page leads to a wrong destination1.png
Severity:	Major

Description

Steps to Reproduce the Bug:



1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.
3. Click the "שירות לקוחות" link on the right part of the page.

Actual result:

This leads the user back to the head of the home page.

Expected result:

A dialog box or form for contacting customer service will be opened.



[THWCIFB-31] First click on the link on the bottom of the home page does open the link Created: 12/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Medium
Reporter:	עמית רן	Assignee:	Unassigned

Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 First click on the bottom of the home page does open it3.png  First click on the bottom of the home page does open it2.png  First click on the bottom of the home page does open it1.png
Severity:	Minor

Description

Steps to Reproduce the Bug:



1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.
3. Click the "מילון מונחי ביטוח" link on the right part of the page.


Actual result:

Clicking on the "מילון מונחי ביטוח" link does not open on the first click but arranges the group of links in a different layout.

Expected result:

Click on the "מילון מונחי ביטוח" link does open the link on the first click.





[THWCIFB-32] [First click on the link on the bottom of the home page does open the link](#)

Created: 13/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Medium
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 First click on the link on the bottom of the home page does open it2.png  First click on the link on the bottom of the home page does open it1.png  First click on the link on the bottom of the home page does open it3.png
Severity:	Minor

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.
3. Click the link " כתבות " link on the right part of the page.



Actual result:

Clicking on the **כתובות** link does not open the link on the first click but arranges the group of links in a different layout.

Expected result:

Clicking on the **כתובות** link does open the link on the first click.





[THWCIFB-33] First click on the bottom link on the home page does open the link

Created: 13/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Medium
Reporter:	עמית רן	Assignee:	Unassigned

Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 First click on the bottom link "אמנה שירות" does open it1.png  First click on the bottom link "אמנה שירות" does open it2.png  First click on the bottom link "אמנה שירות" does open it3.png
Severity:	Minor

Description

Steps to Reproduce the Bug:



1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.
3. Click the " “אמנה שירות” link on the right part of the page.


Actual result:

Clicking on the " “אמנה שירות” link does not open the link on the first click but arranges the group of links in a different layout.

Expected result:

Clicking on the " “אמנה שירות” link does open the link on the first click.





[THWCIFB-34] [First click on the link on the bottom of the home page does open the link](#)

Created: 14/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Medium
Reporter:	עמית רן	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	First click on the link on the bottom of the home page does open it1.png First click on the link on the bottom of the home page does open it2.png First click on the link on the bottom of the home page does open it3.png
Severity:	Minor

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.
3. Click the "תנאי שימוש" link on the right part of the page.



Actual result:

Clicking on the "תנאי שימוש" link does not open the link on the first click but arranges the group of links in a different layout.

Expected result:

Clicking on the "תנאי שימוש" link does open the link on the first click.





[THWCIFB-35] First click on the הצערת נגישות link on the bottom of the home page does open the link

Created: 14/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Medium
Reporter:	<u>עמיית רן</u>	Assignee:	Unassigned

Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 First click on the bottom link does open it1.png  First click on the bottom link does open it2.png
Severity:	Minor

Description

Steps to Reproduce the Bug:



1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.
3. Click the "הצהרת נגישות" link on the right part of the page.

Actual result:

Clicking on the "הצהרת נגישות" link does not open the link on the first click but arranges the group of links in a different layout.

Expected result:

Clicking on the "הצהרת נגישות" link does open the link on the first click.



[THWCIFB-36] [First click on the "מפת האתר" link on the bottom of the home page does open the link on the first click](#)

Created: 14/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Medium
Reporter:	עמית רן	Assignee:	Unassigned

Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 First click on the 'דף הבית' link on the bottom of the home page does open it1.png  First click on the 'דף הבית' link on the bottom of the home page does open it2.png
Severity:	Minor

Description

Steps to Reproduce the Bug:



1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.
3. Click the "דף הבית" link on the right part of the page.

Actual result:

Clicking on the "דף הבית" link does not open the link on the first click but arranges the group of links in a different layout.

Expected result:

Clicking on the "דף הבית" link does open the link on the first click.



[THWCIFB-37] The "כל הזכויות שמורות" stating on the bottom of the home page is not supposed to be a link

Created: 14/Mar/25 Updated: 14/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned

Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 The 'כל הזכויות שמורות' link on the bottom of the home page is a link which sends the user to the top of the page1.png  The 'כל הזכויות שמורות' link on the bottom of the home page is a link which sends the user to the top of the page2.png
Severity:	Low

Description

Steps to Reproduce the Bug:



1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.
3. Click the " כל הזכויות שמורות " link on the bottommost right part of the page.

Actual result:

The " כל הזכויות שמורות " stated on the bottom of the home page is a link which sends the user to the top of the page

Expected result:

The " כל הזכויות שמורות " stating on the bottom of the home page should not be a link which sends the user to the top of the page.



[THWCIFB-38] [The telephone number link *2744 on the bottom left of the home page does not respond](https://www.wobi.co.il/) Created: 15/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	High
Reporter:	עמית רן	Assignee:	Unassigned

Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 The telephone number link 2744 on the bottom of the home page does not respond.png
Severity:	Critical

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.
3. Click the " *2744 " link on the bottom left part of the page.

Actual result:

The telephone number link *2744 on the bottom left of the home page does not respond.

Expected result:

The telephone number link *2744 on the bottom of the home page should respond.



[THWCIFB-39] The telephone receiver icon link on the bottom left of the home page does not respond correctly and opens an empty web page

Created: 15/Mar/25 Updated: 16/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	High
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	The telephone icon link on the bottom left of the home page does not respond correctly and opens an empty web page2.png The telephone icon link on the bottom left of the home page does not respond correctly and opens an empty web page1.png
Severity:	Critical

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.
3. Click the receiver link on the bottom left part of the page.


Actual result:

The telephone receiver icon link on the bottom left of the home page does not respond correctly and opens an empty web page not promoting the communication between the user and the company.

Expected result:

The telephone receiver icon link on the bottom left of the home page does not respond correctly and should promote communication between the user and the company, and not open an empty web page.





[THWCIFB-40] The scroll button up and down on the homepage hides part of the linking words 'Customer Service' and the sentence 'All rights reserved' in the bottom right section of the page

Created: 15/Mar/25 Updated: 15/Mar/25

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רן	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	The scroll button up and down on the homepage hides two links on the bottom right section of the page.png
Severity:	Low

Description

Steps to Reproduce the Bug:


1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.

Actual result:

The scroll button up and down on the homepage hides part of the linking words 'Customer Service' and the sentence 'All rights reserved' in the bottom right section of the page.

Expected result:

The scroll button up and down on the homepage should not hide part of the linking words 'Customer Service' and the sentence 'All rights reserved' in the bottom right section of the page.



[THWCIFB-41] [The WhatsApp contact button hides a word in the sentence on the most bottom left of the home page](#)

Created: 15/Mar/25 Updated:

Status:	To Do
Project:	Testing https://www.wobi.co.il/ for bugs
Components:	None
Affects versions:	None
Fix versions:	None

Type:	Bug	Priority:	Low
Reporter:	עמית רז	Assignee:	Unassigned
Resolution:	Unresolved	Votes:	0
Labels:	None		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		
Environment:	Google Chrome browser		

Attachments:	 The WhatsApp contact button hides a word in the sentence on the most bottom left of the home page.png
Severity:	Low

Description

Steps to Reproduce the Bug:

1. Browse the Wobi website on Google Chrome at <https://www.wobi.co.il/>.
2. Scroll down to the **bottom part** of the home page.

Actual result:

The WhatsApp contact button for 'Customer Service' hides the word 'secure' in the sentence 'The purchase process is secure through Comodo Secure.'

Expected result:

The WhatsApp contact button for 'Customer Service' should not hide the word 'secure' in the sentence 'The purchase process is secure through Comodo Secure.'

