



MANUFACTURES INSPECTION REPORT 1-9-26

Billed to:

Contact name: Kurt Kamrad
Contact Email: kurtkamrad@gmail.com
Street address: 1122 Laguna Springs
City: Weston
State FL 33326
Phone: 954 536 6204

S Tile 4/12 3848'


Total pgs (7)

Manufacturer Evaluation Inspection Report with Specifications for the
Roof Shield Coating System for a sq ft (1 Story) S Tile (Closed Valleys) Roof System.



(See Drawing)

Owner reported possible Leak Moisture near left front entrance in bedroom area.
(Exact location has not been determined)



Common Area Tile (R slope) cracked Tile & chipped Corners





End Cap on Ridege Crushed – Missing Cement





All Solar System panels require complete removal



Fascia Board outer edge Rot



Specifications Roof Coating Application

Advanced Roof Coating System to be applied on all S Tile Roof Surfaces

Base required for all Filed Terminations where needed

Agreement, Scope of work Details.

- A. Cleaning (Chem Clean) , wash down.
- B. Monolithic Base & Prep
- C. 1 Coat Sealer / Primer
- D. Top Final Top Coatings (Roofprotect)

***Owner Responsible to have rework undertaken prior to application**

The Manufacturers Inspection is not intended on providing Structural Integrity Advise, the undertaking of the review of your roof was for the purpose of confirmation of stable surfaces of your Flat roof or Roof tiles, The Flat Deck or Tile attachements, presence of any chips or Cracks, Flat decks Tie Ins, seams and edges are secure, all Returns, Eaves and Sofets are free of rot from mositure and water Intrusion, any Insulation or Wood that may be soft or wet and dangerous to walk on that needs to be repaired prior to the appication of Roof Coatings.

The main Purpose of this is Inspection is for the future successful application of our Products that require the roof surfaces to be traversed to apply Protective Coatings, you may be alerted to rework areas or other concerns that should be addressed. The owner is ultimately responsible for any repairs or rework indicated prior to application, (unless other wise specified and to be included depending on its scope), of our roof coatings and or roof maintenance systems and may be at an additional cost above the standard application costs for the installation of our Products.

(Report prepared by Product Manufacturer)

If the client proceeds with the installation this report and accompanied any drawings for the suggested rework and or repairs aforementioned and will be an adjunct to any written Service Orders.

Roofprotect Manufacturing Division of

Storm Shield Paint Systems

Inc dba Roof Shield Coating

System

515 East Las Olas Blvd , Ft

Lauderdale Fl, 33301

(954)-210-9614 option 1.

Specifications Roof Coating Application

2000 sq ft' B.U.R Advanced Roof Coating to be applied on to All Flat Deck Areas
walls and Terminations may be included depending on the Service Contract
Agreement, Scope of work Details.

A. Cleaning (Chem Clean)

B. Monolithic Base Where
Needed

C. 1 Coat Sealer / Primer

D. Top Final Top Coatings (Roofprotect)

***Owner Responsible to have rework undertaken prior to application**

The Manufacturers Inspection is not intended on providing Structural Integrity Advise, the undertaking of the review of your roof was for the purpose of confirmation of stable surfaces of your Flat roof or Roof tiles, The Flat Deck or Tile attachments, presence of any chips or Cracks, Flat decks Tie Ins, seams and edges are secure, all Returns, Eaves and Sofets are free of rot from moisture and water Intrusion, any Insulation or Wood that may be soft or wet and dangerous to walk on that needs to be repaired prior to the application of Roof Coatings. The main Purpose of this inspection is for the future

successful application of our Products that require the roof surfaces to be traversed to apply Protective Coatings, you may be alerted to rework areas or other concerns that should be addressed. The owner is ultimately responsible for any repairs or rework indicated prior to application, (unless other wise agreed to be included depending on its scope), of our roof coatings and or roof maintenance systems and may be and additional cost above the standard application costs for the insatllation of our Products.

(Report prepared by Product Manufacturer)

If the client proceeds with the installation this report and accompanied a drawings for the suggested rework and or repairs aforementioned will be an adjunct to any written Service Orders.

Roofprotect Manufacturing Division of

Storm Shield Paint Systems

Inc dba Roof Shield Coating

System

515 East Las Olas Blvd , Ft

Lauderdale Fl, 33301

(954)-210-9614 option 1.

pg (7)