


Path Traversal vulnerability, is when a parameter loads a file from a directory and there's no security measures in place; Avoid passing raw user input to files-system. And instead map requests to a predefined list. Using Portswigger labs. We see that the website loads images of products from a directory, I tried to roll back to the root directory and read the /etc/passwd file. Which worked



I tried another lab, this lab had the same vulnerable parameter. The application blocked traversal sequences(./ ../). but the backend assumes the file supplied lives inside a specific asset folder. It concatenates the base path with the user's input, so I only typed /etc/passwd

