TEST REPORT

No. : GZPL220700711502PS
Date : Aug 03, 2022

scan to see the report
GZPL220700711502PS

CUSTOMER NAME: WINGKAY PLASTIC PRODUCT COMPANY LIMITED

ADDRESS: NO.8 ZHONGFU ROAD, ZHONGCHONG INDUSTRY LELIU TOWN, SHUNDE DISTRICT FOSHAN CITY GUANGDONG, CHINA

Sample Name : EPDM GB

Product Specification : 85°±5°

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

****

Date of Receipt : Jul 15, 2022

Testing Start Date : Jul 15, 2022

Testing End Date : Aug 03, 2022

Test result(s) : For further details, please refer to the following page(s)
(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Testing Center

Quincey Lee
Authorized signatory

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Testing Centre Materials & Reliability Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

198 Kezhu Road, Scientech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t (86-20) 82155555 f (86-20) 82075188 www.sgsgroup.com.cn
中国・广州・经济技术开发区科学城科珠路198号 邮编: 510663 t (86-20) 82155555 f (86-20) 82075188 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)

TEST REPORT

No. : GZPL220700711502PS
Date : Aug 03, 2022

Summary of Results:

No.	Test Item	Test Method	Result	Conclusion
1	Hardness	GB/T 24498-2019 Section 6.4.1.1 & GB/T 531.1-2008	84 Shore A	Pass
2	Hot Air Ageing	GB/T 24498-2019 Section 6.4.2.1.1, Section 6.4.1.1 & GB/T 3512-2014 & GB/T 531.1-2008	+4 Shore A	Pass

Note: Pass : Meet the requirements;
Fail : Does not meet the requirements;
/ : Not Apply to the judgment.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co.,Ltd. Guangzhou Branch Testing Centre-Materials & Reliability Laboratory
198 Kezhu Road, Scientech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t (86-20) 82155555 f (86-20) 82075188 www.sgsgroup.com.cn
中国·广州·经济技术开发区科学城科珠路198号 邮编: 510663 t (86-20) 82155555 f (86-20) 82075188 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)

TEST REPORT

No. : GZPL220700711502PS
Date : Aug 03, 2022

1.Test Item: Hardness

Sample Description: Rubber part

Test Method: GB/T 24498-2019 Section 6.4.1.1 & GB/T 531.1-2008

Test Condition:

Specimen thickness: 6.01mm

Shore A hardness durometer

Read time: 3s


Nominal hardness: 85Shore A

Lab Environmental Condition: 23±2℃, 50±5%RH


Test Result:

Test Item	Test Result	Requirement in GB/T 24498-2009 Table 2	Conclusion
Hardness	84 Shore A	(85±5)Shore A	Pass

Test Photo:



Original sample 002



During Test

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co.,Ltd. Guangzhou Branch Testing Centre Materials & Reliability Laboratory
198 Kezhu Road, Scientech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t (86-20) 82155555 f (86-20) 82075188 www.sgsgroup.com.cn
中国・广州・经济技术开发区科学城科珠路198号 邮编: 510663 t (86-20) 82155555 f (86-20) 82075188 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)

TEST REPORT

Equipment Information:

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Multifunction Hardness Tester	Digitest Ⅱ	GZMR-PL-E156	2022-05-06	2023-05-05

2.Test Item: Hot Air Ageing

Sample Description: Rubber part

Test Method: GB/T 24498-2019 Section 6.4.2.1.1, Section 6.4.1.1 & GB/T 3512-2014 & GB/T 531.1-2008

Test Condition:

Heat ageing condition: 100℃,168h→(23±2)℃,(50±5)%RH,24h

Specimen thickness: 6.01mm


Lab Environment Condition: (23±2)℃,(50±5)%RH

Test Result:

Test Item	Test Result	Requirement in GB/T 24498-2009 Table 2	Conclusion
Change in Hardness	+4Shore A	(-5～+10)Shore A	Pass

Note: Change in Hardness =Value after ageing – Value as received

Test Photo:



Original sample 002



During Test - Heat ageing

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

TEST REPORT

No. : GZPL220700711502PS
Date : Aug 03, 2022

Equipment Information:

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Oven	UF110	GZMR-PL-E232	2022-05-09	2023-05-08
Multifunction Hardness Tester	Digitest Ⅱ	GZMR-PL-E156	2022-05-06	2023-05-05

Appendix information: In the territory of the People's Republic of China, the test report without CMA logo expresses the test report shall only be used for client scientific research, teaching, internal quality control, product research and development, etc., and just for client internal reference.

******** End of report********

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Testing Centre-Materials & Reliability Laboratory
198 Kezhu Road, Scientech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t (86-20) 82155555 f (86-20) 82075188 www.sgsgroup.com.cn
中国·广州·经济技术开发区科学城科珠路198号 邮编: 510663 t (86-20) 82155555 f (86-20) 82075188 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)