

Ship/HULL NO. LCU-1651	Ship/HULL NAME NBU-7	JON:	ICN: 38NBA51217	Rev:	Key Op: A01
TITLE: Overflow and Natural Vent Piping; inspect and replace					

JOB SPECIFICATION

Anticipated Award Date: 12/08/2025 5/01/2026	Production Completion Date: 8/21/2026 8/29/2026	PREPARING ACTIVITY: SASEBO	
POP Start Date: 2/02/2026 6/01/2026	POP End Date: 7/15/2025 9/30/2026		
PREPARED BY: M.NOGUCHI	4/9/2026 Avelino L. Reyes Jr.	CODE P NM	DATE 9/25/2025
APPROVED BY: S.MURAKAMI	<i>SM</i>	CODE S225	
CONCURRED BY: T.TAKAMASU	<i>TT</i>	CODE S234	
ASSIST PLANNER'S NAME: H.MUTA		CODE H MU	
ASSIST PLANNER'S NAME:		CODE	
ASSIST PLANNER'S NAME:		CODE	
DESCRIPTION:			
JSN(S): CU51-2100		CASREP #	
S/F CONTACT: MOREL MM2 / KHULLAR		CWP #	CCNS #
Approved by S300/S900 A. REYES PM, S320		Date: <i>9/29/25</i>	Avl: 6C2 4/9/2026 6B1 Avelino L. Reyes Jr.
		LWC:	
Work Completed			
S/Force:	Rate:	Date:	
SHIPSUPT:	Date:	SRF CONTROL NO.:	1301357121
WORK CERTIFICATION SIGNATURES			
COMPLETION OF WORK REVIEW:	BADGE NO.:	SHOP/CODE:	PHONE DATE:

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA51217		A01

TITLE:

Overflow and Natural Vent Piping; inspect and replace

1. SCOPE:

- 1.1 Title: Overflow and Natural Vent Piping; inspect and replace
- 1.2 Location of Work:
 - 1.2.1 AFT Engine ROOM (2-56-0-E)
 - 1.2.2 Bulwark, See ENCLOSURE (A)
- 1.3 Identification:
 - 1.3.1 Quantity (One EA), Waste Oil Tank (Capacity: Approximate 113 Gallon), Located in 1.2.1
 - 1.3.2 Quantity (Total 120 FT), One Inch IPS through 6 Inch IPS Tank Overflow and Natural Vent Piping Located in 1.2.2, C-Steel and CuNi, See ENCLOSURE (A)
 - 1.3.3 Quantity (Total 50 FT), One Inch IPS through 6 Inch IPS Tank Overflow and Natural Vent Piping which are Found Deterioration and Rejected by Visual Inspection, C-Steel and CuNi

2. REFERENCES:

- 2.1 Standard Items (FY 26)
- 2.2 500-5104332 Rev A, Fire, Bilge, Ballast & Oily Water Systems

3. REQUIREMENTS:

- 3.1 Accomplish the requirements of ENCLOSURE (T) for cleaning of each waste oil tank listed in 1.3.1 using 2.2 for guidance.
- 3.2 Accomplish the visual inspection of piping listed in 1.3.2 to locate the deteriorated area of piping listed in 1.3.2.

(V) "REPORT"

3.2.1 Submit One legible condition report listing results of the requirements of 3.2 to SUPERVISOR.

3.3 Clean piping affected by this work item to a gas/oil free condition, in accordance with 29 CFR 1915 Subpart B.

(V) "REPORT"

3.3.1 Submit one legible condition report of the Marine Chemist certificate to SUPERVISOR, including certified location.

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA51217		A01

TITLE:

Overflow and Natural Vent Piping; inspect and replace

3.4 Remove existing and install new piping to replace piping listed in 1.3.3.

3.4.1 Accomplish the requirements of 009-12 of 2.1, including Table One, Column A, Lines One through 10.

3.4.1.1 Fabricate each backing ring in accordance with Line 6.

(V) (G) "AIR FLOW TEST"

3.4.2 Accomplish the air flow test of new and disturbed piping affected by this work item to verify no leak and unobstructed flow, until the specified criteria is verified. Allowable leakage and obstructive flow: None.
- S130

(V) "REPORT"

3.4.3 Submit one legible condition report of location and length of replaced piping to SUPERVISOR.

3.5 Accomplish the requirements of 009-32 of 2.1 for cleaning and preservation of each new and disturbed surface to match surrounding areas.

4. NOTES:

4.1 Initial Condition - Overflow and natural vent piping are corroded.

4.2 SRF tool room will issue torque wrenches when required.

4.3 Tank cleaning work for ballast tanks will be covered by ICN 38NBA12311-A01.

4.4 Tank cleaning work for fuel oil tanks will be covered by ICN 38NBA12312-A01.

5. GOVERNMENT FURNISHED MATERIAL:

5.1 SRF will provide following material.

MATERIAL LIST									
ITEM NO.	PC NO.	REF NO.	M / C	DESCRIPTION	STOCK NUMBER	HAZ MAT	DOC NO.	QTY REQD/ UNIT	PARA NO.
001			M	PIPE, 6"IPS, 6.625"OD X 0.280"WT, SCH 40, ASTM-A106 GR.B, C-STEEL	9B 4710 010142591	N		20/FT	3.4
002			M	PIPE, 5"IPS, 5.563"OD X 0.258"WT, SCH 40, MIL-P-24691/1, C-STEEL	9B 4710 002894519	N		30/FT	3.4
003			M	PIPE, 4"IPS, 4.500"OD X 0.237"WT, SCH 40, ASTM-A106 GR.B, C-STEEL	9B 4710 003475111	N		5/FT	3.4

3/10

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA51217		A01

TITLE:

Overflow and Natural Vent Piping; inspect and replace

MATERIAL LIST									
ITEM NO.	PC NO.	REF NO.	M / C	DESCRIPTION	STOCK NUMBER	HAZ MAT	DOC NO.	QTY REQD/ UNIT	PARA NO.
004			M	PIPE, METALLIC, 2-1/2"IPS, 2.875"OD X 0.203"WT, SCH 40, ASTM A-106 GR.B, C-STEEL	9B 4710 008925913	N		10/FT	3.4
005			M	PIPE, PIPE, 2"IPS, 2.375"OD X 0.154"WT, SCH40, ASTM-A106 GR.B, C-STEEL	9B 4710 008490871	N		10/FT	3.4
006			M	PIPE, 1-1/2"IPS, 1.900"OD X 0.145"WT, SCH 40, ASTM A-106 GR.B, C-STEEL	9B 4710 008925914	N		15/FT	3.4
007			C	PIPE, 1-1/2"IPS, 1.900"OD X 0.072"WT, 200#, MIL-T-16420 GR.1 TY.1, CNA 70/30	9B 4710 002897993	N		10/FT	3.4
008			C	PIPE, 1"IPS, 1.315"OD X 0.065"WT, 200#, MIL-T-16420, CUNI 70/30	9B 4710 002774543	N		10/FT	3.4
009			M	TANK VENT VALVE, 6"IPS, BW, TATE TEMCO 52-20V-6N, W/OUT COVER, CAST STEEL	9B 4730 SA4593867	N		2/EA	3.4
010			M	TANK VENT VALVE, 5"IPS, BW, TATE TEMCO 52-20V-5IN, W/OUT COVER, CAST STEEL	9B 4730 SA4593868	N		6/EA	3.4
011			M	TANK VENT VALVE, 5"IPS, BW, TATE TEMCO 52-45V5, W/COVER, CAST STEEL	9B 4730 SA4798729	N		3/EA	3.4
012			M	TANK VENT VALVE, 5"IPS, BW, TATE TEMCO 52-40V5IN, W/OUT COVER, CAST STEEL	9B 4730 SAPYA0098	N		1/EA	3.4
013			M	TANK VENT VALVE, 4"IPS, BW, TATE TEMCO 52-40V-4IN, W/OUT COVER, CAST STEEL	9B 4730 SAPYA0097	N		1/EA	3.4
014			M	TANK VENT VALVE, 2-1/2"IPS, BW, TATE TEMCO 52-45V2-1/2, W/COVER, CAST STEEL	9B 4730 SA4798731	N		2/EA	3.4
043			M	TANK VENT VALVE, 2"IPS, BW, TATE TEMCO 52-20V-2IN, W/OUT COVER, CAST STEEL	9B 4820 SAPTE0035	N		1/EA	3.4
015			M	TANK VENT VALVE, 1-1/2"IPS, BW, TATE TEMCO 52-40V-1-1/2IN, W/COVER, CAST STEEL	9B 2040 011062926	N		1/EA	3.4
016			M	TANK VENT VALVE, 1-1/2"IPS, 52-40S W/40 MESH SCREEN, BRONZE	3B 4820 016547717	N		1/EA	3.4
017			M	180 DEG RETURN, 6"IPS, LR, SCH40, OPEN PATTERN, ANSI B16.9, C-STEEL	9B 4730 SAPNM0120	N		2/EA	3.4
018			M	180 DEG RETURN,, 5"IPS, LR, SCH40, OPEN PATTERN, ANSI B16.9, C-STEEL	9B 4730 SAPIK0049	N		2/EA	3.4
019			M	180 DEG RETURN, 4"IPS, LR, SCH40, OPEN PATTERN, ANSI B16.9, C-STEEL	9B 4730 SAPTA0229	N		1/EA	3.4
020			M	180 DEG RETURN, 2-1/2"IPS, LR, SCH40, OPEN PATTERN, ANSI B16.9, C-STEEL	9B 4730 SAPKA0020	N		1/EA	3.4
021			M	180 DEG RETURN, 1-1/2"IPS, LR, SCH40, OPEN PATTERN, ANSI B16.9, C-STEEL	9B 4730 SA5613157	N		1/EA	3.4
022			M	RETURN BEND, 1-1/2"IPS, SB, OPEN, BRZ, 400PSI, W/RING, MIL-F-1183/1-12	9B 4730 SAPTA0082	N		1/EA	3.4
023			M	RETURN BEND, 1" IPS, SB, TYPE A, OPEN, BRZ, 400PSI, MIL-F-1183/1-06A	9B 4730 014168560	N		1/EA	3.4
045			M	COUPLING, 2"IPS, ANSI B16.11, SW, 3000#, C-STL	9B 4730 008226539	N		1/EA	3.4
024			M	COUPLING, 1-1/2"IPS, SW, 3000#, ANSI B16.11, C-STEEL	9B 4730 011060796	N		1/EA	3.4
025			C	COUPLING, 1-1/2"IPS, SB, 400#, MIL-F-1183/3-07, BRONZE	9B 4730 005425106	N		4/EA	
026			C	COUPLING, 1"IPS, SB, 400#, MIL-F-1183/3-05, BRONZE	9B 4730 005425104	N		2/EA	
027			M	ELBOW, 90, LR, 6", ANSI B16.9, BW, SCH 40, CARBON STEEL	9B 4730 002871650	N		4/EA	3.4
028			M	ELBOW, 5" IPS, 90 LR, ANSI B16.9, C-STEEL, BW, SCH 40	9B 4730 010266451	N		6/EA	3.4

4/10

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA51217		A01

TITLE:

Overflow and Natural Vent Piping; inspect and replace


MATERIAL LIST									
ITEM NO.	PC NO.	REF NO.	M / C	DESCRIPTION	STOCK NUMBER	HAZ MAT	DOC NO.	QTY REQD/ UNIT	PARA NO.
029			M	ELBOW, 5"IPS, 90 DEG, SR, BW, ANSI B16.9, SCH40, C-STEEL	9B 4730 SA4801583	N		6/EA	3.4
030			M	ELBOW, 2-1/2"IPS, 90DEG SR, SW, #3000, ANSIB16.11, C-STEEL	9B 4730 SAPKA0003	N		2/EA	3.4
044			M	ELBOW, 2"IPS, 90 DEG, SR, SW, 3000#, ANSI B16.11, C-STEEL	9B 4730 000838773	N		3/EA	3.4
031			M	ELBOW, 1-1/2"IPS, 90 DEG, SR, SW, 3000#, ANSI B16.11, C-STEEL	9B 4730 008330291	N		2/EA	3.4
032			C	ELBOW, 1-1/2"IPS, 90DEG, SR, SB, 400#, MIL-F-1183/5-07, BRONZE	9B 4730 005425146	N		5/EA	
033			C	ELBOW, 1"IPS, 90 DEG, SR, SB, 400#, MIL-F-1183/5-05, BRONZE	9B 4730 005425144	N		2/EA	
046			C	BHD/DK SLEEVE, 2"IPS, 810-2145801, C-STEEL	9B 2040 002730690	N		2/EA	
034			C	BHD/DK SLEEVE, 2-1/2"IPS, 810-2145801, C-STEEL	9B 2040 002775784	N		2/EA	
035			C	BHD/DK SLEEVE, 1-1/2"IPS, 810-2145801, C-STEEL	9B 2040 002730689	N		4/EA	
036			C	BHD/DK SLEEVE, 1"IPS, 810-2145801, C-STEEL	9B 2040 002730687	N		2/EA	
037			M	WELDING ELECTRODE,, 1/16 X 36, MIL-70S-2, MIL-E-23765/1, CL.6, GTAW, 5 LB/CO	9B 3439 009008737	Y		1/CO	3.4
038			M	WELDING ELECTRODE,, 3/32 X 36, MIL-70S-2, MIL-E-23765/1, CL.6, GTAW	9B 3439 010172792	Y		1/CO	3.4
039			M	WELDING ELECTRODE, 1/16 X 36, MIL-RN60, MIL-E-21562, CL.2, GTAW	9B 3439 000887791	Y		1/BX	3.4
040			M	WELDING ELECTRODE, 3/32 X 36, MIL-RN60, MIL-E-21562, CL.2, GTAW	9B 3439 000888986	Y		1/BX	3.4
041			C	BRAZING ALLOY, 1/8" X 0.050" X 20", GR.III, STRIP, BCUP-5, QQ-B-654, 28 EA/LB	9B 3439 005288578	Y		1/LB	
042			C	BRAZING FLUX, O-F-499 TYPE B, GR.III & IV, 16 OZ/JR	9B 3439 009148390	Y		1/JR	
101			M	RUBBER SHEET SOLID, RUBBER SYSTHETIC OIL RESISTANT, MIL-R-900, 1/16"THK X 36"W X 48"L, 45-53 DURO-A	9B 9320 000574557	N		1/SH	3.1
102			M	NUT,PLAIN,HEXAGON, 3/8-16UNC-2B, STEEL ZINC,MIL-DTL-1222 TY-1 GR-5, 100EA/BX	9B 5310 012945273	N		1/BX	3.1
103			M	WASHER,FLAT, STEEL WASHER, ZINC-YELLOW-CHROMATE-PLATED, FOR 3/8" SCREW SIZE, 1.00" OD, THE SAME AS MCMASER P/N:98026A031	9B 5310 010831540	N		50/EA	3.1

5/10

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA51217		A01

TITLE:

Overflow and Natural Vent Piping; inspect and replace



ENCLOSURE (A) 1/3

6/10

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA51217		A01

TITLE:

Overflow and Natural Vent Piping; inspect and replace

STBD SIDE

- ① 2 Inch IPS Vent Piping for Seawater Ballast Tank (2-8-0-W), Including Vent Valve (52-20V), C-Steel
- ② 5 Inch IPS Vent Piping for Ramp Handling Machinery Compartment (2-12-0-Q), Including Vent Valve (52-45V), C-Steel
- ③ 5 Inch IPS Vent Piping for Seawater Ballast Tank (2-18-1-W), Including Vent Valve (52-20V), C-Steel
- ④ 5 Inch IPS Vent Piping for Equipment & Repair Parts Stores (2-40-0-A), Including Vent Valve (52-25V), C-Steel
- ⑤ 2-1/2 Inch IPS Vent Piping for Diesel Oil Tank (2-46-1-F), Including Vent Valve (52-20V), C-Steel
- ⑥ One Inch IPS Vent Piping for CHT System, CuNi 90/10
- ⑦ 1-1/2 Inch IPS Vent Piping for Sea Chest, Cuni 90/10
- ⑧ 1-1/2 Inch IPS Vent Piping for Sea Chest, Cuni 90/10
- ⑨ 5 Inch IPS vent Piping for Anchor Winch Compartment (2-62-0-Q), Including Vent Valve (52-20V), C-Steel

ENCLOSURE (A) ^{2/3}

7/10

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA51217		A01

TITLE:

Overflow and Natural Vent Piping; inspect and replace

PORT SIDE

- ⑩ 5 Inch IPS Vent Piping for Seawater Ballast Tank (2-18-2-W), Including Vent Valve (52-20V), C-Steel
- ⑪ 6 Inch IPS Vent Piping for Void Space (2-18-0-V), Including Vent Valve (52-20V), C-Steel
- ⑫ 5 Inch IPS Vent Piping for Flammable Liquid Storeroom (2-23-2-A), Including Vent Valve (52-20V), C-Steel
- ⑬ 4 Inch IPS Vent Piping for AC Room (2-28-2-Q), Including Vent Valve (52-40V), C-Steel
- ⑭ 1-1/2 Inch IPS Vent Piping for Magazine (2-40-2-M0, Including Vent Valve (52-40V), C-Steel
- ⑮ 5 Inch IPS Vent Piping for Equipment & Repair Parts Stores (2-40-0-A), Including Vent Valve (52-45V), C-Steel
- ⑯ 2-1/2 Inch IPS Vent Piping for Diesel Oil Tank (2-46-2-F), Including Vent Valve (52-45V), C-Steel
- ⑰ 1-1/2 Inch IPS Vent Piping for Oily Waste Tank Located in AFT Engine Room (2-56-0-E), Including Vent Valve (52-40S), CuNi
- ⑱ 5 Inch IPS Vent Piping for Seawater Ballast Tank (2-66-0-W), Including Vent Valve (52-20V), C-Steel
- ⑲ 5 Inch IPS Vent Piping for Seawater Ballast Tank (2-66-0-W), Including Vent Valve (52-20V), C-Steel

ENCLOSURE (A) ^{3/3}

8/10

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA51217		A01

TITLE:

Overflow and Natural Vent Piping; inspect and replace

General Requirements
For Tank, Void and/or Cofferdam Cleaning

Ver.05012021

1. REQUIREMENTS:

1.1 Open, ventilate, conduct gas free, empty, clean, render dry, and maintain each tank, void and/or cofferdam throughout the work item performance period.

1.1.1 Ensure that each harmful vapor, fume, and mist is ventilated to the exterior of the vessel.

(V) "REPORT"

1.1.1.1 Submit one legible copy of a report listing the location, origin, and quantity of each manhole cover removed in 1.1 with respect to its tank, ship's frame and distance off centerline to SUPERVISOR after the inspection.

1.1.2 Remove and dispose of waste liquid that is not being stored for reuse to a Government provided waste liquid conveyance.

1.1.2.1 Contact the SRF-JRMC Detachment Sasebo ESH Division, Environmental Branch, S106.3 prior to transfer of waste liquid to the conveyance.

1.1.2.2 Provide watches and following spill kits (absorbent pads, booms, etc. for oil or chemical spill containment) at each affected area where waste liquid is being transferred to ensure that each liquid is not released to any shipboard compartment or the sea. In case of a spill, take immediate action to contain the spill, and contact S106.3.

1.1.2.3 Identify each transfer hose to the conveyance by affixing the company's name and tank/space location pumping from on each hose.

1.1.2.4 Establish and maintain communication between the pumping station and the conveyance when the waste liquid is being transferred.

(V) "INSPECT PIPING AND HOSE ALIGNMENT"

1.1.2.5 Inspect alignment of each hose, valve and piping in the flow path prior to the start of pumping, purging, or flushing.

1.1.2.6 Accomplish a periodic walkthrough of each piping, hose, and valve alignment for leaks at least once an hour.

1.1.2.7 Pumping after sunset is not authorized unless approved by SUPERVISOR.

ENCLOSURE (T) 1/2

9/10

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA51217		A01

TITLE:

Overflow and Natural Vent Piping; inspect and replace

1.1.3 Coordinate the off-loading or transferring of each fluid through the ship's Damage Control Assistant (DCA), via SHIPSUPT, to maintain ship's stability and to prevent flooding.

(V) (G) "VISUAL INSPECTION"

1.2 Inspect each tank, void and/or cofferdam for cleanliness, prior to final closing. Document the personnel who were present during the inspection and confirm that they have exited the space prior to closure of each tank, void, and cofferdam. Designate one person to account for personnel who may have entered the space. -S130

1.2.1 Install each manhole cover for each tank, using each new gasket and fastener.

2. NOTES:

2.1 Booklet of General Plans and Tank Sounding Tables are available for review at the office of the SUPERVISOR.

2.2 The SUPERVISOR will provide a waste liquid conveyance to accumulate waste liquids in each tank for work being accomplished for SRF-JRMC availabilities.

2.3 See additional CHT/sewage tanks disinfection requirements of Local Standard Item 099-901YO for SRF-JRMC Sasebo availabilities.

10/10