Landing Page UI Test Report

Page: https://pcmdev.shearheavenpetspa.com/ (signed out). Front-end build index-C63CMm-c. Tested 12 Nov 2026 in Chromium at desktop 1440x900, tablet 768x1024 and mobile 375x812. Scope: layout, spacing, typography, imagery, components, responsiveness and visible content only - no API, backend or business-logic checks. Every issue below was verified on screen; red boxes in the screenshots mark the problem area.

Summary

Severity	Issues	Bug IDs
High	0	-
Medium	5	UI-LP-01, UI-LP-02, UI-LP-03, UI-LP-04, UI-LP-05
Low	14	UI-LP-06, UI-LP-07, UI-LP-08, UI-LP-09, UI-LP-10, UI-LP-11, UI-LP-12, UI-LP-13, UI-LP-14, UI-LP-15, UI-LP-16, UI-LP-17, UI-LP-18, UI-LP-19
Total	**19**	

ID	Section	Issue	Sev	Viewports
UI-LP-01	Header / Hero (page load)	Developer 'demo content' banner and placeholder store shown on first load	Medium	Desktop 1440x900; Mobile 375x812
UI-LP-02	Why Choose Us (feature cards)	All four feature cards repeat the same description text	Medium	Desktop 1440x900; Tablet 768x1024; Mobile 375x812
UI-LP-03	Stats grid ('Zero Toxins' tile)	'Zero Toxins' heading overlaps the puppy image on tablet	Medium	Tablet 768x1024
UI-LP-04	Meet Our Certified Pet Stylists	'Book Stylist' button overlaps the 'Pet Parents Rating' label and spills outside the card on tablet	Medium	Tablet 768x1024
UI-LP-05	Navigation drawer (tablet/mobile)	Floating 'Chat' button stays on top of the open navigation menu	Medium	Tablet 768x1024; Mobile 375x812
UI-LP-06	Global - floating Chat button	Floating 'Chat' button covers page content and footer links	Low	Desktop 1440x900; Tablet 768x1024; Mobile 375x812
UI-LP-07	Footer - Contact Details	Email address breaks in the middle of the domain	Low	Desktop 1440x900
UI-LP-08	Signature Spa & Salon Services	Every service card uses the same placeholder photo	Low	Desktop 1440x900; Tablet 768x1024; Mobile 375x812
UI-LP-09	Services / Packages / Stylists	Card rows with only 1-2 items are left-aligned, leaving large empty areas	Low	Desktop 1440x900
UI-LP-10	Meet Our Certified Pet Stylists	Carousel arrows shown and active although every stylist is already visible	Low	Desktop 1440x900
UI-LP-11	Signature Spa & Salon Services - category tabs	Tab label typo: 'Baths & Fluff Day'	Low	Desktop 1440x900; Tablet 768x1024; Mobile 375x812
UI-LP-12	Hero	Stray space in hero copy: 'stress- free'	Low	Desktop 1440x900; Tablet 768x1024; Mobile 375x812
UI-LP-13	Footer - copyright bar	Copyright text grammar: 'All Right Reserved'	Low	Desktop 1440x900; Tablet 768x1024; Mobile 375x812
UI-LP-14	Global typography	Inconsistent text casing and heading weights	Low	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

ID	Section	Issue	Sev	Viewports
UI-LP-15	'Ready to Give Your Dog the Care They Deserve?' strip	Image strip ignores the page gutter and runs to the screen edges	Low	Desktop 1440x900
UI-LP-16	Footer - Spa Treatments	Footer lists demo treatments that do not exist in the services section	Low	Desktop 1440x900; Tablet 768x1024; Mobile 375x812
UI-LP-17	Reviews	Every testimonial shows 4 of 5 stars next to a '10K+ Five Star Reviews' claim	Low	Desktop 1440x900; Tablet 768x1024; Mobile 375x812
UI-LP-18	Services - category tabs (tablet/mobile)	Category tab bar is cut off mid-label with no scroll cue	Low	Tablet 768x1024; Mobile 375x812
UI-LP-19	All Inclusive Spa Packages	Only package carries a 'Most Recommended' badge and a redundant price note	Low	Desktop 1440x900; Tablet 768x1024; Mobile 375x812


Checked and found OK (not reported): no horizontal page overflow at 375/768/1440 px; no broken images; header, sticky navigation and mobile drawer layout; hero buttons; footer columns on tablet and mobile; email wrap on tablet/mobile; stylist cards on mobile; app-download banner at all sizes.

UI-LP-01 - Developer 'demo content' banner and placeholder store shown on first load


Bug ID	UI-LP-01	Severity	Medium
Page / Section	Landing page - Header / Hero (page load)	Viewport(s)	Desktop 1440x900; Mobile 375x812

Steps to reproduce	1. Open https://pcmdev.shearheavenpetspa.com/ in a fresh tab (signed out). 2. Watch the top of the page while it loads (first ~1 s).
Actual result	A black bar reading 'Showing demo content - start PetCareServer on port 3464 for live data.' appears above the header, and the location bar shows 'Prices and packages shown for: Shear Heaven Pet Spa' with no store selector. A moment later the bar disappears, the page shifts up and the location bar switches to the 'QA Auto Store Edited' dropdown (visible layout shift).
Expected result	No developer/debug message is ever shown to visitors; the location bar renders in its final state (or a neutral skeleton) without content jumping.

Evidence



Desktop, first paint




Mobile, first paint

UI-LP-02 - All four feature cards repeat the same description text

Bug ID	UI-LP-02	Severity	Medium
Page / Section	Landing page - Why Choose Us (feature cards)	Viewport(s)	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Open the landing page. 2. Scroll to the four cards under 'Pet Care Redefined With Love & Dignity'.
Actual result	'Fear Free Certified Handling', 'Hospital Grade Sanitation', 'All Natural Botanical Shampoos' and 'One On One Dedicated Attention' all show the identical copy 'Low-Stress Techniques, Calming Lavender Diffusers, And Warm Gentle Dryers That Eliminate Pet Anxiety.'
Expected result	Each card has its own description matching its heading (e.g. sanitation copy under 'Hospital Grade Sanitation').

Evidence



Desktop - same text in all four cards

UI-LP-03 - 'Zero Toxins' heading overlaps the puppy image on tablet


Bug ID	UI-LP-03	Severity	Medium
Page / Section	Landing page - Stats grid ('Zero Toxins' tile)	Viewport(s)	Tablet 768x1024

Steps to reproduce	1. Set the viewport to 768x1024 (tablet). 2. Scroll to the stats grid below 'Explore Salon Experiences'.
Actual result	The 'Zero Toxins' heading and 'using 100% Organic Products' text are drawn on top of the spaniel image - the 'Z' and 'O' sit over the dog's ear.
Expected result	Text and image sit side by side (or stack) with clear spacing; no overlap at any breakpoint. (Desktop and mobile render correctly.)

Evidence



Tablet - zoomed




Tablet - stats grid

UI-LP-04 - 'Book Stylist' button overlaps the 'Pet Parents Rating' label and spills outside the card on tablet


Bug ID	UI-LP-04	Severity	Medium
Page / Section	Landing page - Meet Our Certified Pet Stylists	Viewport(s)	Tablet 768x1024

Steps to reproduce	1. Set the viewport to 768x1024. 2. Scroll to 'Meet Our Certified Pet Stylists'.
Actual result	In both stylist cards the 'Book Stylist' button covers the second stat label ('Pet Parer...' is cut off) and its right edge extends past the white info panel.
Expected result	Stats and button fit inside the panel without overlap (wrap the button below the stats on narrow widths, as mobile already does).

Evidence



Tablet - zoomed




Tablet - both cards

UI-LP-05 - Floating 'Chat' button stays on top of the open navigation menu

Bug ID	UI-LP-05	Severity	Medium
Page / Section	Landing page - Navigation drawer (tablet/mobile)	Viewport(s)	Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Set the viewport to 768x1024 (or 375x812). 2. Tap the menu icon (four dots) at the top right.
Actual result	The menu drawer and dark overlay open, but the 'Chat' pill is still drawn above them in the bottom-right corner (chat z-index 10000 vs drawer 99).
Expected result	The open menu (and its overlay) sits above all floating widgets, or the chat button is hidden while the menu is open.

Evidence




Tablet - menu open

UI-LP-06 - Floating 'Chat' button covers page content and footer links


Bug ID	UI-LP-06	Severity	Low
Page / Section	Landing page - Global - floating Chat button	Viewport(s)	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Open the landing page at any size. 2. Scroll through the sections and to the footer.
Actual result	The fixed 'Chat' pill hides content beneath it: card text in 'Why Choose Us' ('...Eliminate Pet Anxiety'), 'Terms & Conditions' in the footer bar, and on mobile the '100% Organic, Cruelty Free Botanicals Used' badge.
Expected result	Enough bottom padding/safe area so the floating button never sits on top of text or links (especially at the page end).

Evidence



Desktop footer




Mobile - badge covered

UI-LP-07 - Email address breaks in the middle of the domain

Bug ID	UI-LP-07	Severity	Low
Page / Section	Landing page - Footer - Contact Details	Viewport(s)	Desktop 1440x900

Steps to reproduce	1. Open the landing page at 1440 px width. 2. Scroll to the footer 'Contact Details' column.
Actual result	'shearheaven.dwg@gmail.c' is shown on one line and 'om' on the next (word-break: break-all on the email).
Expected result	The address wraps only at sensible points (e.g. before '@') or the column is wide enough to keep it on one line.

Evidence




Desktop footer

UI-LP-08 - Every service card uses the same placeholder photo

Bug ID	UI-LP-08	Severity	Low
Page / Section	Landing page - Signature Spa & Salon Services	Viewport(s)	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Open the landing page. 2. Scroll to 'Signature Spa & Salon Services' (All Services tab).
Actual result	'QA Full Groom' and 'QA OddDur' show the identical corgi photo (svc_spa.png, upscaled ~1.7x from 356x424).
Expected result	Each service shows its own image (or a clearly generic category image), at sufficient resolution.

Evidence




Desktop

UI-LP-09 - Card rows with only 1-2 items are left-aligned, leaving large empty areas


Bug ID	UI-LP-09	Severity	Low
Page / Section	Landing page - Services / Packages / Stylists	Viewport(s)	Desktop 1440x900

Steps to reproduce	1. Open the landing page at 1440 px. 2. Scroll through Services, Spa Packages and Meet Our Stylists.
Actual result	2 service cards, 1 package card and 2 stylist cards hug the left edge of a 3-4 column grid; the right half of each section is empty while the section headings above are centred.
Expected result	Cards are centred (or the grid adapts) so sections with few items look balanced.

Evidence



Services




Packages

UI-LP-10 - Carousel arrows shown and active although every stylist is already visible

Bug ID	UI-LP-10	Severity	Low
Page / Section	Landing page - Meet Our Certified Pet Stylists	Viewport(s)	Desktop 1440x900

Steps to reproduce	1. Open the landing page at 1440 px. 2. Scroll to 'Meet Our Certified Pet Stylists'.
Actual result	Previous/Next arrows are displayed (enabled, full opacity) under two cards that already fit on screen; the arrows are centred on the page while the cards are left-aligned.
Expected result	Hide or disable the arrows when there is nothing to scroll, and align them with the carousel.

Evidence




Desktop

UI-LP-11 - Tab label typo: 'Baths & Fluff Day'

Bug ID	UI-LP-11	**Severity**	Low
Page / Section	Landing page - Signature Spa & Salon Services - category tabs	**Viewport(s)**	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Open the landing page. 2. Look at the category tabs under 'Signature Spa & Salon Services'.
Actual result	Second tab reads 'Baths & Fluff Day'.
Expected result	'Baths & Fluff Dry' (the grooming term used elsewhere in the app).

Evidence




Desktop

UI-LP-12 - Stray space in hero copy: 'stress- free'

Bug ID	UI-LP-12	Severity	Low
Page / Section	Landing page - Hero	Viewport(s)	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Open the landing page. 2. Read the paragraph under the hero heading.
Actual result	Text reads 'stress- free breed styling' (space after the hyphen).
Expected result	'stress-free breed styling'.

Evidence



Desktop

UI-LP-13 - Copyright text grammar: 'All Right Reserved'

Bug ID	UI-LP-13	Severity	Low
Page / Section	Landing page - Footer - copyright bar	Viewport(s)	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Scroll to the bottom of the landing page.
Actual result	'(c) 2026 Shear Heaven Pet Spa. All Right Reserved.'
Expected result	'All Rights Reserved.'

Evidence




Desktop

UI-LP-14 - Inconsistent text casing and heading weights

Bug ID	UI-LP-14	Severity	Low
Page / Section	Landing page - Global typography	Viewport(s)	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Scroll through the landing page and compare section subtitles and paragraphs.
Actual result	Long paragraphs and subtitles are Title-Cased word by word ('For Over 20 Years, Shear Heaven Pet Spa Has Been A Trusted...', footer about text, review/stylist/package subtitles) while others are sentence case (hero copy, 'Ready to Give Your Dog...', 'Dogs & cats needing full pampering' vs 'Dogs & Cats Needing Full Pampering'). The newsletter heading uses weight 700 while every other section heading uses 500.
Expected result	One casing rule (sentence case for body copy) and one weight for section headings across the page.

Evidence




Desktop - Title Case paragraph

UI-LP-15 - Image strip ignores the page gutter and runs to the screen edges

Bug ID	UI-LP-15	Severity	Low
Page / Section	Landing page - 'Ready to Give Your Dog the Care They Deserve?' strip	Viewport(s)	Desktop 1440x900

Steps to reproduce	1. Open the landing page at 1440 px. 2. Scroll to the 'Ready to Give Your Dog...' strip above Spa Packages.
Actual result	The outer dog photos start 10 px from the left edge and end 10 px from the right edge, while every other section is inset 80 px, so the strip looks misaligned with the content above and below.
Expected result	The strip aligns with the same container width/gutter as the other sections (or is intentionally full-bleed with matching padding).

Evidence




Desktop

UI-LP-16 - Footer lists demo treatments that do not exist in the services section

Bug ID	UI-LP-16	Severity	Low
Page / Section	Landing page - Footer - Spa Treatments	Viewport(s)	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Note the services shown in 'Signature Spa & Salon Services'. 2. Scroll to the footer 'Spa Treatments' column.
Actual result	Footer shows 'The Royal Spa Sanctuary', 'Full Luxury Scissor Styling' and 'Hydro Aroma Bubbly' (name looks truncated), none of which appear in the page's service list.
Expected result	Footer links reflect the real services offered (or generic category links).

Evidence




Desktop footer

UI-LP-17 - Every testimonial shows 4 of 5 stars next to a '10K+ Five Star Reviews' claim

Bug ID	UI-LP-17	Severity	Low
Page / Section	Landing page - Reviews	Viewport(s)	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Scroll to the stats grid ('10K+ Five Star Reviews'). 2. Scroll to 'Loved By Thousands Of Pet Parents'.
Actual result	All review cards display 4 filled stars and 1 empty star.
Expected result	Star ratings shown are consistent with the headline claim (or the claim is reworded).

Evidence




Desktop

UI-LP-18 - Category tab bar is cut off mid-label with no scroll cue

Bug ID	UI-LP-18	Severity	Low
Page / Section	Landing page - Services - category tabs (tablet/mobile)	Viewport(s)	Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Set the viewport to 768x1024 or 375x812. 2. Scroll to the category tabs under 'Signature Spa & Salon Services'.
Actual result	The pill bar is clipped at the right edge ('Therapeutic Spa' cut on tablet, 'Haircuts' cut on mobile; 'Nails & Dental' not visible) with no arrow, fade or other hint that it scrolls.
Expected result	Tabs wrap, or show a clear horizontal-scroll affordance (edge fade/arrow).

Evidence




Tablet

UI-LP-19 - Only package carries a 'Most Recommended' badge and a redundant price note

Bug ID	UI-LP-19	Severity	Low
Page / Section	Landing page - All Inclusive Spa Packages	Viewport(s)	Desktop 1440x900; Tablet 768x1024; Mobile 375x812

Steps to reproduce	1. Scroll to 'All Inclusive Spa Packages' (signed out).
Actual result	The single package card is labelled 'Most Recommended' and shows '$80.00 (from $80 by pet size)'.
Expected result	A 'recommended' badge only when there are alternatives; price shown once (e.g. 'From $80').

Evidence



Desktop