



Native OpenFOAM JFO — 4000 rpm cavitation severity



Current model diagnostic: rupture means $\theta_{\text{fill}} < 1$; external validation pending.