



Native OpenFOAM JFO — 2000 rpm cavitation severity



Current model diagnostic: rupture means $\theta_{fill} < 1$; external validation pending.