
Reported flood places: mean rank 84 at street scale (p < 0.001)
vs 69 with census-section values (paired p = 0.010, n = 13)
Rank of each place
street scale — street (Cadastre addresses)
street scale — exact spot or road (OpenStreetMap)
street scale — approximate location
census-section scale (sub-city units)
calle San Gregorio (2023-06-21) · 35 % flooded
calle Clavijo, bajo la N-111 (2018-09-17) · 36 % flooded
calle Clavijo (2018-09-17) · 10 % flooded
CARPA (Urgencias) (2023-06-21) · 6 % flooded
calle Clavijo, cerca del Palacio de Deportes (2023-06-21) · 6 % flooded
LO-20 (2018-09-17) · 5 % flooded
calle Ebro (2023-06-21) · 5 % flooded
rotonda de club Deportivo (2024-10-16) · 1 % flooded
LO-20, bajo la rotonda de la calle Chile (2023-06-21) · 1 % flooded
avenida de Burgos (2024-10-16) · 0.8 % flooded
el Adarraga (2018-09-17) · 0.6 % flooded
avenida Colón (2023-06-21, 2024-10-16) · 0.5 % flooded
Paseo del Espolón (2024-10-16) · 0 % flooded
typical street
← drier
more flooded →
0
20
40
60
80
100
More flooded in the model than …% of Logroño's other 512 streets
(share of nearby open ground under ≥ 30 cm, 100-year storm)


Same for every design storm
(all p < 0.001)
vs central streets
vs all streets
no better than chance
Mean rank of the 13 places (street scale)
0
20
40
60
80
100
2
5
10
25
50
100
200
Design storm return period (years)