

# Certified Test Report

Report No.: 2019-0479F

Date of Report: 10/21/2016

Requested by: WIZNET

Type of Product: WizFi360 (Model: PA)

This report was prepared and certified by Korea Electronics Technology Institute



## Korea Electronics Technology Institut

The product tested in this report has been provided by the test request. The information contained in this report is designed to improve and enhance the quality level of the product. But, it is provided with the understanding that the requester is not engaged in rendering legal, accounting, engineering, or other professional services. KETI disclaims any responsibility or liability fot the use of this information outside of its original purpose.

# **Summary of Test**

#### 1. Customer Information

Company Name	WIZNET				
Name of President/CEO	Lee Yun Bong				
Company Address	5F Hunmax village, 216 Hwangsaeul-ro, Bundang-Gu, Seongnam-Si, Gyeonggi-Do				
Contact Person	Seo Ji hoon	Request Received	9/16/2019		
Type of Specimen	WizFi360 (Model: PA)	No. of Specimen	1 ea		
Purpose of Test	Reliability test				
Total Page	7 Pages				

#### 2. Test

2. 1000						
Test Item	Low tepmperature operation test and 4 other cases					
Test Method	To summit customer					
Test Result	See test result					
Testing Time	9/26/2019 ~ 10/17/2019					
Room Environment	Temperature	(25 ± 10) ℃	Humidity	75 % R.H. and below		
	Prepared by		Reviewed by			
(Technical personnel)		(Technical manager)				
Hyunwoo Park (sign)		Kwanhun Lee (sign)				

### **Test Result**

1. Purpose of Test: Reliability test

2. Specimen: WizFi360 (Model: PA)





3. Specimen Sampling Method: Provided by the applicant

#### 4. Test Description

Test Item	est Item Test Condition				
Low tepmperature operation test	$(-40 \pm 2)$ °C, 16 h, Check operation before, during and after test				
High tepmperature operation test	$(85 \pm 2)$ °C, 16 h, Check operation before, during and after test				
Humidity operation test	$(55 \pm 2)$ °C, $(95 \pm 3)$ % R.H., 48 h, Check operation before, during and after test				
$(25 \pm 2) \text{ °C}, 2 \text{ h}, (25 \pm 2) \text{ °C} \rightarrow (85 \pm 2) \text{ °C}, 2 \text{ h},$ $(85 \pm 2) \text{ °C}, 4 \text{ h}, (85 \pm 2) \text{ °C} \rightarrow (25 \pm 2) \text{ °C}, 2 \text{ h},$ $(25 \pm 2) \text{ °C}, 4 \text{ h}, (25 \pm 2) \text{ °C} \rightarrow (85 \pm 2) \text{ °C}, 2 \text{ h},$ $(25 \pm 2) \text{ °C}, 4 \text{ h}, (25 \pm 2) \text{ °C} \rightarrow (85 \pm 2) \text{ °C}, 2 \text{ h},$ $(85 \pm 2) \text{ °C}, 4 \text{ h}, (85 \pm 2) \text{ °C} \rightarrow (25 \pm 2) \text{ °C}, 2 \text{ h},$ $(25 \pm 2) \text{ °C}, 2 \text{ h}, (95 \pm 3) \text{ % R.H., Check operation}$ before, during and after test					
Rapid change of temperature operation test	$(-40 \pm 2)$ °C $\leftrightarrow$ $(85 \pm 2)$ °C each 3 h 5 cycles Check				

#### 5. Test Equipment

① Low tepmperature operation test, High tepmperature operation test, Humidity operation test, Humidity cycling operation test

Climatics chamber 2221HA (A26) (Climats, France)







2 Rapid change of temperature operation test

Thermal shock chamber TSA-101S (W06) (ESPEC, japan)







#### 6. Testing Time

① Low temperature operation test :  $09/26/2019 \sim 09/27/2019$ 

② High tepmperature operation test :  $09/27/2019 \sim 09/28/2019$ 

(3) Humidity operation test :  $09/30/2019 \sim 10/02/2019$ 


4 Humidity cycling operation test :  $10/03/2019 \sim 10/05/2019$ 

 $\bigcirc$  Rapid change of temperature operation test :  $10/16/2019 \sim 10/17/2019$ 

#### 7. Result

- ① Before, during & after the test, any specified defect or damage to the case was not found by visual inspection and all specimen was operated properly.
- Operation check pictures







- 2 Test Log Profile.
- Low temperature operation test




#### - High temperature operation test



#### - Humidity operation test



#### - Humidity cycling operation test



#### - Rapid change of temperature operation test

