

Certified Test Report

Report No.: 2019-0481F

Date of Report: 10/21/2016

Requested by: WIZNET

Type of Product: WizFi630S

This report was prepared and certified by Korea Electronics Technology Institute



Korea Electronics Technology Institute

The product tested in this report has been provided by the test request. The information contained in this report is designed to improve and enhance the quality level of the product. But, it is provided with the understanding that the requester is not engaged in rendering legal, accounting, engineering, or other professional services. KETI disclaims any responsibility or liability fot the use of this information outside of its original purpose.

Summary of Test

1. Customer Inf	formation				
Company Name	WIZNET				
Name of President/CEO	Lee Yun Bong				
Company Address	5F Hunmax village, 216 Hwangsaeul-ro, Bundang-Gu, Seongnam-Si, Gyeonggi-Do				
Contact Person	Seo Ji hoon		Request Received	9/16/2019	
Type of Specimen	WizFi630S		No. of Specimen	1 ea	
Purpose of Test	Reliability test				
Total Page	7 Pages				
2. Test		(a)			
Test Item	Low temperature test and 4 other cases				
Test Method	To summit cus	tomer		Ta.	
Test Result	See test result				
Testing Time	9/25/2019 ~ 10	/8/2019			
Room Environment	Temperature	(25 ± 10) ℃	Humidity	75 % R.H. and below	
Prepared by		Reviewed by			
(Technical personnel) /		(Technical manager)			

Hyunwoo Park


(sign)

Kwanhun Lee

Test Result

1. Purpose of Test: Reliability test

2. Specimen: WizFi630S





3. Specimen Sampling Method: Provided by the applicant

4. Test Description

Test Item	Test Condition			
Low temperature test	(-25 ± 2) °C, 16 h, Check operation before and after test			
High temperature test	(85 \pm 2) °C, 16 h, Check operation before and after test			
Humidity test (55 \pm 2) °C, (95 \pm 3) % R.H., 48 h, Check operation before and after test		1 ea		
Humidity cycling test $(25 \pm 2) \text{ °C, } 2 \text{ h, } (25 \pm 2) \text{ °C} \rightarrow (85 \pm 2) \text{ °C, } 2 \text{ h} \\ (85 \pm 2) \text{ °C, } 4 \text{ h, } (85 \pm 2) \text{ °C} \rightarrow (25 \pm 2) \text{ °C, } 2 \text{ h} \\ (25 \pm 2) \text{ °C, } 4 \text{ h, } (25 \pm 2) \text{ °C} \rightarrow (85 \pm 2) \text{ °C, } 2 \text{ h} \\ (85 \pm 2) \text{ °C, } 4 \text{ h, } (85 \pm 2) \text{ °C} \rightarrow (25 \pm 2) \text{ °C, } 2 \text{ h} \\ (85 \pm 2) \text{ °C, } 4 \text{ h, } (85 \pm 2) \text{ °C} \rightarrow (25 \pm 2) \text{ °C, } 2 \text{ h} \\ (25 \pm 2) \text{ °C, } 2 \text{ h, } (95 \pm 3) \text{ % R.H., Check operators}$ before and after test				
Rapid change of (-25 ± 2) °C \leftrightarrow (85 ± 2) °C, each 3 h, 5 cycles, Check temperature test operation before and after test				

5. Test Equipment

1 Low temperature test, High temperature test, Humidity test

EX5425-HE (W08) (Climats, France)







2 Humidity cycling test

Climatics chamber 2221HA (A26) (Climats, France)







3 Rapid change of temperature test

Thermal shock chamber 120CT (W14) (Climats, France)







6. Testing Time

① Low temperature test : $09/25/2019 \sim 09/26/2019$

② High temperature test : $09/26/2019 \sim 09/27/2019$

(3) Humidity test : $09/27/2019 \sim 09/29/2019$


4 Humidity cycling test : $10/03/2019 \sim 10/05/2019$

Solution Rapid change of temperature test $10/07/2019 \sim 10/08/2019$

7. Result

- ① Before & after the test, any specified defect or damage to the case was not found by visual inspection and all specimen was operated properly.
 - Operation check pictures







- 2 Test Log Profile.
- Low temperature test




- High temperature test



- Humidity test



- Humidity cycling test



- Rapid change of temperature test

