Technical BulletinModel 6 Cyl.Group 6SubjectPart Identifier Care of Targa Roof Cover StripsPart Identifier 6636Number 9604


ATTENTION: Service Manager / Service Technician

Models Affected: Model Year 1996 911 Targa

Concern: When cleaning the cover strips on the Targa roof, it is very important to

clean them only with a soap and water solution. Petroleum cleaning products used on the cover strips or any other plastic parts can cause

them to become brittle and crack.



Parts Information:

Part Number 993 562 513 00 993 562 514 00 **Description**Left side cover strip
Right side cover strip

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Varioram® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.

