
RAPID DISASTER SITUATION REPORT (SITREP)

Educational Prototype

Event Date: **2024-07-02** | Satellite: **2024-07-04 to 2024-07-11** | AOI: **[92.85, 26.55, 93.10, 26.75]**

17.36 km²	9	0	5
OBSERVED HAZARD	FLOODED BUILDINGS	FLOODED BRIDGES	CUT-OFF SETTLEMENTS

1. WHERE DID THE FLOOD HIT?



Satellite change detection & damage extent

Satellite analysis identifies **17.36 km²** of directly observed hazard extent and **0.0 km²** inferred along tributaries. Affected stretch extends along **Brahmaputra** from near **Chutia** to near **Kuwarital** (Sensors: Pre 2024-06-21 to 2024-07-01 / Post 2024-07-04 to 2024-07-11).

3. WHO IS CUT OFF?

5 settlements cut off from any town or hospital by road (pessimistic: **5**). **5 settlements** have no ground access (dual vehicle & walking severed).

No-Ground-Access Settlements (Air / Boat Priority)

Settlement	Lat, Lon	Bld
Near Silghat (6.1 km)	26.5992, 92.9868	**20**
Near Silghat (6.6 km)	26.6054, 92.9921	**13**
Near Silghat (6.4 km)	26.6048, 92.9900	**10**
Near Silghat (6.3 km)	26.5989, 92.9893	**5**
Near Silghat (7.0 km)	26.6101, 92.9960	**5**

5 Largest Road Cut-Off Settlements

Settlement	Lat, Lon	Bld
Near Silghat (6.1 km)	26.5992, 92.9868	**20**
Near Silghat (6.6 km)	26.6054, 92.9921	**13**
Near Silghat (6.4 km)	26.6048, 92.9900	**10**
Near Silghat (6.3 km)	26.5989, 92.9893	**5**
Near Silghat (7.0 km)	26.6101, 92.9960	**5**

2. WHAT WAS DAMAGED?

Asset	Flooded	Damaged	Cloud-Unv.	Total
Buildings	**9**	4	0	2191
Bridges	**0**	0	0	22
Roads (km)	**2.74**	1.35	0.0	381.43

- Major road damage: **track: 1.56 km** (Total 2.74 km flooded, 1.35 km possibly damaged, 0.0 km unverified under clouds).
- Major corridor bridges destroyed: none on primary roads.

4. WHAT TO REPAIR FIRST

- Best single repair: way/1196159793, 354 m -> 5 settlements (53 buildings).
- **Package 1 (1 elements, 353.7 m) restores vehicle access to 5 settlements (53 buildings).**

Known Data Limitations:

- 0 buildings and 0.0 km roads remain unverified under cloud cover.
- Drainage hazard hydraulically inferred; radar shadow/layover masked with DEM look-angle.
- Asset baseline derived from pre-event OpenStreetMap; census population not included.

Contains modified Copernicus Sentinel data 2024. Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved. © OpenStreetMap contributors under ODbL. European Union, Copernicus Emergency Management Service data (EMSR927, EMSR692, EMSR659). Bountos et al., 2024 (Kuro Siwo). Educational prototype, not an operational tool.