
RAPID DISASTER SITUATION REPORT (SITREP)

Educational Prototype

Event Date: **2026-08-26** | Satellite: **2026-08-27 to 2026-09-01** | AOI: **[85.30, 28.10, 85.42, 28.25]**

1.08 km²	107	12	44
OBSERVED HAZARD	DESTROYED BUILDINGS	DESTROYED BRIDGES	CUT-OFF SETTLEMENTS



1. WHERE DID THE FLOOD HIT?

Satellite analysis identifies **1.08 km²** of directly observed hazard extent and **1.07 km²** inferred along tributaries. Affected stretch extends along **Bhote Koshi** from near **Dalphedi** to near **Sano Bharkhu** (Sensors: Pre 2026-08-12 to 2026-08-24 / Post 2026-08-27 to 2026-09-01).

2. WHAT WAS DAMAGED?

Asset	Destroyed	Damaged	Cloud-Unv.	Total
Buildings	**107**	42	1196	3738
Bridges	**12**	1	2	27
Roads (km)	**5.98**	4.39	32.21	104.6

- Major road damage: **Pasang Lhamu Highway (NH42): 4.42 km** (Total 5.98 km destroyed, 4.39 km possibly damaged, 32.21 km unverified under clouds).
- Major corridor bridges destroyed: NH42, NH18.

3. WHO IS CUT OFF?

44 settlements cut off from any town or hospital by road (pessimistic: **44**). **4 settlements** have no ground access (dual vehicle & walking severed).

No Ground Access (Air / Boat Priority)

Settlement	Lat, Lon	Bld
Near Dalphedi (डाल्फेडी) (1.5 km)	28.2419, 85.3586	**24**
Near Dalphedi (डाल्फेडी) (1.2 km)	28.2391, 85.3577	**16**
Near Dalphedi (डाल्फेडी) (1.1 km)	28.2377, 85.3588	**14**
Near Lingling (लिङलिङ) (2.0 km)	28.1962, 85.3463	**6**

5 Largest Road Cut-Off Settlements

Settlement	Lat, Lon	Bld
Aamachhodingmo (आमाछोदिङ्मो)	28.1706, 85.3131	**330**
Near Bahun Danda (बाहुनडाँडा) (1.4 km)	28.1631, 85.3359	**260**
Near Bhrajam (भ्रजम) (1.6 km)	28.1833, 85.3019	**95**
Near Lingling (लिङलिङ) (1.6 km)	28.1991, 85.3667	**92**
Near Aamachhodingmo (आमाछोदिङ्मो) (1.3 km)	28.1807, 85.3062	**59**

4. WHAT TO REPAIR FIRST

- Best single repair: Pasang Lhamu Highway (NH42), way/248705796, 265 m -> 2 settlements (38 buildings).
- **Package 1 (4 elements, 1021.1 m) restores vehicle access to 19 settlements (939 buildings).**

Known Data Limitations:
- 1196 buildings and 32.21 km roads remain unverified under cloud cover.
- Drainage hazard hydraulically inferred; radar shadow/layover masked with DEM look-angle.
- Asset baseline derived from pre-event OpenStreetMap; census population not included.

Contains modified Copernicus Sentinel data 2026. Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved. © OpenStreetMap contributors under ODbL. European Union, Copernicus Emergency Management Service data (EMSR927, EMSR692, EMSR659). Bountos et al., 2024 (Kuro Siwo). Educational prototype, not an operational tool.