
RAPID DISASTER SITUATION REPORT (SITREP)

Educational Prototype

Event Date: **2021-06-15** | Satellite: **2021-06-16 to 2021-06-24** | AOI: **[85.53, 27.80, 85.62, 27.95]**

0.9 km²	72	4	5
OBSERVED HAZARD	DESTROYED BUILDINGS	DESTROYED BRIDGES	CUT-OFF SETTLEMENTS

1. WHERE DID THE FLOOD HIT?



Satellite change detection & damage extent

Satellite analysis identifies **0.9 km²** of directly observed hazard extent and **0.99 km²** inferred along tributaries. Affected stretch extends along **Indrawati river** from near **Dongdhing** to near **Sikharpur** (Sensors: Pre 2021-06-04 to 2021-06-14 / Post 2021-06-16 to 2021-06-24).

3. WHO IS CUT OFF?

5 settlements cut off from any town or hospital by road (pessimistic: **16**). **5 settlements** have no ground access (dual vehicle & walking severed).

No-Ground-Access Settlements (Air / Boat Priority)

Settlement	Lat, Lon	Bld
Melamchi	27.8291, 85.5759	**150**
Local Settlement	27.8669, 85.5541	**56**
Near Gyalthum (3.5 km)	27.9129, 85.5495	**12**
Near Gyalthum (3.4 km)	27.9115, 85.5477	**5**
Near Talamarang (0.6 km)	27.8449, 85.5557	**5**

5 Largest Road Cut-Off Settlements

Settlement	Lat, Lon	Bld
Melamchi	27.8291, 85.5759	**150**
Local Settlement	27.8669, 85.5541	**56**
Near Gyalthum (3.5 km)	27.9129, 85.5495	**12**
Near Gyalthum (3.4 km)	27.9115, 85.5477	**5**
Near Talamarang (0.6 km)	27.8449, 85.5557	**5**

2. WHAT WAS DAMAGED?

Asset	Destroyed	Damaged	Cloud-Unv.	Total
Buildings	**72**	57	9785	17492
Bridges	**4**	7	18	39
Roads (km)	**4.24**	4.39	246.52	423.42

- Major road damage: **track: 1.88 km** (Total 4.24 km destroyed, 4.39 km possibly damaged, 246.52 km unverified under clouds).
- Major corridor bridges destroyed: F30.

4. WHAT TO REPAIR FIRST

- Best single repair: F30, way/341952352, 371 m -> 2 settlements (17 buildings).
- **Package 1 (1 elements, 371.0 m) restores vehicle access to 2 settlements (17 buildings).**

Known Data Limitations:

- 9785 buildings and 246.52 km roads remain unverified under cloud cover.
- Drainage hazard hydraulically inferred; radar shadow/layover masked with DEM look-angle.
- Asset baseline derived from pre-event OpenStreetMap; census population not included.

Contains modified Copernicus Sentinel data 2021. Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved. © OpenStreetMap contributors under ODbL. European Union, Copernicus Emergency Management Service data (EMSR927, EMSR692, EMSR659). Bountos et al., 2024 (Kuro Siwo). Educational prototype, not an operational tool.