



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

Client: John Kajkowski
Property: 906 Walnut Ave
Bensalem, PA 19020

Home: (267) 767-3784

Operator: TRISTATE

Estimator: Gary Poltonowicz
Company: MDL Restoration Inc
Business: 606 WM Leigh Drive
Tullytown, PA 19007

Business: (215) 943-3382
E-mail: Gary@mdlrestorationinc.com

Type of Estimate: Water Damage
Date Entered: 8/8/2021 Date Assigned:

Price List: PAPH8X_AUG21
Labor Efficiency: Restoration/Service/Remodel
Estimate: KAJKOWSKI-REBUILD
File Number: A00003499756




MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

KAJKOWSKI-REBUILD

Main Level



Bedroom

Height: 8'

303.21 SF Walls	122.40 SF Ceiling
425.60 SF Walls & Ceiling	122.40 SF Floor
13.60 SY Flooring	39.33 LF Floor Perimeter
44.33 LF Ceil. Perimeter	

Door	2' 6" X 6' 8"	Opens into Exterior
Door	2' 6" X 6' 8"	Opens into Exterior
Window	4' 10" X 3' 9"	Opens into Exterior

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
1. Content Manipulation charge - per hour	2.00 HR	0.00	46.80	0.00	18.72	112.32
2. Provide box, packing paper & tape - medium size	3.00 EA	0.00	3.90	1.50	2.46	15.66
3. Ceiling fan - Detach & reset	1.00 EA	0.00	228.82	0.00	45.76	274.58
4. R&R Crown molding - 3 1/4"	44.33 LF	0.79	4.68	4.39	49.38	296.25
5. Window blind - horizontal or vertical - Detach & reset	1.00 EA	0.00	39.26	0.00	7.86	47.12
6. R&R Casing - 3 1/4"	18.00 LF	0.59	3.18	2.17	14.00	84.03
7. Baseboard heat - steam/hot wtr cover only - Detach & reset	11.00 EA	0.00	14.05	0.00	30.92	185.47
8. R&R 1/2" drywall - hung, taped, floated, ready for paint	155.20 SF	0.50	2.96	5.49	108.50	650.98
<i>half of ceiling, exterior wall</i>						
9. Additional cost for gluing drywall	155.20 SF	0.00	0.35	0.47	10.96	65.75
10. R&R Batt insulation - 4" - R15 - paper / foil faced	94.00 SF	0.29	1.18	4.12	28.46	170.76
11. Clean floor or roof joist system	61.20 SF	0.00	1.03	4.62	12.62	80.28
12. Clean stud wall	61.20 SF	0.00	0.83	3.73	10.18	64.71
13. Remove Carpet	122.40 SF	0.32	0.00	0.00	7.84	47.01
14. Carpet	140.76 SF	0.00	3.59	22.21	105.50	633.04
15 % waste added for Carpet.						
15. R&R Carpet pad	122.40 SF	0.14	0.62	3.60	19.32	115.95
16. Clean floor underlayment / wood subfloor	122.40 SF	0.00	0.47	4.22	11.52	73.27
17. Mask the floor per square foot - plastic and tape - 4 mil	122.40 SF	0.00	0.22	0.37	5.46	32.76




MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

CONTINUED - Bedroom

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
18. Seal/prime then paint the walls and ceiling twice (3 coats)	425.60 SF	0.00	1.18	6.89	101.82	610.92
19. Seal & paint crown molding - two coats	44.33 LF	0.00	1.37	0.37	12.22	73.32
20. Seal & paint door or window opening (per side)	4.00 EA	0.00	28.62	1.13	23.12	138.73
21. Seal & paint window sill	6.00 LF	0.00	2.32	0.09	2.80	16.81
22. Seal & paint door slab only (per side)	2.00 EA	0.00	34.28	0.93	13.90	83.39
23. Seal & paint baseboard - two coats	27.58 LF	0.00	1.35	0.18	7.48	44.89
24. Clean baseboard heater - exterior	11.00 LF	0.00	2.70	2.15	5.94	37.79
25. Paint baseboard heater	11.00 LF	0.00	5.98	0.53	13.26	79.57
26. Final cleaning - construction - Residential	122.40 SF	0.00	0.28	2.47	6.86	43.60
Totals: Bedroom				71.63	676.86	4,078.96
Total: Main Level				71.63	676.86	4,078.96

Level 2



Master Bedroom

Height: Sloped

359.06 SF Walls	196.39 SF Ceiling
555.45 SF Walls & Ceiling	195.55 SF Floor
21.73 SY Flooring	47.67 LF Floor Perimeter
60.76 LF Ceil. Perimeter	

Door	2' 6" X 6' 8"	Opens into Exterior
Door	2' 6" X 6' 8"	Opens into Exterior
Window	2' 8" X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into Exterior
Door	5' X 6' 8"	Opens into CLOSET

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
27. Content Manipulation charge - per hour	3.00 HR	0.00	46.80	0.00	28.08	168.48
28. Protect contents - Cover with plastic	300.00 SF	0.00	0.38	1.08	23.02	138.10
29. Provide box, packing paper & tape - medium size	5.00 EA	0.00	3.90	2.50	4.10	26.10
30. Ceiling fan - Detach & reset	1.00 EA	0.00	228.82	0.00	45.76	274.58



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

CONTINUED - Master Bedroom


DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
31. R&R Casing - 3 1/4" stain grade	22.00 LF	0.59	3.50	3.08	18.62	111.68
32. Baseboard heat - steam/hot wtr cover only - Detach & reset	5.00 EA	0.00	14.05	0.00	14.06	84.31
33. R&R 1/2" drywall - hung, taped, floated, ready for paint	106.00 SF	0.50	2.96	3.75	74.12	444.63
<i>2 sheets on ceiling, rest around window on exterior wall</i>						
34. Additional cost for gluing drywall	106.00 SF	0.00	0.35	0.32	7.48	44.90
35. R&R Batt insulation - 6" - R19 - paper / foil faced	64.00 SF	0.34	1.16	2.65	19.74	118.39
36. R&R Batt insulation - 4" - R15 - paper / foil faced	42.00 SF	0.29	1.18	1.84	12.72	76.30
37. Clean floor or roof joist system	64.00 SF	0.00	1.03	4.83	13.20	83.95
38. Clean stud wall	42.00 SF	0.00	0.83	2.56	7.00	44.42
39. Clean and deodorize carpet	195.55 SF	0.00	0.49	7.03	19.18	122.03
40. Mask the floor per square foot - plastic and tape - 4 mil	195.55 SF	0.00	0.22	0.59	8.72	52.33
41. Seal/prime then paint the walls and ceiling twice (3 coats)	555.45 SF	0.00	1.18	9.00	132.88	797.31
42. Stain & finish casing	22.00 LF	0.00	1.41	0.25	6.26	37.53
43. Stain & finish wood window sill	3.00 LF	0.00	2.68	0.03	1.60	9.67
44. Final cleaning - construction - Residential	195.55 SF	0.00	0.28	3.95	10.96	69.66
Totals: Master Bedroom				43.46	447.50	2,704.37
Total: Level 2				43.46	447.50	2,704.37

Basement



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



Basement Den

Height: 6' 4"

384.43 SF Walls	270.33 SF Ceiling
654.76 SF Walls & Ceiling	270.33 SF Floor
30.04 SY Flooring	60.04 LF Floor Perimeter
75.33 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

6' 4" X 6' 4"

Opens into BAR_AREA

Door

2' 6" X 6'

Opens into Exterior

Missing Wall

2' 9 1/2" X 6' 4"

Opens into STAIRS

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
45. Content Manipulation charge - per hour	6.00 HR	0.00	46.80	0.00	56.16	336.96
46. Protect contents - Cover with plastic	200.00 SF	0.00	0.38	0.72	15.34	92.06
47. Provide box, packing paper & tape - medium size	8.00 EA	0.00	3.90	4.00	6.56	41.76
48. R&R Chair rail - 2 1/2"	13.25 LF	0.50	3.22	1.02	10.06	60.38
49. R&R Baseboard - 3 1/4"	13.25 LF	0.54	3.66	1.12	11.36	68.14
50. R&R 1/2" drywall - hung, taped, floated, ready for paint	83.92 SF	0.50	2.96	2.97	58.68	352.01
<i>exterior wall portion</i>						
51. Additional cost for gluing drywall	83.92 SF	0.00	0.35	0.25	5.94	35.56
52. Clean stud wall	83.92 SF	0.00	0.83	5.13	13.96	88.74
53. Clean and deodorize carpet	270.33 SF	0.00	0.49	9.71	26.54	168.71
54. Mask the floor per square foot - plastic and tape - 4 mil	270.33 SF	0.00	0.22	0.81	12.06	72.34
55. Recessed light fixture - Detach & reset trim only	6.00 EA	0.00	3.61	0.00	4.34	26.00
56. Seal/prime then paint the walls and ceiling twice (3 coats)	614.65 SF	0.00	1.18	9.96	147.06	882.31
57. Seal & paint chair rail - two coats	53.71 LF	0.00	1.30	0.42	14.04	84.28
58. Seal & paint baseboard - two coats	53.71 LF	0.00	1.35	0.35	14.58	87.44
59. Seal & paint door or window opening (per side)	6.00 EA	0.00	28.62	1.70	34.68	208.10
60. Seal & paint door slab only (per side)	5.00 EA	0.00	34.28	2.32	34.74	208.46



MDL Restoration Inc


606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

CONTINUED - Basement Den

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
61. Final cleaning - construction - Residential	270.33 SF	0.00	0.28	5.45	15.14	96.28
Totals: Basement Den				45.93	481.24	2,909.53

Stairs

Height: 13'



179.34 SF Walls	24.08 SF Ceiling
203.42 SF Walls & Ceiling	41.63 SF Floor
4.63 SY Flooring	19.75 LF Floor Perimeter
17.42 LF Ceil. Perimeter	

Missing Wall


2' 9 1/2" X 12' 11 15/16"

Opens into BASEMENT_DEN

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
62. Clean and deodorize carpet	41.63 SF	0.00	0.49	1.51	4.08	25.99
63. Mask the floor per square foot - plastic and tape - 4 mil	41.63 SF	0.00	0.22	0.12	1.86	11.14
64. Seal/prime then paint the walls and ceiling (2 coats)	203.42 SF	0.00	0.86	2.07	35.40	212.41
65. Seal & paint chair rail - two coats	4.00 LF	0.00	1.30	0.03	1.04	6.27
66. Final cleaning - construction - Residential	41.63 SF	0.00	0.28	0.84	2.34	14.84
Totals: Stairs				4.57	44.72	270.65

Bar Area

Height: 6' 6"



494.00 SF Walls	285.04 SF Ceiling
779.04 SF Walls & Ceiling	285.04 SF Floor
31.67 SY Flooring	76.00 LF Floor Perimeter
76.00 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

6' 4" X 6' 4"

Opens into BASEMENT_DEN

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
67. Content Manipulation charge - per hour	3.00 HR	0.00	46.80	0.00	28.08	168.48
68. Protect contents - Cover with plastic	300.00 SF	0.00	0.38	1.08	23.02	138.10



MDL Restoration Inc


606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

CONTINUED - Bar Area

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
69. Provide box, packing paper & tape - medium size	5.00 EA	0.00	3.90	2.50	4.10	26.10
70. Mask the floor per square foot - plastic and tape - 4 mil	285.04 SF	0.00	0.22	0.86	12.72	76.29
71. Recessed light fixture - Detach & reset trim only	4.00 EA	0.00	3.61	0.00	2.88	17.32
72. Seal/prime then paint the ceiling (2 coats)	285.04 SF	0.00	0.86	2.91	49.60	297.64
73. Seal & paint door or window opening (per side)	1.00 EA	0.00	28.62	0.28	5.78	34.68
74. Final cleaning - construction - Residential	285.04 SF	0.00	0.28	5.75	15.96	101.52
Totals: Bar Area				13.38	142.14	860.13
Total: Basement				63.88	668.10	4,040.31

Roof

Rear Slope



426.30 Surface Area
87.40 Total Perimeter Length

4.26 Number of Squares

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
75. R&R Rubber roofing - Fully adhered system - 45 mil	1.20 SQ	93.72	560.00	11.31	159.16	954.93
76. R&R Sheathing - plywood - 1/2" - treated	32.00 SF	0.67	4.70	5.84	35.52	213.20
77. R&R Drip edge/gutter apron	29.00 LF	0.39	2.97	1.90	19.86	119.20
78. Roofing sealer - Traffic coat	426.30 SF	0.00	2.15	18.16	186.96	1,121.67
79. Remove Additional charge for high roof (2 stories or greater)	1.20 SQ	6.22	0.00	0.00	1.50	8.96
80. Additional charge for high roof (2 stories or greater)	1.20 SQ	0.00	23.20	0.00	5.56	33.40
Totals: Rear Slope				37.21	408.56	2,451.36
Total: Roof				37.21	408.56	2,451.36



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

General

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
81. Dumpster load - Approx. 20 yards, 4 tons of debris	1.00 EA	593.00	0.00	0.00	118.60	711.60
82. Taxes, insurance, permits & fees (Bid Item)	1.00 EA	0.00	0.00	0.00	0.00	0.00
<i>If permits are needed will bill as incurred.</i>						
83. Lead Paint Safety (Bid Item)	1.00 EA	0.00	0.00	0.00	0.00	0.00
Totals: General				0.00	118.60	711.60
Line Item Totals: KAJKOWSKI-REBUILD				216.18	2,319.62	13,986.60

Grand Total Areas:

1,719.65 SF Walls	910.41 SF Ceiling	2,630.06 SF Walls and Ceiling
927.12 SF Floor	103.01 SY Flooring	241.29 LF Floor Perimeter
0.00 SF Long Wall	0.00 SF Short Wall	290.01 LF Ceil. Perimeter
927.12 Floor Area	1,001.23 Total Area	1,598.36 Interior Wall Area
1,775.82 Exterior Wall Area	241.04 Exterior Perimeter of Walls	
426.30 Surface Area	4.26 Number of Squares	0.00 Total Perimeter Length
0.00 Total Ridge Length	0.00 Total Hip Length	



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

Summary

Line Item Total	11,450.80
Material Sales Tax	141.73
Cleaning Mtl Tax	5.05
Subtotal	11,597.58
Overhead	1,159.81
Profit	1,159.81
Cleaning Sales Tax	69.40
Replacement Cost Value	\$13,986.60
Net Claim	\$13,986.60

Gary Poltonowicz



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

Recap of Taxes, Overhead and Profit

Overhead (10%)	Profit (10%)	Material Sales Tax (6%)	Cleaning Mtl Tax (6%)	Cleaning Sales Tax (6%)	Clothing Acc Tax (6%)	Manuf. Home Tax (6%)	Storage Rental Tax (6%)	Dryclean/Lau dry Tax (6%)
Line Items								
1,159.81	1,159.81	141.73	5.05	69.40	0.00	0.00	0.00	0.00
Total								
1,159.81	1,159.81	141.73	5.05	69.40	0.00	0.00	0.00	0.00



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

Recap by Room

Estimate: KAJKOWSKI-REBUILD

Area:	Main Level		
	Bedroom	3,330.47	29.09%
	Area Subtotal: Main Level	3,330.47	29.09%
Area:	Level 2		
	Master Bedroom	2,213.41	19.33%
	Area Subtotal: Level 2	2,213.41	19.33%
Area:	Basement		
	Basement Den	2,382.36	20.81%
	Stairs	221.36	1.93%
	Bar Area	704.61	6.15%
	Area Subtotal: Basement	3,308.33	28.89%
Area:	Roof		
	Rear Slope	2,005.59	17.51%
	Area Subtotal: Roof	2,005.59	17.51%
	General	593.00	5.18%
	Subtotal of Areas	11,450.80	100.00%
	Total	11,450.80	100.00%



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382

Recap by Category

O&P Items	Total	%
CLEANING	876.36	6.27%
CONTENT MANIPULATION	959.20	6.86%
CONT: PACKING,HANDLNG, STORAGE	81.90	0.59%
GENERAL DEMOLITION	1,108.15	7.92%
DRYWALL	1,142.34	8.17%
FLOOR COVERING - CARPET	581.22	4.16%
FINISH CARPENTRY / TRIMWORK	432.87	3.09%
HEAT, VENT & AIR CONDITIONING	224.80	1.61%
INSULATION	234.72	1.68%
LIGHT FIXTURES	493.74	3.53%
PAINTING	3,423.32	24.48%
ROOFING	1,852.92	13.25%
WINDOW TREATMENT	39.26	0.28%
<hr/>		
O&P Items Subtotal	11,450.80	81.87%
Material Sales Tax	141.73	1.01%
Cleaning Mtl Tax	5.05	0.04%
Overhead	1,159.81	8.29%
Profit	1,159.81	8.29%
Cleaning Sales Tax	69.40	0.50%
<hr/>		
Total	13,986.60	100.00%



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



1

1-1st Floor (1)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



2

2-1st Floor (2)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



3

3-1st Floor (3)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



4

4-1st Floor (4)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



5

5-1st Floor (5)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



6

6-1st Floor (6)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



7

7-1st Floor (7)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



8

8-1st Floor (8)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



9

9-1st Floor (9)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



10 10-1st Floor (10)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



11 11-1st Floor (11)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



12 12-1st Floor (12)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



13

13-1st Floor (13)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



14

14-1st Floor (14)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



15

15-1st Floor (15)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



16

16-1st Floor (16)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



17

17-1st Floor (17)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



18

18-1st Floor (18)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



19

19-1st Floor (19)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



20

20-1st Floor (20)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



21 21-1st Floor (21)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



22 22-1st Floor (22)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



23

23-1st Floor (23)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



24 24-1st Floor (24)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



25

25-1st Floor (25)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



26

26-1st Floor (26)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



27

27-1st Floor (27)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



28

28-1st Floor (28)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



29

29-1st Floor (29)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



30

30-1st Floor (30)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



31 31-1st Floor (31)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



32

32-1st Floor (32)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



33

33-1st Floor (33)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



34

34-1st Floor (34)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



35

35-1st Floor (35)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



36 36-1st Floor (36)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



37


37-1st Floor (37)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



38

38-1st Floor (38)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



39


39-1st Floor (39)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



40

40-1st Floor (40)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



41

41-1st Floor (41)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



42

42-1st Floor (42)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



43

43-1st Floor (43)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



44


44-2nd Floor (1)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



45

45-2nd Floor (2)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



46

46-2nd Floor (3)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



47

47-2nd Floor (4)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



48


48-2nd Floor (5)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



49


49-2nd Floor (6)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




50 50-2nd Floor (7)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



51

51-2nd Floor (8)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



52

52-2nd Floor (9)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



53 53-2nd Floor (10)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



54

54-2nd Floor (11)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



55

55-2nd Floor (12)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



56

56-2nd Floor (13)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



57

57-2nd Floor (14)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



58

58-2nd Floor (15)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



59

59-2nd Floor (16)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



60

60-2nd Floor (17)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



61

61-2nd Floor (18)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



62

62-2nd Floor (19)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



63


63-2nd Floor (20)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



64


64-2nd Floor (21)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



65

65-2nd Floor (22)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



66

66-2nd Floor (23)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



67

67-2nd Floor (24)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



68

68-2nd Floor (25)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



69

69-2nd Floor (26)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



70


70-2nd Floor (27)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



71

71-2nd Floor (28)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



72

72-2nd Floor (29)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



73

73-2nd Floor (30)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



74

74-2nd Floor (31)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



75

75-2nd Floor (32)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



76

76-2nd Floor (33)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



77

77-2nd Floor (34)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



78

78-2nd Floor (35)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



79

79-2nd Floor (36)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



80 80-2nd Floor (37)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




81 81-2nd Floor (38)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



82


82-2nd Floor (39)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



83

83-2nd Floor (40)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



84 84-2nd Floor (41)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



85

85-2nd Floor (42)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



86

86-2nd Floor (43)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



87

87-2nd Floor (44)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



88

88-2nd Floor (45)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



89


89-2nd Floor (46)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



90 90-2nd Floor (47)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



91

91-2nd Floor (48)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



92

92-2nd Floor (49)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



93 93-2nd Floor (50)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



94 94-2nd Floor (51)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



95

95-2nd Floor (52)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



96

96-2nd Floor (53)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



97

97-2nd Floor (54)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



98

98-2nd Floor (55)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



99 99-2nd Floor (56)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




100 100-2nd Floor (57)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



101 101-2nd Floor (58)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



102 102-2nd Floor (59)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




103 103-Basement (1)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




104 104-Basement (2)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




105 105-Basement (3)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




106 106-Basement (4)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




107 107-Basement (5)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




108 108-Basement (6)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



109 109-Basement (7)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




110 110-Basement (8)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



111 111-Basement (9)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



112 112-Basement (10)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




113 113-Basement (11)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



114 114-Basement (12)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



115 115-Basement (13)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



116 116-Basement (14)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



117 117-Basement (15)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



118 118-Basement (16)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



119 119-Basement (17)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




120 120-Basement (18)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




121 121-Basement (19)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




122 122-Basement (20)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




123 123-Basement (21)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



124 124-Basement (22)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



125 125-Basement (23)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



126 126-Basement (24)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




127 127-Basement (25)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




128 128-Basement (26)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



129 129-Basement (27)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



130 130-Basement (28)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



131 131-Basement (29)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



132 132-Basement (30)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




133 133-Basement (31)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



134 134-Basement (32)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



135 135-Basement (33)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



136 136-Basement (34)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



137 137-Basement (35)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




138 138-Basement (36)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



139 139-Basement (37)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




140 140-Basement (38)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




141 141-Basement (39)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




142 142-Basement (40)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




143 143-Basement (41)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




144 144-Basement (42)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




145 145-Basement (43)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



146 146-Basement (44)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



147 147-Basement (45)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



148

148-Basement (46)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



149 149-Basement (47)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



150 150-Basement (48)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



151 151-Basement (49)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



152

152-Basement (50)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




153 153-Basement (51)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




154 154-Basement (52)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



155 155-Basement (53)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



156 156-Front of House

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382




157 157-Rear Exterior (1)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



158

158-Rear Exterior (2)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



159


159-Rear Exterior (3)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



160

160-Rear Exterior (4)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



161 161-Rear Exterior (5)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



162 162-Rear Exterior (6)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



163 163-Rear Exterior (7)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



164 164-Rear Exterior (8)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



165

165-Rear Exterior (9)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



166

166-Rear Exterior (10)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



167

167-Rear Exterior (11)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



168 168-Rear Exterior (12)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



169

169-Rear Exterior (13)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



170 170-Rear Exterior (14)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



171

171-Rear Exterior (15)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



172

172-Rear Exterior (16)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



173

173-Rear Exterior (17)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



174

174-Rear Exterior (18)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



175

175-Rear Exterior (19)

Date Taken: 8/6/2021



MDL Restoration Inc

606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



176

176-Rear Exterior (20)

Date Taken: 8/6/2021



MDL Restoration Inc


606 WM Leigh Drive
Tullytown PA 19007
215-943-3382



177


177-Rear Exterior (21)

Date Taken: 8/6/2021




Basement

Main Level




Main Level



N
↑

Level 2

Roof



N
↑

Roof