
Vehicle

**RTS** 

Diagnostics



**VEHICLE DATA** Modules Fault Timeline DTC Helptext **DTC Snapshot** Vehicle last read (NIT): 11-08-2025 11:30:59 GMT+1 ECU Data Data Logger Mileage Last Read: 15155 mi at 11-08-2025 11:30:57 GMT+1 Module T **Description Status** Y **BCM Description Body Control Module** DTC **CCM Description** Cruise Control Module DTC **IDMA Description** Interactive Display Module 'A' DTC **NFSM Description** Near Field Sensing Module

Cookie Policy

Privacy policy

© 2025 Terms and conditions

Contact us

Links

# **PCM Description** Powertrain Control Module DTC **RFA Description** Remote Function Actuator DTC **TBM Description Towbar Control Module** DTC **AAM** Description Audio Amplifier Module **RESPONDED ABS Description** Anti-Lock Brake System Control Module **RESPONDED ATCM Description** All Terrain Control Module **RESPONDED BECM** Links Contact us Cookie Policy Privacy policy © 2025 Terms and conditions Third-Party Licenses

Battery Energy Control Module
RESPONDED
СНСМ
Description
Chassis Control Module
RESPONDED
DADC
Description
Driver Assistance Domain Controller
RESPONDED
DDCM
Description
Driveline Disconnect Control Module
RESPONDED
DDM
Description
Driver Front Door Module
RESPONDED
DRDM
Description
Driver Rear Door Module
RESPONDED
DSM
Description
<b>Description</b> Driver Seat Module
RESPONDED  nks Contact us Cookie Policy Privacy policy © 2025 Terms and conditions Third-Party License


# **EPICD** Description Electric Power Inverter Converter Control Module 'D' **RESPONDED GSM Description** Gear Shift Module RESPONDED **GWM Description** Gateway Module **RESPONDED** НСМ **Description** Headlamp Control Module A **RESPONDED HCMB Description** Headlamp Control Module B **RESPONDED HVAC Description HVAC Control Module** RESPONDED **ICCM**

Infotainment Compute Control Module **RESPONDED IGM Description** Infotainment Gateway Module **RESPONDED IPCB Description** Instrument Panel Cluster Control Module B **RESPONDED IPMA Description** Image Processing Module 'A' RESPONDED **PDM Description** Passenger Front Door Module **RESPONDED PRDM Description** Passenger Rear Door Module RESPONDED **PSCM Description** Power Steering Control Module RESPONDED Links Contact us Cookie Policy Privacy policy © 2025 Terms and conditions Third-Party Licenses

# **PSCMB** Description Power Steering Control Module B **RESPONDED PSM Description** Passenger Front Seat Module RESPONDED **RCM Description** Restraints Control Module **RESPONDED RGTM Description** Rear Gate / Trunk Module **RESPONDED RGTMB Description** Rear Gate Trunk Module B **RESPONDED SASM Description** Steering Angle Sensor Module RESPONDED **SGCM**

Starter Generator Control Module **RESPONDED SODL Description** Side Obstacle Detection Control Module - Left **RESPONDED SODR Description** Side Obstacle Detection Control Module - Right **RESPONDED TCCM Description** Transfer Case Control Module RESPONDED **TCM Description** Transmission Control Module **RESPONDED TCU Description** Telematic Control Unit Module RESPONDED **TPM Description** Tire Pressure Monitor Module RESPONDED Links Contact us Cookie Policy Privacy policy © 2025 Terms and conditions Third-Party Licenses

# WDCM Description Wireless Device Charger Module



# Date (UTC)

07-May-2025 11:07:51 (UTC)

# **Odometer reading**

13998 mi

#### **Translated status**

Historic DTC

# Module

**RFA** 

#### **DTC**

B1DD5-13

Historic

#### **Description**

Right Doors Zone Passive Entry Transmitter - Circuit open

# Date (UTC)

23-Feb-2024 11:18:29 (UTC)

# **Odometer reading**

3602 mi

#### Translated status

Historic DTC

#### Module

**CCM** 

#### DTC

C1A67-97

Historic

# **Description**

Forward Looking Sensor - Component or system operation obstructed or blocked

# Date (UTC)

Date unavailable

#### **Odometer reading**

Unavailable

#### **Translated status**

Historic DTC

Links

Contact us Cookie Policy Privacy policy

© 2025 Terms and conditions

# **IDMA**

#### **DTC**

B14A2-13

Historic

# Description

APIX Display Link - Front Display Screen - Circuit open

# Date (UTC)

Date unavailable

# **Odometer reading**

Unavailable

# Translated status

Historic DTC

#### Module

**NFSM** 

#### DTC

B129D-67

Historic

# Description

Right Front Side Sensor - Signal incorrect after event

# Date (UTC)

Date unavailable

# **Odometer reading**

Unavailable

# **Translated status**

Historic DTC

# Module

**NFSM** 

#### **DTC**

B12BD-67

Historic

# **Description**

Rear Camera - Signal incorrect after event

# Date (UTC)

Links

Contact us Cookie Policy Privacy policy © 2025 Terms and conditions

# **Odometer reading**

Unavailable

#### **Translated status**

Historic DTC

#### Module

**NFSM** 

#### DTC

B12C0-67

Historic

# **Description**

Left Mirror Camera - Signal incorrect after event

#### Date (UTC)

Date unavailable

#### **Odometer reading**

Unavailable

#### **Translated status**

Historic DTC

# Module

**NFSM** 

#### **DTC**

B12C1-67

Historic

# **Description**

Right Mirror Camera - Signal incorrect after event

# Date (UTC)

Date unavailable

# **Odometer reading**

Unavailable

# Translated status

Historic DTC

# Module

**NFSM** 

Links

Contact us Cookie Policy Privacy policy © 2025 Terms and conditions

B1300-02 Historic

#### **Description**

Video Output "A" - General signal failure

#### Date (UTC)

Date unavailable

# **Odometer reading**

Unavailable

#### Translated status

Historic DTC

#### Module

**NFSM** 

#### DTC

B19FE-67

Historic

#### **Description**

Front Bumper Center Camera - Signal incorrect after event

# Date (UTC)

Date unavailable

#### **Odometer reading**

Unavailable

# **Translated status**

Historic DTC

# Module

**NFSM** 

# DTC

B1B38-67

Historic

# **Description**

Right Front Inner Sensor - Signal incorrect after event

# Date (UTC)

Date unavailable

# **Odometer reading**

Links Contact us

Cookie Policy Privacy policy © 2025 Terms and conditions

#### **Translated status**

Historic DTC

#### Module

**NFSM** 

# DTC

B1B42-67

Historic

#### **Description**

Left Front Inner Sensor - Signal incorrect after event

# Date (UTC)

Date unavailable

#### **Odometer reading**

Unavailable

# Translated status

Historic DTC

#### Module

**PCM** 

#### **DTC**

P037D-31

Historic

# **Description**

Glow Plug Sense Circuit - No signal

# Date (UTC)

Date unavailable

# **Odometer reading**

Unavailable

#### Translated status

Historic DTC

# Module

**PCM** 

# DTC

P20E9-84

Historic

# **Description**

Reductant Pressure Too High - Signal below allowable range

#### Date (UTC)

Date unavailable

# **Odometer reading**

Unavailable

#### **Translated status**

Historic DTC

#### Module

**PCM** 

#### DTC

P20E9-85

Historic

# **Description**

Reductant Pressure Too High - Signal above allowable range

#### Date (UTC)

Date unavailable

#### **Odometer reading**

Unavailable

#### **Translated status**

Historic DTC

#### Module

**PCM** 

#### **DTC**

P20FB-00

Historic

# **Description**

Reductant Pump "B" Control Performance / Stuck Off - No sub type information

#### Date (UTC)

Date unavailable

# **Odometer reading**

Unavailable

Translated status

Links

Contact us Cookie Policy Privacy policy © 2025 Terms and conditions

**Odometer reading** 

Unavailable

Module
PCM

DTC
P2BAE-00

Description
NOx Exceedance - NOx Control Monitoring System - No sub type information

Date (UTC)
Date unavailable