


SAFETYVISION AI

INDUSTRIAL VISUAL SAFETY INSPECTION AUDIT REPORT

Inspection ID: INS-20261007-7EDC37	Date/Time: 2026-10-07 07:54:39
Equipment Type: Industrial Angle Grinder	Model Version: 0.1.0
Operator: QA-Auditor-2	AI Confidence: 95.0%

OVERALL RESULT: FAIL — CRITICAL VIOLATION

VISUAL EVIDENCE ARTIFACT



SAFETY COMPONENT VERIFICATION MATRIX

Component	Mandatory	Detection Status	Confidence	Severity	Audit Finding
Protective Wheel Guard	YES	FAIL	N/A	CRITICAL	Abrasive wheel guard is missing. Operating wi...
Auxiliary Side Handle	YES	PASS	93.0%	NONE	Auxiliary Side Handle verified in position.
Power Cable & Strain Relief	YES	PASS	91.0%	NONE	Power Cable & Strain Relief verified in posit...
Safety Trigger / Switch	YES	PASS	89.0%	NONE	Safety Trigger / Switch verified in position.

INSPECTION FINDINGS & REQUIRED ACTION

Root Evaluation: FAIL — Missing mandatory components: guard.

Recommended Action: Do NOT operate tool. Lockout/tagout equipment immediately and schedule a certified competent-person mechanical and electrical safety inspection.

STATUTORY SAFETY NOTICE & COMPETENT PERSON DISCLAIMER: SafetyVision AI provides automated visual condition verification against configured visual safety criteria only. This software does NOT certify universal, physical, mechanical, or electrical safety and does NOT replace formal statutory inspections, manufacturer safety maintenance, job safety analyses (JSA), or evaluations conducted by an OSHA-defined Competent Person. Unsafe equipment must be tagged out and removed from service immediately.