



	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	OVERVIEW			Panel No.
Panel Name	-				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	38.1 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	OVERVIEW TOP		Panel No.	-
Panel Name	-				

IR IMAGE




VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	33.4 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	OVERVIEW BOTTOM		Panel No.	-
Panel Name	-				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	33.0 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE COMPARTMENT	Panel No.	CCH00666	
Panel Name	JALAN BOH				

IR IMAGE




VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	31.8 °C
Spot Temp. 2 (Sp2)	31.8 °C
Average Temp. (Ar1)	31.7 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.0 °C
Load (A)	-
Defect	

PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE



Decibel (dB)	OdB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE ENTRY		Panel No.	CCH00666
Panel Name	JALAN BOH				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	29.7 °C
Spot Temp. 2 (Sp2)	29.3 °C
Average Temp. (Ar1)	29.7 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.4 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE




Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE COMPARTMENT		Panel No.	CCH00667
Panel Name	TX 100kVA				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	31.5 °C	Serial No.	B21729024
Spot Temp. 2 (Sp2)	31.9 °C	Heater (A)	-
Average Temp. (Ar1)	31.7 °C	CB Position	CLOSE
Ambient Temp.	23.2 °C	Busbar Position	-
Delta T (Δ T)	0.4 °C	Cable Type	XLPE
Load (A)	-		
Defect			

ULTRASOUND IMAGE	
	
Decibel (dB)	OdB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE ENTRY		Panel No.	CCH00667
Panel Name	TX 100kVA				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	30.1 °C
Spot Temp. 2 (Sp2)	29.5 °C
Average Temp. (Ar1)	30.3 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.5 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE



Decibel (dB)	OdB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE COMPARTMENT		Panel No.	CCH00668
Panel Name	SSU HOSPITAL				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	38.3 °C
Spot Temp. 2 (Sp2)	37.9 °C
Average Temp. (Ar1)	38.7 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.4 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE



Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE ENTRY		Panel No.	CCH00668
Panel Name	SSU HOSPITAL				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	30.0 °C
Spot Temp. 2 (Sp2)	30.6 °C
Average Temp. (Ar1)	33.0 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.6 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE





Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	

Analysis & Recommendations:

Analysis: No Anomaly.


Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 4:02 PM
	Model	HERMETICALLY SEAL	Rating	100kVA	Humidity: 77%
	Area	OVERVIEW		Tx No.	1
Location					

IR IMAGE		VISUAL IMAGE																													
																															
<table><tr><th>PARAMETER</th><th>VALUE</th></tr><tr><td>Spot Temp.1 (Sp1)</td><td>40.8 °C</td></tr><tr><td>Spot Temp. 2 (Sp2)</td><td>39.9 °C</td></tr><tr><td>Average Temp. (Ar1)</td><td>36.4 °C</td></tr><tr><td>Ambient Temp.</td><td>23.2 °C</td></tr><tr><td>Delta T (Δ T)</td><td>0.8 °C</td></tr><tr><td>Load (A)</td><td>-</td></tr><tr><td>Defect</td><td>-</td></tr></table>		PARAMETER	VALUE	Spot Temp.1 (Sp1)	40.8 °C	Spot Temp. 2 (Sp2)	39.9 °C	Average Temp. (Ar1)	36.4 °C	Ambient Temp.	23.2 °C	Delta T (Δ T)	0.8 °C	Load (A)	-	Defect	-	<table><tr><th>PARAMETER</th><th>VALUE</th></tr><tr><td>Serial No.</td><td>T/800/1452/1486</td></tr><tr><td>Heater (A)</td><td>-</td></tr><tr><td>CB Position</td><td>-</td></tr><tr><td>Busbar Position</td><td>-</td></tr><tr><td>Cable Type</td><td>-</td></tr></table>		PARAMETER	VALUE	Serial No.	T/800/1452/1486	Heater (A)	-	CB Position	-	Busbar Position	-	Cable Type	-
PARAMETER	VALUE																														
Spot Temp.1 (Sp1)	40.8 °C																														
Spot Temp. 2 (Sp2)	39.9 °C																														
Average Temp. (Ar1)	36.4 °C																														
Ambient Temp.	23.2 °C																														
Delta T (Δ T)	0.8 °C																														
Load (A)	-																														
Defect	-																														
PARAMETER	VALUE																														
Serial No.	T/800/1452/1486																														
Heater (A)	-																														
CB Position	-																														
Busbar Position	-																														
Cable Type	-																														
ULTRASOUND IMAGE  <table><tr><td>Decibel (dB)</td><td>-</td></tr><tr><td>Sound characteristic</td><td>-</td></tr><tr><td>Defect</td><td>-</td></tr><tr><td>Sound clip</td><td></td></tr></table>				Decibel (dB)	-	Sound characteristic	-	Defect	-	Sound clip																					
Decibel (dB)	-																														
Sound characteristic	-																														
Defect	-																														
Sound clip																															
Analysis & Recommendations:																															
Analysis: No Anomaly.																															
Recommendation: -																															

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 4:02 PM
	Model	HERMETICALLY SEAL	Rating	100kVA	Humidity: 77%
	Area	BUSHING		Tx No.	1
Location	HV SIDE				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	36.5 °C
Spot Temp. 2 (Sp2)	36.3 °C
Average Temp. (Ar1)	19.8 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.2 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	T/800/1452/1486
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE



Decibel (dB)	OdB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 4:02 PM
	Model	HERMETICALLY SEAL	Rating	100kVA	Humidity: 77%
	Area	CABLE		Tx No.	1
Location	HV SIDE				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	31.1 °C
Spot Temp. 2 (Sp2)	30.9 °C
Average Temp. (Ar1)	15.3 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.2 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	T/800/1452/1486
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE




Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 4:02 PM
	Model	HERMETICALLY SEAL	Rating	100kVA	Humidity: 77%
	Area	BUSHING		Tx No.	1
Location	LV SIDE				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	29.5 °C	Serial No.	T/800/1452/1486
Spot Temp. 2 (Sp2)	29.8 °C	Heater (A)	-
Average Temp. (Ar1)	27.8 °C	CB Position	-
Ambient Temp.	23.2 °C	Busbar Position	-
Delta T (ΔT)	0.3 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 4:02 PM
	Model	HERMETICALLY SEAL	Rating	100kVA	Humidity: 77%
	Area	CABLE		Tx No.	1
Location	LV SIDE				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	28.1 °C	Serial No.	T/800/1452/1486
Spot Temp. 2 (Sp2)	28.2 °C	Heater (A)	-
Average Temp. (Ar1)	20.7 °C	CB Position	-
Ambient Temp.	23.2 °C	Busbar Position	-
Delta T (Δ T)	0.0 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -