



	Substation	S/S LOJI AIR HABU			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:21 PM
	Model	FALCON BETA	Rating	12kV	Humidity: 80%
	Area	OVERVIEW		Panel No.	-
Panel Name		-			

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	27.4 °C
Ambient Temp.	21.2 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B971569
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	S/S LOJI AIR HABU			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:21 PM
	Model	FALCON BETA	Rating	12kV	Humidity: 80%
	Area	OVERVIEW TOP		Panel No.	-
Panel Name	-				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	27.2 °C
Ambient Temp.	21.2 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B971569
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	S/S LOJI AIR HABU			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:21 PM
	Model	FALCON BETA	Rating	12kV	Humidity: 80%
	Area	OVERVIEW BOTTOM		Panel No.	-
Panel Name	-				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	26.6 °C
Ambient Temp.	21.2 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B971569
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	S/S LOJI AIR HABU			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:21 PM
	Model	FALCON BETA	Rating	12kV	Humidity: 80%
	Area	CABLE COMPARTMENT		Panel No.	CCH00347
Panel Name	KTRS TNB				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	27.2 °C
Spot Temp. 2 (Sp2)	27.3 °C
Average Temp. (Ar1)	27.2 °C
Ambient Temp.	21.2 °C
Delta T (ΔT)	0.1 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B971569
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE




Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	S/S LOJI AIR HABU			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:21 PM
	Model	FALCON BETA	Rating	12kV	Humidity: 80%
	Area	CABLE ENTRY		Panel No.	CCH00347
Panel Name	KTRS TNB				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	27.2 °C	Serial No.	B971569
Spot Temp. 2 (Sp2)	27.2 °C	Heater (A)	-
Average Temp. (Ar1)	26.6 °C	CB Position	CLOSE
Ambient Temp.	21.2 °C	Busbar Position	-
Delta T (Δ T)	0.0 °C	Cable Type	XLPE
Load (A)	-		
Defect			

ULTRASOUND IMAGE	
	
Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	S/S LOJI AIR HABU			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:21 PM
	Model	FALCON BETA	Rating	12kV	Humidity: 80%
	Area	CABLE COMPARTMENT	Panel No.	CCH00346	
Panel Name	LOJI AIR				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	26.6 °C
Spot Temp. 2 (Sp2)	26.9 °C
Average Temp. (Ar1)	26.8 °C
Ambient Temp.	21.2 °C
Delta T (ΔT)	0.3 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B971569
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE



Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	S/S LOJI AIR HABU			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:21 PM
	Model	FALCON BETA	Rating	12kV	Humidity: 80%
	Area	CABLE ENTRY		Panel No.	CCH00346
Panel Name	LOJI AIR				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	26.5 °C
Spot Temp. 2 (Sp2)	26.4 °C
Average Temp. (Ar1)	26.3 °C
Ambient Temp.	21.2 °C
Delta T (ΔT)	0.1 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B971569
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE



Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	S/S LOJI AIR HABU			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:21 PM
	Model	FALCON BETA	Rating	12kV	Humidity: 80%
	Area	CABLE COMPARTMENT		Panel No.	CCH00345
Panel Name	SSU HABU				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	27.0 °C
Spot Temp. 2 (Sp2)	26.9 °C
Average Temp. (Ar1)	27.0 °C
Ambient Temp.	21.2 °C
Delta T (Δ T)	0.2 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B971569
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE




Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	S/S LOJI AIR HABU			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:21 PM
	Model	FALCON BETA	Rating	12kV	Humidity: 80%
	Area	CABLE ENTRY		Panel No.	CCH00345
Panel Name	SSU HABU				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	26.5 °C	Serial No.	B971569
Spot Temp. 2 (Sp2)	26.4 °C	Heater (A)	-
Average Temp. (Ar1)	26.2 °C	CB Position	CLOSE
Ambient Temp.	21.2 °C	Busbar Position	-
Delta T (Δ T)	0.1 °C	Cable Type	XLPE
Load (A)	-		
Defect			

ULTRASOUND IMAGE	
	
Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	
Analysis & Recommendations:	
Analysis: No Anomaly.	
Recommendation: -	